

SIEMENS

SINUMERIK Operate

Cycle 800

ADVANCED

**SINUMERIK
828D/840D sl**

Edition 2019.01
Training Manual

SINUMERIK

Cycle 800 ADVANCED

Valid for:

SINUMERIK 828D
SINUMERIK 840D sl

SW4.8
SW4.8



Module Description:


This module introduces CYCLE800.
3+2 swiveling with this CYCLE800 is shown.
The respective setting options are discussed.


Module Objective:

After working through this module, you know the CYCLE800 from Siemens with all its input options.

Content:

- Introduction
- "CYCLE800" settings
- Swiveling in "JOG"
- "Axis-by-axis" swiveling
- "Spatial angle" swiveling
- "Projection angle" swiveling
- "Direct" swiveling
- "Turn on" tool






Notes:

Introduction:


This module concerns "CYCLE800".

This simplifies programming for 3+2 axis machining, also called 2½D machining. This is equivalent to working in swiveled planes. If a milling machine has one or two additional rotary axes, an oblique plane can be defined in space and the tool set perpendicular to it.

The "right-hand rule" described in the previous M101 module serves as basis.





The resulting linear and rotary axes are shown in the right-hand graphic using a coordinate cube.



Irrespective of the associated machine kinematics

Type T (T= Tool)

Type P (P= Part)



or whether a combination of both.

The swivel axes are always rotated so that the machining plane is perpendicular to the tool axis for the subsequent machining. The direct programming of rotary axes is a special case.

"CYCLE800" is responsible for this.



Notes:

CYCLE800

This cycle is also a subprogram that accesses data which was commissioned so that the programming and application are optimized and simplified for operators and programmers.


The cycle, however, is not essential for swiveling. Examples without "CYCLE800" were shown in the previous module.

This module shows examples for working with "CYCLE800".


You can use swivel heads or swivel tables to set up and machine oblique planes. Swiveling is possible in JOG mode as well as in AUTOMATIC mode. Swivel operation parameter assignment and programming are facilitated by the clearly laid out graphics.

You can either program all the swivel axes directly on the machine (A, B, C) or you can simply specify the rotations around the geometry axes (X, Y, Z) of the workpiece coordinate system as described in the relevant workpiece drawing. The rotation of the workpiece coordinate system in the program is then automatically converted to a rotation of the relevant swivel axis of the machine during machining.

The swivel axes are always rotated in such a way that the machining plane is perpendicular to the tool axis for machining. The machining plane is then fixed during the machining. When the axes are swiveled, the active zero points and tool offsets are automatically converted for the swiveled state, resulting in a new coordinate system.




The input screen of "CYCLE800" represents the machine kinematics.



Die Eingabemasken und Möglichkeiten werden anhand der nachfolgenden Beispiele Schritt für Schritt erklärt und praktisch angewendet. ➔

Notes:

The machining plane is then fixed during the machining.



All this is implemented via "CYCLE800".


The term "CYCLE800" does not appear in ShopMill.

However, because this cycle permits swiveling, it is used completely for this purpose.

Pressing



opens the input screen for swiveling in JOG.




If no TC (Tool Carrier) that contains the machine kinematics for swiveling is selected, this field remains empty.



Notes:


Only when a TC is selected does the input screen with the appropriate kinematics open.



The TC, beginning with the name through to the parameterization, is normally commissioned by the manufacturer. This is not the basis this module, but rather of the commissioning.

To simplify understanding, the function of a Tool Carrier as of version 4.8 is described in detail.

Pressing



opens the Tool Carrier. The name of the TC ("TABLE") is arbitrary. If necessary, several Tool Carriers can also be created, for example, when a replaceable head is used for machining.

Caution:


Alle geänderten Daten sind sofort aktiv.



Notes:

The complete mathematics of the machine axes are stored in the Tool Carrier.

Table	Offset I2	200.000000	300.000000
+	Offset I2	260.000000	300.000000
+	Fine offset I2	0.000000	0.000000
+	Rotation axis 1	A	
	Mode	automatically	
	Direction v1	-1.000000	0.000000
	Offset	0.000	0.000 °
	Angle area	-100.000	100.000 °
	Hirth teeth	No	
+	Offset I3	0.000000	20.400000
+	Fine offset I3	0.000000	0.000000
+	Rotation axis 2	C	
	Mode	automatically	
	Direction v2	0.000000	-1.000000
	Offset	0.000	0.000 °
	Angle area	0.000	360.000 °



In addition to the values for the axis measurement, machine-related strategies are also specified in the Tool Carrier. Such strategies are normally made by the machine manufacturer / distributor.


Select retract	
- Incremental in tool direction	Yes
- Maximal in tool direction	Yes
- Machine axis Z	Yes
- Machine axis Z and then XY	No
- Retract position Z	500.000
Select swivel mode	
- Axis by axis	Yes
- Projection angle	Yes
- Solid angle	No
- Rotary axes direct	No
Select prefer. direction	Yes default=+
Reference axis pref. direction	Rotation axis 2
Select tracking	No
Shop*fill functions	
Swivel data set change	automatically
Tool change	automatically

Notes:

Pressing




opens the screen for swiveling the plane in the "Jog" operating area.




Es können hier unabhängig von einem Programm die Achsen geschwenkt werden.

The axes can be swiveled in two ways.


Specify the X, Y or Z axes in various



sequences by entering a degree,




or by the




direct selection of an axis

entering a degree.



Notes:


This manufacturer-neutral machine tool forms the basis of the 5-axis and the CAM documentation from Siemens.



Familiarize yourself with the swiveling of axes on a real or virtual machine.


Swivel plane

TC	TABLE
Retract	No
Swivel plane	New
Swivel mode	directly
A	-45.000 °
C	0.000 °
Z	0.000 °



Swivel plane

TC	TABLE
Retract	No
Swivel plane	New
Swivel mode	directly
A	0.000 °
C	45.000 °
Z	0.000 °



With the "additive" swivel plane, the following swiveling adds to the previous one.

Swivel plane


TC	TABLE
Retract	No
Swivel plane	New
Swivel mode	directly
A	0.000 °
C	0.000 °
Z	0.000 °

Notes:


1st example, swiveling in ShopMill**Task:**

The blank for the program example has the dimensions 100x100x52 mm

- ⇒ Programming in ShopMill
- ⇒ Travel machine to the initial setting
- ⇒ Face milling of the workpiece in the initial setting at a height of 50 mm
- ⇒ Swivel the workpiece and calculate the required infeed
- ⇒ Face milling of the workpiece in the swiveled state
- ⇒ Travel machine to the initial setting

Drawing:**Notes:**


Flow diagram:



After creating a new ShopMill program



and programming the program header,



Notes:


face cutting is performed in the initial setting.

After pressing






the machine with selected swivel data set is in the initial

setting.



After pressing



face milling in the initial setting is programmed.




Notes:

After pressing



the input screen for "CYCLE800" opens and the first swivel is programmed.




Name	TABLE	Kinematic	Swivel table	No.
Enable	Yes			
Retract	Z or Z, XY or max. in tool direction or inc. in tool dir.			
	X	Y	Z	
Retract position	-666.000	-555.000	1555.000 [mm]	
Offset vector I2	100.000000	200.000000	0.000000 [mm]	
Rotary axis vector U1	-1.000000	0.000000	0.000000	
Offset vector I3	-100.000000	-200.000000	100.000000 [mm]	
Rotary axis vector U2	0.000000	0.000000	-1.000000	
Offset vector I4	0.000000	0.000000	-100.000000 [mm]	
Swivel mode	Axis by axis			
Rotary axes direct	Yes	Track tool	Yes	
Projection angle	Yes			
Solid angle	Yes			
Direction refer.	Rotary axis 1, + direction selected			
JobShop functions	Automatic swivel data record change			

The desired "Tool Carrier" is selected with the first input field "TC".

If there are several Tool Carriers, the most recently programmed one is active.

In "CYCLE800" with ShopMill, the tool - as always in ShopMill - is selected directly in the input screen.



Select tool

Loc.	Type	Tool name	ST	D	Length	∅	Magazine
16	✓	DRILL_10	1	1	100.000	10.000	
17	✓	DRILL_10	1	1	100.000	10.000	
18	✓	BALL_END_CYL_D8	1	1	100.000	8.000	
19	✓	CUTTER_D5	1	1	100.000	5.000	
20	✓	CUTTER_D8	1	1	100.000	8.000	
21	✓	CUTTER_16	1	1	100.000	16.000	
22	✓	ENDMILL_D32	1	1	100.000	32.000	
23	✓	FACING_TOOL_D63	1	1	100.000	63.000	
24							
25	✓	ENDMILL_D20	1	1	100.000	20.000	
26	✓	CENTERDRILL_12	1	1	100.000	12.000	
27	✓	BALL_END_CYL_D10	1	1	100.000	5.000	
28	✓	MILL_CR00_D12	1	1	100.000	12.000	


OK



If the input field remains empty, the previous active tool is taken.

Notes:

The "retract" possibilities are:



TC		TABLE	
T	FACEMILL 63	D	1
Retract	No		
Swivel	No	Yes	
Swivel plane	Z	New	
X0	Z, XY		
Y0	Max		
Z0	inc		
Swivel mode	Axis by axis		
Sequence of axes:	Y X Z		
Y	0.000 °		
X	-15.000 °		
Z	0.000 °		
X1	0.000		
Y1	0.000		
Z1	0.000		
Select		+	

Com-	Explanation
No	No retract performed before swiveling.
Z	Retract in the direction of machine axis Z. The retract length is that selected in the program header.
ZXY	Retract in the direction of machine axis Z, and then in X and Y.
MAX	Maximum retract in the tool direction.
INK	The retract length is entered via an input field in the cycle.

ink ZR 100.000


For "Swivel", select "Yes".

This implements physical swiveling on the machine.

Swiveling is not performed for "No".

This is used, for example, when only a position should be calculated, after which a further swiveling follows.


This programming is explained in the following examples.



TC		TABLE	
T	FACEMILL 63	D	1
Retract	Z		
Swivel		Yes	
Swivel plane		New	
X0	0.000		
Y0	0.000		
Z0	0.000		
Swivel mode	Axis by axis		
Sequence of axes:	Y X Z		
Y	0.000 °		
X	-15.000 °		
Z	0.000 °		
X1	0.000		
Y1	0.000		
Z1	0.000		
Select		+	

No

Yes



If swiveling requires that the position of the coordinate system is moved, this is performed for each axis via the **X0**, **Y0** and **Z0** parameters.

Swivel plane		New
X0	0.000	
Y0	0.000	
Z0	0.000	


previous swivel plane, selectz.

The following examples are programmed with this selection.

Swivel plane Additive


Notes:

Swiveling is normally performed "axis-by-axis". Consequently, this is used in most examples.




TC	TABLE	
T	FACEMILL 63	D 1
Retract	\uparrow , Z	
Swivel		Yes
Swivel plane		Additive
X0	0.000	
Y0	0.000	
Z0	0.000	
Swivel mode	Axis by axis	
Sequence of axes	Axis by axis	
Y	0.0	Solid angle
X	-15.0	Project. angle
Z	0.0	directly
X1	0.000	
Y1	0.000	
Z1	0.000	
Select		+

The axis sequence is generally arbitrary.




- Sequence of axes:
- Y X Z
 - X Y Z
 - X Z Y
 - Y X Z**
 - Y Z X
 - Z X Y
 - Z Y X

After the rotation, a further movement can be programmed via X1, Y1, Z1.




TC	TABLE	
T		D 1
Retract	\uparrow , Z	
Swivel		Yes
Swivel plane		New
X0	0.000	
Y0	0.000	
Z0	0.000	
Swivel mode	Axis by axis	
Sequence of axes	X Y Z	
X	0.000 °	
Y	0.000 °	
Z	0.000 °	
X1	0.000	
Y1	0.000	
Z1	0.000	
Select		+




Notes:

The swivel direction can be specified in the last input field of the cycle.
 There are always two directions that mathematically lead to the result. Plus (+) and minus (-).
 The operator can select to achieve an optimum view of the workpiece.

Select -



Select +




"+" is used for programming in the examples.

In this example, swiveling is made at the Z axis.

TC	TABLE
T	FACEMILL 63 D 1
Retract	Z XY
Swivel	Yes
Swivel plane	New
X0	0.000
Y0	0.000
Z0	0.000
Swivel mode	Axis by axis
Sequence of axes:	Y X Z
Y	0.000 °
X	-15.000 °
Z	0.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+

The position of the workpiece zero point remains unchanged.




P	Program header	G54 Block	
	Swivel plane	X=0 Y=0 Z=0 Z XY	
	Face milling	T=FACEMILL 63 F=0.125/t V=650m X0=0 Y0=0 Z0=2 Z1=0	
	Swivel plane	Y=0 X=-15 Z=0 T=FACEMILL 63 Z XY	
END	End of program		

The swivel cycle is transferred to the program.




Notes:

After swiveling, the face milling cycle for milling the oblique surface opens again.
The start plane "Z0" must now be calculated.




T	FACING_TOOL_D63	D 1
F	0.200	mm/tooth
U	300.000	m/min
Machining		▽▽▽
Direction		⚡
X0	0.000	
Y0	0.000	
Z0	0.000	
X1	100.000	abs
Y1	100.000	abs
Z1	0.000	abs
DXY	75.000	%
UZ	1.000	



The values for the traversal paths are calculated with the angle functions.

- 1 Adjacent (AK)
- 2 Hypotenuse (H)
- 3 Opposite (GK)
- α Angle
- β Angle



Sine function

$$\sin \alpha = \frac{GK}{H}$$

$$H = \frac{GK}{\sin \alpha}$$

$$GK = \sin \alpha * H$$

Cosine function

$$\cos \alpha = \frac{AK}{H}$$

$$H = \frac{AK}{\cos \alpha}$$

$$AK = \cos \alpha * H$$

Tangent function

$$\tan \alpha = \frac{GK}{AK}$$

$$AK = \frac{GK}{\tan \alpha}$$

$$GK = \tan \alpha * AK$$

Notes:


Based on the current example, the following calculation results:

Note: (Calculation of the "Z0" parameter)

$$\sin \alpha = GK / HP \rightarrow \sin 15 = GK / 100$$

$$GK = \sin 15 * 100$$

$$\Rightarrow GK = \underline{25.882}$$



The calculation can be performed externally or directly in the input field.

After opening the face milling cycle,



the calculated value can be entered in the input field directly as value



T	FACEMILL 63	D 1
F	0.125 mm/tooth	
V	650.000 m/min	
Machining		▽
Direction		↕
X0	0.000	
Y0	0.000	
Z0	25.881	
X1	102.000 abs	
Y1	102.000 abs	
Z1	0.000 abs	
DXY	50.000 %	
DZ	3.000	
UZ	0.000	

or as calculated formula. The result is then automatically the value for "Z0".
 For the values "X1" and "Y1", a protrusion of 2 mm is programmed (empirical values).


$$GK = \sin 15 * 100 \rightarrow Z0 \quad \text{SIN}(15)*100$$

Notes:

After machining, the initial setting is programmed and the "TC" deselected via "CYCLE800".

The program is now fully created.

P	Program header	G54 Block	
	Swivel plane	X=0 Y=0 Z=0 Z XY	
	Face milling	T=FACEMILL 63 F=0.125/t U=650m X0=0 Y0=0 Z0=2 Z1=0	 ▾
	Swivel plane	Y=0 X=-15 Z=0 T=FACEMILL 63 Z XY	
	Face milling	T=FACEMILL 63 F=0.125/t U=650m X0=0 Y0=0 Z0=25.881	 ▾
	Swivel plane	X=0 Y=0 Z=0 T=ENDMILL_D8 Z	
	Swivel plane	Z XY TC=0	
END	End of program		



2nd example, swiveling in programGUIDE

The workpiece for the "1st example" is now created as G-code program.





Task:

The blank for the program example has the dimensions 100x100x52 mm


- ⇒ Programming in programGUIDE
- ⇒ Travel machine to the initial setting
- ⇒ Face milling of the workpiece in the initial setting at a height of 50 mm
- ⇒ Swivel the workpiece and calculate the required infeed
- ⇒ Face milling of the workpiece in the swiveled state
- ⇒ Travel machine to the initial setting

Notes:

Drawing:



Flow diagram:



Notes:

After creating a new G-code program,

describe a block structure for this G-code program.

Function	Block name
Start commands	START
Face milling initial setting	FACE_MILLING
Swivel plane	SWIVEL
Mill oblique surfaces	OBLIQUE
End commands	END

After pressing



the individual blocks in the program are created.



The blocks improve the clarity of the program. Consequently, all G-code programs are programmed as blocks in the training modules.



Notes:

The program header is programmed in the "START" block.

```
N20 G54 G17 G90 G40
N30 CYCLE800(2, "TABLE", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 1, , 1)
N40 WORKPIECE(, "C", , "BOX", 64, 2, -50, -
80, 0, 0, 100, 100)
N50 T="ENDMILL_D32"
N60 M6
N70 D1
N80 S5000 M3
```


```
N10 START
N20 G54 G17 G40 G90
N30 CYCLE800(2, "TABLE", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 1, 100, 1)
N40 WORKPIECE(, "C", , "BOX", 112, 2, -50, -80, 0, 0, 100, 100)
N50 T="FACEMILL_63"
N60 M6
N70 S2000 F1000 M3
N80 End of group
```

It is important that travel to the "Initial setting" is always programmed before the first machining block with "CYCLE800".

The face milling in the initial setting is programmed in the "FACE_MILLING" block.

```
N100 G0 X5 Y5 Z5
N110 CYCLE61
(10, 1, 5, 0, 0, 0, 100, 100, 1, 50, 0, 2000, 32, 0, 1, 10)
N120 G0 Z200
```

```
N90 FACE_MILLING
N100 G0 X5 Y5 Z5
N110 CYCLE61(10, 2, 5, 0, 0, 0, 100, 100, 3, 75, 0, 2000, 31, 0, 1, 10)
N120 G0 Z200
N130 End of group
```



The swiveling of the plane defined in the "PL" field is programmed in the "SWIVEL" block.


PL	G17 (XY)
TC	TABLE
Retract	Z XY
Swivel	Yes
Swivel plane	New
X0	0.000
Y0	0.000
Z0	0.000
Swivel mode	Axis by axis
Sequence of axes	Z Y X
Z	0.000 °
Y	0.000 °
X	-15.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+

```
N160 CYCLE800(2, "TABLE", 200000, 27, 0, 0, 0, 0, 0, 15, 0, 0, 0, 0, 1, , 1)
```


```
N140 SWIVEL
N150 CYCLE800(2, "TABLE", 200000, 27, 0, 0, 0, 0, 0, -15, 0, 0, 0, 1, 100, 1)
N160 End of group
```

Notes:

The oblique surface is programmed in the "OBLIQUE" block.



PL	G17 (XY)
RP	30.000
SC	5.000
F	2000.000
Machining	▽
Direction	⇄
X0	0.000
Y0	0.000
Z0	SIN(15)*105
X1	102.000 abs
Y1	102.000 abs
Z1	0.000 abs
DXY	50.000 %
DZ	3.000
UZ	0.000



The "Z0" start plane is calculated with the formula programmed directly in the associated input field. The value 105 used here includes the tool protrusion in the calculation.
 CYCLE61 (100, SIN (15) *105, 1, 0, 100, 0, 0, 100, 5, 5, 0.2, 3000, 21, 0, 1, 11000)

```

N170 OBLIQUE
N180 CYCLE61(30, 25.881, 5, 0, 0, 0, 102, 102, 3, 50, 0, 2000, 31, 0, 1, 11010)
N190 End of group
    
```

The program end is programmed in the "END" block.


```

N210 CYCLE800(2, "TABLE", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, 100, 1)
N220 CYCLE800(2, "0", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, 100, 1)
N230 M30
    
```

```

N200 END
N210 CYCLE800(2, "TABLE", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, 100, 1)
N220 CYCLE800(2, "0", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, 100, 1)
N230 M30
    
```

The program is fully programmed.




Notes:

3rd example, swivelling axis-by-axis**Task:**

The blank for the program example has the dimensions 100x100x50 mm

- ⇒ Programming in programGUIDE
- ⇒ Programming chamfers with "**Axis-by-axis swiveling**"

Drawing:

Notes:

After creating a new G-code program,

New G code program

Type

Name

a new block structure for this G-code program is programmed.

Function	Block name
Start commands	START
1st swivel	1_SWIVEL
1st operation	1_CHAMFER
2nd swivel	2_SWIVEL
2nd operation	2_CHAMFER
3rd swivel	3_SWIVEL
3rd operation	3_CHAMFER
4th swivel	4_SWIVEL
4th operation	4_CHAMFER
End commands	END

```

+ N10 START
+ N90 1_SWIVEL
+ N120 1_CHAMFER
+ N190 2_SWIVEL
+ N220 2_CHAMFER
+ N290 3_SWIVEL
+ N320 3_CHAMFER
+ N390 4_SWIVEL
+ N420 4_CHAMFER
+ N490 END
    
```

The "START" block is programmed.




```

N20 G54 G17 G40 G90
N30 CYCLE800(2,"TABLE",200000,57,0,0,0,0,0,0,0,0,0,0,1,100,1)
N40 WORKPIECE(", "C", , "RECTANGLE", 0, 0, -50, -80, 100, 100)
N50 T="CUTTER 16"
N60 M6
N70 S2000 F1000 M3
    
```

```


N10 START
N20 G54 G17 G40 G90
N30 CYCLE800(2,"TABLE",200000,57,0,0,0,0,0,0,0,0,0,0,1,100,1)
N40 WORKPIECE(", "C", , "RECTANGLE", 0, 0, -50, -80, 100, 100)
N50 T="CUTTER 16"
N60 M6
N70 S2000 F1000 M3
N80 End of group
    
```

- 1st step:** Move the coordinate system from the center to the point where the edge should result.
- 2nd step:** Always rotate at the center point.
- 3rd step:** Swivel by 45°.




Notes:

In the first step, move the coordinate cross to the swivel point (chamfer start).
The coordinate cross is then swiveled by 45°.



PL	G17 (XY)
TC	TABLE
Retract	Z XY
Swivel	Yes
Swivel plane	New
X0	40.000
Y0	0.000
Z0	0.000
Swivel mode	Axis by axis
Sequence of axes	Z Y X
Z	0.000 °
Y	45.000 °
X	0.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+



Pressing



accepts the values in block.


the "1_SWIVEL"

```
N90 1_SWIVEL
N100 CYCLE800(2, "TABLE", 200000, 27, 40, 0, 0, 0, 45, 0, 0, 0, 0, 1, 100, 1)
N110 End of group
```

The first chamfer is programmed in the "1_CHAMFER" block.


```
N130 G0 X8 Y-65 Z100
N140 G0 Z5
N150 G1 Z0
N160 G1 Y65
N170 G0 Z100
```

```
N120 1_CHAMFER
N130 G0 X8 Y-65 Z100
N140 G0 Z5
N150 G1 Z0
N160 G1 Y65
N170 G0 Z100
N180 End of group
```




The second swivel is programmed in the "2_SWIVEL"

block.



PL	G17 (XY)
TC	TABLE
Retract	Z XY
Swivel	Yes
Swivel plane	New
X0	0.000
Y0	40.000
Z0	0.000
Swivel mode	Axis by axis
Sequence of axes	Z Y X
Z	90.000 °
Y	45.000 °
X	0.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+




Notes:

The second chamfer is programmed in the "2_CHAMFER" block. It corresponds exactly to the first programming for "1_CHAMFER". Only the coordinate system is rotated by "Z".


```
N230 G0 X8 Y-65 Z100
N240 G0 Z5
N250 G1 Z0
N260 G1 Y65
N270 G0 Z100
```

```
N220 2_CHAMFER
N230 G0 X8 Y-65 Z100
N240 G0 Z5
N250 G1 Z0
N260 G1 Y65
N270 G0 Z100
N280 End of group
```

The swivel is programmed in the "3_SWIVEL" block.



PL G17 (XY)	
TC	TABLE
Retract	Z XY
Swivel	Yes
Swivel plane	New
X0	-40.000
Y0	0.000
Z0	0.000
Swivel mode	Axis by axis
Sequence of axes	Z Y X
Z	180.000 °
Y	45.000 °
X	0.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+




The third chamfer is programmed in the "3_CHAMFER" block.


```
N330 G0 X8 Y-65 Z100
N340 G0 Z5
N350 G1 Z0
N360 G1 Y65
N370 G0 Z100
```

```
N320 3_CHAMFER
N330 G0 X8 Y-65 Z100
N340 G0 Z5
N350 G1 Z0
N360 G1 Y65
N370 G0 Z100
N380 End of group
```

The swivel is programmed in the "4_SWIVEL" block.



PL G17 (XY)	
TC	TABLE
Retract	Z XY
Swivel	Yes
Swivel plane	New
X0	0.000
Y0	-40.000
Z0	0.000
Swivel mode	Axis by axis
Sequence of axes	Z Y X
Z	270.000 °
Y	45.000 °
X	0.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+




Notes:

The fourth chamfer is programmed in the "4_CHAMFER" block.

```

N430 G0 X8 Y-65 Z100
N440 G0 Z5
N450 G1 Z0
N460 G1 Y65
N470 G0 Z100
N420 4_CHAMFER
N430 G0 X8 Y-65 Z100
N440 G0 Z5
N450 G1 Z0
N460 G1 Y65
N470 G0 Z100
N480 End of group
    
```




In the "END" block, "CYCLE800" travels to the initial setting and the Tool Carrier is deselected.

The program is now fully created.

```

N490 END
N400 CYCLE800(2, "TABLE", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, 100, 1)
N410 CYCLE800(1, "0", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, 100, 1)
M30
N500 End of group
    
```



How the axes are swiveled on the machine is immaterial for this programming.

Only rotations at the axes of the coordinate system are considered.

The control then implements this on the machine.

4th example, swiveling with spatial angle

The **spatial angle** is the three-dimensional counterpart of the normal two-dimensional angle.

With regard to CNC technology, this describes the position of the workpiece coordinate system by the spatially-fixed coordinate system.

This is independent of the actual machine axes.

This has the advantage that the angle values can be taken directly from the drawing. The position is determined by two spatial angles.

The rotation direction of the two spatial angles can also be determined with the "right-hand rule".

- The thumb points in the positive axis direction.
- The bent fingers point in the positive rotation direction.




SINUMERIK converts the spatial angle relative to the associated machine kinematics in the machine axis angle.

Notes:

Task:

The blank for the program example has the dimensions 100x100x50 mm

- ⇒ Programming in programGUIDE
- ⇒ The program is programmed on the basis of spatial angles.

Drawing:

Notes:

After creating a new G-code program,

New G code program

Type Main program MPF

Name EXAMPLE_04

describe a block structure for this G-code program.

Function	Block name
Start commands	START
1st swivel	1_SWIVEL
1st operation	1_CHAMFER
2nd swivel	2_SWIVEL
2nd operation	2_CHAMFER
3rd swivel	3_SWIVEL
3rd operation	3_CHAMFER
4th swivel	4_SWIVEL
4th operation	4_CHAMFER
End commands	END

```

+ N10 START
+ N90 1_SWIVEL
+ N120 1_CHAMFER
+ N190 2_SWIVEL
+ N220 2_CHAMFER
+ N290 3_SWIVEL
+ N320 3_CHAMFER
+ N390 4_SWIVEL
+ N420 4_CHAMFER
+ N490 END
    
```

The "START" block is programmed.


```

N20 G54 G17 G40 G90
N30 CYCLE800(2, "TABLE", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, 100, 1)
N40 WORKPIECE(, "C", , "RECTANGLE", 0, 0, -50, -80, 100, 100)
N50 T="CUTTER 16"
N60 M6
N70 S2000 F1000 M3
    
```

```


- N10 START
  N20 G54 G17 G40 G90
  N30 CYCLE800(2, "TABLE", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, 100, 1)
  N40 UORKPIECE(, "C", , "RECTANGLE", 0, 0, -50, -80, 100, 100)
  N50 T="CUTTER 16"
  N60 M6
  N70 S2000 F1000 M3
    
```

- 1st step:** Move the coordinate system from the center to the point where the edge should result.
- 2nd step:** Always rotate at the center point.
- 3rd step:** Swivel by 45°.



Notes:


The spatial angle is selected in "CYCLE800".



PL	G17 (XY)
TC	TABLE
Retract	↓, Z
Swivel	Yes
Swivel plane	New
X0	40.000
Y0	0.000
Z0	0.000
Swivel mode	Solid angle Axis by axis
α	0.0 Solid angle
β	0.0 Project. angle directly
X1	0.000
Y1	0.000
Z1	0.000
Select	+


Alpha specifies the rotation angle in the X/Y plane (at the Z axis).

α 0.000 °




Beta specifies the rotation angle in space (rotation at the new Y axis).

β 0.000 °





In the **first** step, the coordinate cross is moved to the swivel point (chamfer start).

The coordinate cross is then swiveled by 45° at beta in space.



PL	G17 (XY)
TC	TABLE
Retract	↓, Z
Swivel	Yes
Swivel plane	New
X0	40.000
Y0	0.000
Z0	0.000
Swivel mode	Solid angle
α	0.000 °
β	45.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+
Tool	⏴



Notes:

Pressing



accepts the values in the "1_SWIVEL" block.


```

N90 1_SWIVEL
N100 CYCLE800(1, "TABLE", 200000, 64, 40, 0, 0, 0, 45, , 0, 0, 0, 1, 100, 1)
N110 End of group
    
```

The first chamfer is programmed in the "1_CHAMFER" block.


```

N130 G0 X8 Y-65 Z100
N140 G0 Z5
N150 G1 Z0
N160 G1 Y65
N170 G0 Z100
N120 1_CHAMFER
N130 G0 X8 Y-65 Z100
N140 G0 Z5
N150 G1 Z0
N160 G1 Y65
N170 G0 Z100
    
```



The second swivel is programmed in the "2_SWIVEL" block.

	PL	G17 (XY)
	TC	TABLE
	Retract	Z
	Swivel	Yes
	Swivel plane	New
	X0	0.000
	Y0	40.000
	Z0	0.000
	Swivel mode	Solid angle
	α	90.000 °
β	45.000 °	
X1	0.000	
Y1	0.000	
Z1	0.000	
Select	+	




α 90.000 °
β 45.000 °

Notes:

The second chamfer is programmed in the "2_CHAMFER" block. It corresponds exactly to the first chamfer.


```
N230 G0 X8 Y-65 Z100
N240 G0 Z5
N250 G1 Z0
N260 G1 Y65
N270 G0 Z100
```

```
N220 2_CHAMFER
N230 G0 X8 Y-65 Z100
N240 G0 Z5
N250 G1 Z0
N260 G1 Y65
N270 G0 Z100
N280 End of group
```



The swivel is programmed in the "3_SWIVEL" block.


PL	G17 (XY)
TC	TABLE
Retract	Z
Swivel	Yes
Swivel plane	New
X0	-40.000
Y0	0.000
Z0	0.000
Swivel mode	Solid angle
α	180.000 °
β	45.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+



The third chamfer is programmed in the "3_CHAMFER" block.


```
N330 G0 X8 Y-65 Z100
N340 G0 Z5
N350 G1 Z0
N360 G1 Y65
N370 G0 Z100
```

```
N320 3_CHAMFER
N330 G0 X8 Y-65 Z100
N340 G0 Z5
N350 G1 Z0
N360 G1 Y65
N370 G0 Z100
```



The swivel is programmed in the "4_SWIVEL" block.

PL	G17 (XY)
TC	TABLE
Retract	Z
Swivel	Yes
Swivel plane	New
X0	0.000
Y0	-40.000
Z0	0.000
Swivel mode	Solid angle
α	270.000 °
β	45.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+




Notes:

The fourth chamfer is programmed in the "4_CHAMFER" block.

```
N430 G0 X8 Y-65 Z100
N440 G0 Z5
N450 G1 Z0
N460 G1 Y65
N470 G0 Z100
```


```
N420 4_CHAMFER
N430 G0 X8 Y-65 Z100
N440 G0 Z5
N450 G1 Z0
N460 G1 Y65
N470 G0 Z100
N480 End of group
```



In the "END" block, "CYCLE800" travels to the initial setting and the Tool Carrier deselected.

The program is now fully created.

```
N490 END
N500 CYCLE800(2, "TABLE", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, 100, 1)
N510 CYCLE800(1, "0", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, 100, 1)
N520 M30
```



5th example, swiveling with projection angle

The blank for the program example has the dimensions 100x100x50 mm

- ⇒ Programming in programGUIDE
- ⇒ The program is programmed on the basis of projection angles

The projection angle is used for rectangular workpieces.

The projection angle also consists of angles that build on each other.

The angles $X\alpha$ and $Y\alpha$ always refer to the non-rotated coordinate system.

The angle $Z\beta$ refers to the rotated coordinate system.

$X\alpha$	0.000 °
$Y\alpha$	0.000 °
$Z\beta$	0.000 °



Notes:

After creating a new G-code program,

New G code program

Type

Name

describe a block structure for this G-code program.

Function	Block name
Start commands	START
1st swivel	1_SWIVEL
1st operation	1_CHAMFER
2nd swivel	2_SWIVEL
2nd operation	2_CHAMFER
3rd swivel	3_SWIVEL
3rd operation	3_CHAMFER
4th swivel	4_SWIVEL
4th operation	4_CHAMFER
End commands	END

```

+ N10 START
+ N90 1_SWIVEL
+ N120 1_CHAMFER
+ N190 2_SWIVEL
+ N220 2_CHAMFER
+ N290 3_SWIVEL
+ N320 3_CHAMFER
+ N390 4_SWIVEL
+ N420 4_CHAMFER
+ N490 END
    
```

The "START" block is programmed.




```

N20 G54 G17 G40 G90
N30 CYCLE800(2,"TABLE",200000,57,0,0,0,0,0,0,0,0,0,0,1,100,1)
N40 WORKPIECE("C",,"RECTANGLE",0,0,-50,-80,100,100)
N50 T="CUTTER 16"
N60 M6
N70 S2000 F1000 M3
    
```

```


N10 START
N20 G54 G17 G40 G90
N30 CYCLE800(2,"TABLE",200000,57,0,0,0,0,0,0,0,0,0,0,1,100,1)
N40 WORKPIECE("C",,"RECTANGLE",0,0,-50,-80,100,100)
N50 T="CUTTER 16"
N60 M6
N70 S2000 F1000 M3
    
```

- 1st step:** Move the coordinate system from the center to the point where the edge should result.
- 2nd step:** Always rotate at the center point.
- 3rd step:** Swivel by 45°.





Notes:

The projection angle is selected in "CYCLE800".



In the first step, move the coordinate cross to the swivel point (chamfer start).

The coordinate cross is then swiveled by 45°.



Notes:

Pressing



accepts the values in the "1_SWIVEL" block.

```

N90 1_SWIVEL
CYCLE800(1, "TABLE", 200000, 185, 40, 0, 0, 0, 45, 0, 0, 0, 0, 1, 100, 1)
N110 End of group
    
```


The first chamfer is programmed in the "1_CHAMFER" block.

```


N130 G0 X8 Y-65 Z100
N140 G0 Z5
N150 G1 Z0
N160 G1 Y65
N170 G0 Z100
    
```

```



N120 1_CHAMFER
N130 G0 X8 Y-65 Z100
N140 G0 Z5
N150 G1 Z0
N160 G1 Y65
N170 G0 Z100
    
```



The second swivel is programmed in the "2_SWIVEL" block.



PL	G17 (XY)
TC	TABLE
Retract	Z
Swivel	Yes
Swivel plane	New
X0	0.000
Y0	40.000
Z0	0.000
Swivel mode	Project. angle
Projection pos.	Xα Yα Zβ
Xα	-45.000 °
Yα	0.000 °
Zβ	90.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+



```

Xα -45.000 °
Yα 0.000 °
Zβ 90.000 °
    
```




Notes:

The second chamfer is programmed in the "2_CHAMFER" block. It corresponds exactly to the first programming for "1_CHAMFER".

```
N230 G0 X8 Y-65 Z100
N240 G0 Z5
N250 G1 Z0
N260 G1 Y65
N270 G0 Z100
```

```
N220 2_CHAMFER
N230 G0 X8 Y-65 Z100
N240 G0 Z5
N250 G1 Z0
N260 G1 Y65
N270 G0 Z100
N280 End of group
```




The swivel is programmed in the "3_SWIVEL" block.

PL	G17 (XY)
TC	TABLE
Retract	Z
Swivel	Yes
Swivel plane	New
X0	-40.000
Y0	0.000
Z0	0.000
Swivel mode	Project. angle
Projection pos.	Xα Yα Zβ
Xα	0.000 °
Yα	-45.000 °
Zβ	180.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+

The third chamfer is programmed in the "3_CHAMFER" block.

```
N330 G0 X8 Y-65 Z100
N340 G0 Z5
N350 G1 Z0
N360 G1 Y65
N370 G0 Z100
```

```
N320 3_CHAMFER
N330 G0 X8 Y-65 Z100
N340 G0 Z5
N350 G1 Z0
N360 G1 Y65
N370 G0 Z100
N380 End of group
```



The swivel is programmed in the "4_SWIVEL" block.


PL	G17 (XY)
TC	TABLE
Retract	Z
Swivel	Yes
Swivel plane	New
X0	0.000
Y0	-40.000
Z0	0.000
Swivel mode	Project. angle
Projection pos.	Xα Yα Zβ
Xα	45.000 °
Yα	0.000 °
Zβ	270.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+

Notes:

The fourth chamfer is programmed in the "4_CHAMFER" block.

```
N430 G0 X8 Y-65 Z100
N440 G0 Z5
N450 G1 Z0
N460 G1 Y65
N470 G0 Z100
```


```
N420 4_CHAMFER
N430 G0 X8 Y-65 Z100
N440 G0 Z5
N450 G1 Z0
N460 G1 Y65
N470 G0 Z100
N480 End of group
```



In the "END" block, "CYCLE800" travels to the initial setting and the Tool Carrier is deselected.

The program is now fully created.

```
N490 END
N500 CYCLE800(2, "TABLE", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, 100, 1)
N510 CYCLE800(1, "0", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, 100, 1)
N520 M30
```



[6th example, swivelling directly](#)

Example for the projection angle.

Another example for projection angle is listed and described step-by-step.

This example cannot be programmed axis-by-axis with these dimensions, because the second axis rotation already refers to a rotated coordinate system.





This is not the case with projection angles. The rotations refer to the projected component edge.

The blank for the program example has the dimensions 100x100x50 mm

- ⇒ Programming in ShopMill
- ⇒ The surface is programmed on the basis of projection angles

Notes:


Drawing:



After creating a new ShopMill program




and programming the program header,




Notes:

the swivel is programmed via "CYCLE800".
To improve clarity, the coordinate system on the completed component is shown.

In the first step, the coordinate system is moved by 25 mm in the "Z direction".




"Xα" is the angle by which the X axis must be rotated so that the component edge results in the Y/Z plane.




Notes:

Again, starting from the implicit, non-rotated coordinate cross,





the second projection angle "Yα" is programmed. This is the angle by which the Y axis must be rotated so that the shown component edge results.

TABLE	
TC	ENDMILL_D8 D 1
Retract	Z XY
Swivel	Yes
Swivel plane	New
X0	0.000
Y0	0.000
Z0	25.000
Swivel mode	Project. angle
Projection pos.	Xα Yα Zβ
Xα	14.036 °
Yα	-10.000 °
Zβ	0.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+



The surface can be programmed only via projection angles, but not via axis angles.




Notes:

6th example, direct swivel


Task:

The blank for the program example has the dimensions 100x100x50 mm
 => Programming in programGUIDE
 => The program is programmed "directly" with "A-C" kinematics

Drawing:



After creating a new G-code program,




describe a block structure for this G-code program.

Function	Block name
Start commands	START
1st swivel	1_SWIVEL
1st operation	1_CHAMFER
2nd swivel	2_SWIVEL
2nd operation	2_CHAMFER
3rd swivel	3_SWIVEL
3rd operation	3_CHAMFER
4th swivel	4_SWIVEL
4th operation	4_CHAMFER
End commands	END



Notes:

The tool axes are rotated so that the first chamfer can then be produced.



Pressing



accepts the values in the "1_SWIVEL" block.


```
1_SWIVEL
CYCLE800(1, "TABLE", 200000, 192, 40, 0, 0, -45, -90, 90, 0, 0, 0, 1, 100, 1)¶
```

The first chamfer is programmed in the "1_CHAMFER" block.

```
G0 X7 Y-60 Z100
G0 Z5
G1 Z0
G1 Y60
G0 Z100
```





```
1_CHAMFER
G0 X7 Y-60 Z100¶
G0 Z5¶
G1 Z0¶
G1 Y60¶
G0 Z100¶
End of group
```



Notes:

The second swivel is programmed in the "2_SWIVEL" block.

PL	G17 (XY)
TC	TABLE
Retract	Z
Swivel	Yes
Swivel plane	New
X0	0.000
Y0	40.000
Z0	0.000
Swivel mode	directly
A	-45.000 °
C	0.000 °
Z	90.000 °
X1	0.000
Y1	0.000
Z1	0.000





The second chamfer is programmed in the "2_CHAMFER" block. It corresponds exactly to the first programming for "1_CHAMFER".

```



G0 X7 Y-60 Z100
G0 Z5
G1 Z0
G1 Y60
G0 Z100
    
```

2_CHAMFER	
G0	X7 Y-60 Z100
G0	Z5
G1	Z0
G1	Y60
G0	Z100



The swivel is programmed in the "3_SWIVEL" block.

PL	G17 (XY)
TC	TABLE
Retract	Z
Swivel	Yes
Swivel plane	New
X0	-40.000
Y0	0.000
Z0	0.000
Swivel mode	directly
A	-45.000 °
C	90.000 °
Z	90.000 °
X1	0.000
Y1	0.000
Z1	0.000





Notes:


The third chamfer is programmed in the "3_CHAMFER" block.

```
G0 X7 Y-60 Z100
G0 Z5
G1 Z0
G1 Y60
G0 Z100
```

```
3_CHAMFER
G0 X7 Y-60 Z100¶
G0 Z5¶
G1 Z0¶
G1 Y60¶
G0 Z100¶
End of group
```



The swivel is programmed in the "4_SWIVEL" block.




PL	G17 (XY)
TC	TABLE
Retract	Z
Swivel	Yes
Swivel plane	New
X0	0.000
Y0	-40.000
Z0	0.000
Swivel mode	directly
A	-45.000 °
C	180.000 °
Z	90.000 °
X1	0.000
Y1	0.000
Z1	0.000

The fourth chamfer is programmed in the "4_CHAMFER" block.

```
G0 X7 Y-60 Z100
G0 Z5
G1 Z0
G1 Y60
G0 Z100
```


```
4_CHAMFER
G0 X7 Y-60 Z100¶
G0 Z5¶
G1 Z0¶
G1 Y60¶
G0 Z100¶
End of group
```



In the "END" block, "CYCLE800" travels to the initial setting and the Tool Carrier is deselected.

The program is now fully created.

```
END
CYCLE800(1, "TABLE", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, 100, 1)¶
CYCLE800(1, "0", 200000, 192, 0, -40, 0, -45, 180, 90, 0, 0, 0, 1, 100, 1)¶
M30¶
```



Notes:

7th example, complex with ShopMill**Task:**




The blank for the program example has the dimensions 100x100x52 mm

- ⇒ Programming in ShopMill
- ⇒ Face milling in the initial setting
- ⇒ Milling oblique surface 15°
- ⇒ Milling centered circular pocket (roughing, finishing)
- ⇒ Milling "1st corner" (roughing, finishing)
- ⇒ Milling "2nd corner" (roughing, finishing)
- ⇒ Circular pockets (-7°) (roughing)
- ⇒ Circular pockets (7°) (roughing)
- ⇒ 1st circular pocket on oblique surface (roughing, finishing)
- ⇒ 2nd circular pocket on oblique surface (roughing, finishing)






Notes:

Drawing, 1st view




Notes:

Drawing, 2nd view



Notes:

Flow diagram:

A new program is created.

Machine manufacturers can program a different behavior for "CYCLE800".


- **New:** Before each tool change, "CYCLE800" must travel to the initial setting. The swivel plane must then be reprogrammed.
Example: Centering, drilling, reaming.
If no "CYCLE800" is programmed in the initial setting, the tool is switched to the swivel plane.
- **Chaining:** After machining in a swivel plane, another cycle in which a tool change is programmed can be called directly. For the tool change, ShopMill travels automatically to the initial setting, changes the tool and swivels in the most-recently programmed plane and continues the program.
(Example: roughing circular pocket, finishing circular pocket with two different tools).

Die Umsetzung ist alleine Sache des Maschinenherstellers.




Notes:

After entering the program header,




Work offset	G54
Blank	Block
X0	0.000
Y0	0.000
X1	100.000 abs
Y1	100.000 abs
ZA	2.000
ZI	-50.000 abs
PL	G17 (XY)
Retraction plane	
RP	100.000
Safety distance	
SC	2.000
Machining sense	
Up-cut	
Retract position pattern	Optimized

travel is made to the initial setting in the next step.




TC	TABLE
T	D 1
Retract	Z, XY
Swivel	Yes
Swivel plane	New
X0	0.000
Y0	0.000
Z0	0.000
Swivel mode	Axis by axis
Sequence of axes	X Y Z
X	0.000 °
Y	0.000 °
Z	0.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+

The face cutting in the non-swiveled state follows.



T	FACEMILL 63	D 1
F	0.125 mm/tooth	
V	650.000 m/min	
Machining		
Direction		
X0	0.000	
Y0	0.000	
Z0	2.000	
X1	100.000 inc	
Y1	100.000 inc	
Z1	0.000 abs	
DXY	75.000 %	
DZ	3.000	
UZ	0.000	



Notes:

A swivel is made on the machining plane of -15° .






TABLE	
T	FACEMILL 63 D 1
Retract	↕, Z XY
Swivel	Yes
Swivel plane	New
X0	0.000
Y0	0.000
Z0	0.000
Swivel mode	Axis by axis
Sequence of axes	Z Y X
Z	0.000 °
Y	0.000 °
X	-15.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+




The face cutting in the swivel plane follows. A protrusion >100 mm is programmed in "X1" and "Y1" so that no edge remains.



FACEMILL 63 D 1	
F	0.125 mm/tooth
U	650.000 m/min
Machining	▾
Direction	↻
X0	0.000
Y0	0.000
Z0	25.881
X1	102.000 abs
Y1	102.000 abs
Z1	0.000 abs
DXY	50.000 %
DZ	3.000
UZ	0.000

P	Program header	G54 Block
	Swivel plane	X=0 Y=0 Z=0 Z XY
	Face milling	T=FACEMILL 63 F=0.125/t U=650m X0=0 Y0=0 Z0=2 Z1=0
	Swivel plane	Z=0 Y=0 X=-15 T=FACEMILL 63 Z XY
	Face milling	T=FACEMILL 63 F=0.125/t U=650m X0=0 Y0=0 Z0=25.881





Notes:

A circular pocket is produced.

Input		Complete
T	ENDMILL_D16	D 1
F	0.205	mm/tooth
V	350.000	m/min
Machining		
	Centric	
	Single position	
X0	50.000	
Y0	51.760	
Z0	0.000	
∅	40.000	
Z1	-15.500	abs
DXY	65.000	%
DZ	6.000	
UXY	0.200	
UZ	0.200	
Insertion Helical		
EP	1.500	mm/rev
ER	6.000	
Removing	Comp. machining	


Input		Complete
T	ENDMILL_D16	D 1
F	0.205	mm/tooth
V	350.000	m/min
Machining		
	Centric	
	Single position	
X0	50.000	
Y0	51.760	
Z0	0.000	
∅	40.000	
Z1	-15.500	abs
DXY	50.000	%
DZ	15.500	
UXY	0.200	
UZ	0.200	
Insertion Helical		
EP	1.500	mm/rev
ER	6.000	

The oblique surface is programmed in the next step. To do this, a swivel is made to a new machining plane.



TC		TABLE
T	ENDMILL_D16	D 1
Retract	↳, Z XY	
Swivel	Yes	
Swivel plane	New	
X0	0.000	
Y0	0.000	
Z0	-25.000	
Swivel mode	Axis by axis	
Sequence of axes:	Z X Y	
Z	-45.000 °	
X	54.736 °	
Y	0.000 °	
X1	0.000	
Y1	0.000	
Z1	0.000	
Select	+	

The value for "X" is calculated as follows.
 $(90^\circ - 35.264^\circ = 54.736)$



Notes:

The inputs for face milling the surface are then made.
Parameter "Z0" must be calculated.

Note: (Calculation of the "Z0" parameter)

$$\sin \alpha = GK / HP$$

$$GK = \sin 35.264 \cdot 25$$

The values "X0", "X1", "Y0" and "Y1" specify the dimensions of the milling plane.

T	ENDMILL_D16	D 1
F	0.200	mm/tooth
V	300.000	m/min
Machining		
Direction		
X0	-20.000	
Y0	0.000	
Z0	14.434	
X1	40.000	inc
Y1	32.000	inc
Z1	0.000	abs
DXY	65.000	%
DZ	6.000	
UZ	0.200	

T	ENDMILL_D16	D 1
F	0.200	mm/tooth
V	300.000	m/min
Machining		
Direction		
X0	-20.000	
Y0	0.000	
Z0	0.200	
X1	40.000	inc
Y1	32.000	inc
Z1	0.000	abs
DXY	65.000	%
UZ	0.200	

The second oblique surface is programmed in the next step.
To do this, a swivel is made to a new machining plane.
The value for "X" is calculated as follows. ($90^\circ - 35.264^\circ = 54.736^\circ$)

TC	TABLE	
T	ENDMILL_D16	D 1
Retract	Z XY	
Swivel	Yes	
Swivel plane	New	
X0	100.000	
Y0	0.000	
Z0	-25.000	
Swivel mode	Axis by axis	
Sequence of axes	Z X Y	
Z	45.000	°
X	54.736	°
Y	0.000	°
X1	0.000	
Y1	0.000	
Z1	0.000	
Select Tool		

Notes:

The inputs for face milling the surface are then made.

Parameter "Z0" must be calculated.

Note: ➔ (Calculation of the "Z0" parameter)

$$\sin \alpha = GK / HP$$

$$GK = \sin 35.264 \cdot 25$$

$$\Rightarrow GK = 14.4336$$

Parameter	Value
T	ENDMILL_D16 D 1
F	0.200 mm/tooth
U	300.000 m/min
Machining Direction	
X0	-20.000
Y0	0.000
Z0	14.434
X1	40.000 inc
Y1	32.000 inc
Z1	0.000 abs
DXY	65.000 %
DZ	6.000
UZ	0.200

The circular pockets below (-7°) are produced in the next step.

A selection can be made in "CYCLE800".

Swivel	No
Swivel plane	No
	Yes

No swiveling is performed for "Swivel No". This swivels to a "theoretical plane" used as basis for the next swiveling.

Parameter	Value
TC	TABLE
T	ENDMILL_D8 D 1
Retract	Z XY
Swivel	No
Swivel plane	New
X0	0.000
Y0	0.000
Z0	0.000
Swivel mode	Axis by axis
Sequence of axes	X Y Z
X	-15.000 °
Y	0.000 °
Z	0.000 °
X1	50.000
Y1	51.760
Z1	0.000
Select	+

Swiveling is first made to the center in this example.

Notes:

"CYCLE800" is called again.

A further swivel plane is now programmed additive on the previous theoretical swiveling.



The degree (-7) and the position of the first circular pocket are programmed.

Swivel plane

Additive

New




Additive



```

Swivel plane X=-15 Y=0 Z=0 T=ENDMILL_D8 Z XY
Swivel plane Additive Z=0 Y=-7 X=0 T=ENDMILL_D8 Z XY
    
```

The two circular pockets are programmed.




Die Position der zweiten Kreistasche wird direkt im Zyklus programmiert.

Notes:


The circular pockets below (7°) are programmed.

Swivel	No
Swivel plane	No
	Yes

A swivel is made to the workpiece center.




TC	TABLE	
T	ENDMILL_D8	D 1
Retract	↑, Z XY	
Swivel	No	
Swivel plane	New	
X0	0.000	
Y0	0.000	
Z0	0.000	
Swivel mode	Axis by axis	
Sequence of axes:	X Y Z	
X	-15.000 °	
Y	0.000 °	
Z	0.000 °	
X1	50.000	
Y1	51.760	
Z1	0.000	
Select	+	




"CYCLE800" is called again.

A swivel is made "additive" to (7°).



TC	TABLE	
T	ENDMILL_D8	D 1
Retract	↑, Z XY	
Swivel	Yes	
Swivel plane	Additive	
X0	35.000	
Y0	35.000	
Z0	0.000	
Swivel mode	Axis by axis	
Sequence of axes:	Z Y X	
Z	0.000 °	
Y	7.000 °	
X	0.000 °	
X1	0.000	
Y1	0.000	
Z1	0.000	
Select	+	

Swivel plane	Additive
	New
	Additive



 Swivel plane	X=-15 Y=0 Z=0 T=ENDMILL_D8 Z XY
 Swivel plane	Additive Z=0 Y=7 X=0 T=ENDMILL_D8 Z XY



Notes:

The two circular pockets are programmed.

Input Complete

T	ENDMILL_D8	D 1
F	0.205	mm/tooth
U	350.000	m/min
Machining	Helical	
	Single position	
X0	0.000	
Y0	0.000	
Z0	0.000	
∅	10.000	
Z1	-10.000	abs
DXY	60.000	%
P	1.000	mm/rev
UXY	0.000	
UZ	0.000	

Removing Comp. machining

Input Complete

T	ENDMILL_D8	D 1
F	0.205	mm/tooth
U	350.000	m/min
Machining	Helical	
	Single position	
X0	0.000	
Y0	-59.000	
Z0	0.000	
∅	10.000	
Z1	-10.000	abs
DXY	60.000	%
P	1.000	mm/rev
UXY	0.000	
UZ	0.000	

Removing Comp. machining

Die Position der zweiten Kreistasche wird direkt im Zyklus programmiert.

A swivel is made on the first corner.

TC TABLE

T	ENDMILL_D8	D 1
Retract	Z XY	
Swivel	Yes	
Swivel plane	New	
X0	0.000	
Y0	0.000	
Z0	-25.000	
Swivel mode	Axis by axis	
Sequence of axes	Z X Y	
Z	-45.000	°
X	54.736	°
Y	0.000	°
X1	0.000	
Y1	0.000	
Z1	0.000	

Select +

C-C

35,264°

20,4

25

Notes:

The circular pocket is programmed in the next step.

Input Complete		
T	ENDMILL_D8	D 1
F	0.205	mm/tooth
V	350.000	m/min
Machining		
	Helical	
	Single position	
X0	0.000	
Y0	20.400	
Z0	0.000	
∅	10.000	
Z1	-5.000	abs
DXY	60.000	%
P	1.000	mm/rev
UXY	0.100	
UZ	0.000	

Input Complete		
T	ENDMILL_D8	D 1
F	0.205	mm/tooth
V	350.000	m/min
Machining		
	Helical	
	Single position	
X0	0.000	
Y0	20.400	
Z0	0.000	
∅	10.000	
Z1	-5.000	abs
P	2.000	mm/rev
UXY	0.100	

Die Position der Tasche wird im Zyklus programmiert.

A swivel is made to the first corner to produce the circular pocket.

TC TABLE		
T	ENDMILL_D8	D 1
Retract	Z, XY	
Swivel	Yes	
Swivel plane	New	
X0	100.000	
Y0	0.000	
Z0	-25.000	
Swivel mode	Axis by axis	
Sequence of axes	Z X Y	
Z	45.000	°
X	54.736	°
Y	0.000	°
X1	0.000	
Y1	0.000	
Z1	0.000	
Select Tool		

C-C

Notes:

The circular pocket is programmed in the next step.

Die Position der Tasche wird im Zyklus programmiert.

A swivel is made to the initial setting.

The "Tool Carrier" is deselected.

Das Programm ist fertig erstellt.

Notes:

8th example, complex with programGUIDE**Task:**




The blank for the program example has the dimensions 100x100x52 mm

- ⇒ Programming in programGUIDE
- ⇒ Face milling in the initial setting
- ⇒ Milling oblique surface 15°
- ⇒ Milling centered circular pocket (roughing, finishing)
- ⇒ Milling "1st corner" (roughing, finishing)
- ⇒ Milling "2nd corner" (roughing, finishing)
- ⇒ Circular pockets (-7°) (roughing)
- ⇒ Circular pockets (7°) (roughing)
- ⇒ 1st circular pocket on oblique surface (roughing, finishing)
- ⇒ 2nd circular pocket on oblique surface (roughing, finishing)






Notes:

Drawing, 1st view




Notes:

Drawing, 2nd view




Notes:

Flow diagram:



Function	Block name
Start commands	START
Face milling	FACE_MILLING_INITIAL_SETTING
Swivel by 15°	SWIVEL_PLANE
Mill oblique by 15°	MILLING_OBLIQUE
Swivel by 15°	SWIVEL_PLANE
Milling centered circ. pocket	MILLING_CIRCULAR_POCKET_CENTERED
Swivel plane 1st corner	SWIVEL_PLANE
Mill the 1st corner	MILLING_FIRST_CORNER
Swivel plane 2nd corner	SWIVEL_PLANE
Mill the 2nd corner	MILLING_SECOND_CORNER
Swivel plane -7°	SWIVEL_PLANE
Circular pockets -7°	CIRCULAR_POCKETS_-7
Swivel plane 7°	SWIVEL_PLANE
Circular pocket on 7°	CIRCULAR_POCKETS_7
Swivel plane 1st corner	SWIVEL_PLANE
Circular pocket on 1st corner	MILLING_CIRCULAR_POCKET_FIRST_CORNER
Swivel plane 2nd corner	SWIVEL_PLANE
Circ. pocket on 2nd corner	MILLING_CIRCULAR_POCKET_SECOND_CORNER
End commands	END

After creating a new program, the blocks



are programmed.





Notes:

The program header in the "START" block is programmed.



```
N20 G54 G17 G40 G90
N30 CYCLE800(2,"TABLE",200000,57,0,0,0,0,0,0,0,0,0,0,1,100,1)
N40 WORKPIECE(,"C",,"BOX",112,2,-50,-80,0,0,100,100)
N50 T="FACEMILL 63"
N60 M6
N70 S2000 F1000 M3
```

```
N10 START
N20 G54 G17 G40 G90
N30 CYCLE800(2,"TABLE",200000,57,0,0,0,0,0,0,0,0,0,0,1,100,1)
N40 UORKPIECE(,"C",,"BOX",112,2,-50,-80,0,0,100,100)
N50 T="FACEMILL 63"
N60 M6
N70 S2000 F1000 M3
N80 End of group
```

Face milling in the "FACE_MILLING_INITIAL_SETTING" block is programmed.




Swivel the plane to 15° in the "SWIVEL_PLANE" block.




Notes:

The face cutting in the swivel plane follows. A protrusion >100 mm is programmed in "X1" and "X2" so that no edge remains.



PL	G17 (XY)
RP	30.000
SC	5.000
F	2000.000
Machining	
Direction	
X0	0.000
Y0	0.000
Z0	25.881
X1	102.000 abs
Y1	102.000 abs
Z1	0.000 abs
DXY	50.000 %
DZ	3.000
UZ	0.000




```

N120 SWIVEL
N130 CYCLE800(2, "TABLE", 200000, 27, 0, 0, 0, 0, 0, -15, 0, 0, 0, 1, 100, 1)
N140 End of group
N150 MILLING_OBLIQUE
N160 CYCLE61(30, 25.881, 5, 0, 0, 0, 102, 102, 3, 50, 0, 2000, 31, 0, 1, 11010)
N170 End of group
    
```


Swivel to 15° in the "SWIVEL_PLANE" block. A tool call is performed beforehand.

```

N190 T="ENDMILL_D16"
N200 M6
N210 D1
N220 S4000 F1800 M3
N230 CYCLE800(2, "TABLE", 200000, 27, 0, 0, 0, 0, 0, -15, 0, 0, 0, 1, 100, 1)
    
```



PL	G17 (XY)
TC	TABLE
Retract	Z XY
Swivel	Yes
Swivel plane	New
X0	0.000
Y0	0.000
Z0	0.000
Swivel mode	Axis by axis
Sequence of axes	Z Y X
Z	0.000 °
Y	0.000 °
X	-15.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+



Notes:

The centered circular pocket is programmed in the "MILLING_CIRCULAR_POCKET_CENTERED" block.

Input	Complete
PL	G17 (XY) Down-cut
RP	100.000
SC	2.000
F	2500.000
Machining	Centric
	Single position
X0	50.000
Y0	51.760
Z0	0.000
∅	40.000
Z1	-15.500 abs
DXY	65.000 %
DZ	6.000
UXY	0.200
UZ	0.200
Insertion	Helical
EP	1.500
ER	
Removin	

Input	Complete
PL	G17 (XY) Down-cut
RP	100.000
SC	2.000
F	2500.000
Machining	Centric
	Single position
X0	50.000
Y0	51.760
Z0	0.000
∅	40.000
Z1	-15.500 abs
DXY	65.000 %
DZ	15.500
UXY	0.200
UZ	0.200
Insertion	Helical
EP	1.500
ER	6.000

```

N250 MILLING_CIRCULAR_POCKET
N260 POCKET4(100, 0, 2, -15.5, 40, 50, 51.76, 6, 0.2, 0.2, 2500, 1000, 0, 21, 65, 0, , 6
N270 POCKET4(100, 0, 2, -15.5, 40, 50, 51.76, 15.5, 0.2, 0.2, 2500, 1000, 0, 22, 65, 0
N280 End of group
    
```

The oblique surface is programmed in the next step. To do this, a swivel is made to a new machining plane.

PL	G17 (XY)
TC	TABLE
Retract	Z, XY
Swivel	Yes
Swivel plane	New
X0	0.000
Y0	0.000
Z0	-25.000
Swivel mode	Axis by axis
Sequence of axes:	Z X Y
Z	-45.000 °
X	54.736 °
Y	0.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+

The degree value for "X" must be calculated.
 $(90^\circ - 35.264^\circ = 54.736)$

Notes:

The first corner is programmed with the face milling cycles in the "MILLING_FIRST_CORNER" block. Parameter "Z0" must be calculated.

Note: (Calculation of the "Z0" parameter)

$$\sin \alpha = GK / HP$$

$$GK = \sin 35.264 \cdot 25$$

$$\Rightarrow GK = \underline{14.4336}$$

The values "X0", "X1", "Y0" and "Y1" specify the dimensions of the milling plane.

PL	G17 (XY)
RP	30.000
SC	5.000
F	2000.000
Machining Direction	
X0	-20.000
Y0	0.000
Z0	14.434
X1	40.000 inc
Y1	32.000 inc
Z1	0.000 abs
DXY	65.000 %
DZ	3.000
UZ	0.000

PL	G17 (XY)
RP	30.000
SC	5.000
F	2000.000
Machining Direction	
X0	-20.000
Y0	0.000
Z0	0.200
X1	40.000 inc
Y1	32.000 inc
Z1	0.000 abs
DXY	65.000 %
UZ	0.200

This is programmed in the "MILLING_SECOND_CORNER" block. The coordinate system is programmed accordingly starting at this point. The degree value for "X" must be calculated. ($90^\circ - 35.264^\circ = 54.736^\circ$)

PL	G17 (XY)
TC	TABLE
Retract	Z XY
Swivel	Yes
Swivel plane	New
X0	100.000
Y0	0.000
Z0	-25.000
Swivel mode	Axis by axis
Sequence of axes	Z X Y
Z	45.000 °
X	54.736 °
Y	0.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+

Notes:


The inputs for the face milling are then made.
Parameter "Z0" must be calculated.

Note: (Calculation of the "Z0" parameter)
 $\sin \alpha = GK / HP$
 $GK = \sin 35.264 * 25 \quad GK = \underline{14.4336}$

The circular pockets below (-7°) are programmed in the "SWIVEL_PLANE" block in the next step.


The selection is made in "CYCLE800".

Swivel	No
Swivel plane	No
	Yes



No physical swiveling is performed for "Swivel No".
This swivel serves to swivel to a "theoretical plane".
The next swivel builds on this.

PL	G17 (XY)
TC	TABLE
Retract	Z XY
Swivel	No
Swivel plane	New
X0	0.000
Y0	0.000
Z0	0.000
Swivel mode	Axis by axis
Sequence of axes	Z X Y
Z	0.000 °
X	-15.000 °
Y	0.000 °
X1	50.000
Y1	51.760
Z1	0.000
Select	+



Es wird zuerst auf die Mitte des Werkstücks geschwenkt.



Notes:


"CYCLE800" is called again.

A further one is now programmed additive on the previous theoretical swivel.


The degree (-7) and the position of the first circular pocket are programmed.

Schwenkebene

additiv
neu
additiv



PL	G17 (XY)
TC	TABLE
Retract	Z XY
Swivel	Yes
Swivel plane	Additive
X0	-35.000
Y0	35.000
Z0	0.000
Swivel mode	Axis by axis
Sequence of axes:	Z Y X
Z	0.000 °
Y	-7.000 °
X	0.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+




```

N430 SWIVEL
N440 CYCLE800(2, "TABLE", 220000, 39, 0, 0, 0, -15, 0, 50, 51.76, 0, 0, 100, 1)
N450 CYCLE800(2, "TABLE", 200001, 27, -35, 35, 0, 0, -7, 0, 0, 0, 0, 1, 100, 1)
N460 End of group
    
```


The two circular pockets are programmed with a new tool in the "CIRCULAR_POCKETS_-7°" block.

```



N10 T="ENDMILL_D8"
N20 M6
N30 D1
N220 S4000 F1800 M3
    
```



Input	G17 (XY)	Complete
RP	100.000	Down-cut
SC	2.000	
F	2500.000	
Machining	Helical	
	Single position	
X0	0.000	
Y0	0.000	
Z0	0.000	
∅	10.000	
Z1	-10.000 abs	
DXY	60.000 %	
P	1.000 mm/rev	
UXY	0.000	
UZ	0.000	
Removing	Comp. machining	



Input	G17 (XY)	Complete
RP	100.000	Down-cut
SC	2.000	
F	2500.000	
Machining	Helical	
	Single position	
X0	0.000	
Y0	-59.000	
Z0	0.000	
∅	10.000	
Z1	-10.000 abs	
DXY	60.000 %	
P	1.000 mm/rev	
UXY	0.000	
UZ	0.000	
Removing	Comp. machining	




Die Position der zweiten Kreistasche wird direkt im Zyklus programmiert.

Notes:


The circular pockets below (7°) are programmed.

Swivel	No
Swivel plane	No
	Yes

A swivel is made to the workpiece center.



PL	G17 (XY)
TC	TABLE
Retract	Z XY
Swivel	No
Swivel plane	New
X0	0.000
Y0	0.000
Z0	0.000
Swivel mode	Axis by axis
Sequence of axes	X Y Z
X	-15.000 °
Y	0.000 °
Z	0.000 °
X1	50.000
Y1	51.760
Z1	0.000
Select	+




"CYCLE800" is called again.

A swivel is made "additive" to (7°).

Swivel	Yes
Swivel plane	Additive

PL	G17 (XY)
TC	TABLE
Retract	Z XY
Swivel	Yes
Swivel plane	Additive
X0	35.000
Y0	35.000
Z0	0.000
Swivel mode	Axis by axis
Sequence of axes	Z Y X
Z	0.000 °
Y	7.000 °
X	0.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+
Tool	



```

N520 SWIVEL
CYCLE800(2, "TABLE", 220000, 57, 0, 0, 0, -15, 0, 0, 50, 51.76, 0, 0, 100, 1)
CYCLE800(2, "TABLE", 200001, 27, 35, 35, 0, 0, 7, 0, 0, 0, 0, 1, 100, 1)
N530 Ende Block
    
```



Notes:

The two circular pockets are programmed.

Input	Complete
PL G17 (XY)	Down-cut
RP 100.000	
SC 2.000	
F 2500.000	
Machining	
Helical	
Single position	
X0 0.000	
Y0 0.000	
Z0 0.000	
∅ 10.000	
Z1 -10.000 abs	
DXY 60.000 %	
P 1.000 mm/rev	
UXY 0.000	
UZ 0.000	

Removing Comp. machining

Input	Complete
PL G17 (XY)	Down-cut
RP 100.000	
SC 2.000	
F 2500.000	
Machining	
Helical	
Single position	
X0 0.000	
Y0 -59.000	
Z0 0.000	
∅ 10.000	
Z1 -10.000 abs	
DXY 60.000 %	
P 1.000 mm/rev	
UXY 0.000	
UZ 0.000	

Removing Comp. machining

Die Position der zweiten Kreistasche wird direkt im Zyklus porgrammiert.

A swivel is made to the first corner to produce the circular pocket.

PL	G17 (XY)
TC	TABLE
Retract	↑, Z XY
Swivel	Yes
Swivel plane	New
X0	0.000
Y0	0.000
Z0	-25.000
Swivel mode	Axis by axis
Sequence of axes	Z X Y
Z	-45.000 °
X	54.736 °
Y	0.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+

Notes:


The circular pocket is programmed in the next step.

Die Position der Tasche wird im Zyklus programmiert.

A swivel is made to the first corner to produce the circular pocket.

Notes:

The circular pocket is programmed in the next step.




Input	Complete
PL	G17 (XY) Down-cut
RP	100.000
SC	2.000
F	2500.000
Machining	Helical
	Single position
X0	0.000
Y0	20.400
Z0	0.000
∅	10.000
Z1	-5.000 abs
DXY	60.000 %
P	1.000 mm/rev
UXY	0.100
UZ	0.000

Removing Comp. machining

Input	Complete
PL	G17 (XY) Down-cut
RP	100.000
SC	2.000
F	2500.000
Machining	Helical
	Single position
X0	0.000
Y0	20.400
Z0	0.000
∅	10.000
Z1	-5.000 abs
P	2.000 mm/rev
UXY	0.100

Die Position der Tasche wird im Zyklus programmiert.


A swivel is made to the initial setting in the "END" block.



PL	G17 (XY)
TC	TABLE
Retract	Z, 2 XY
Swivel	Yes
Swivel plane	New
X0	0.000
Y0	0.000
Z0	0.000
Swivel mode	Axis by axis
Sequence of axes	X Y Z
X	0.000 °
Y	0.000 °
Z	0.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+

TC	0
----	---

The "Tool Carrier" is deselected.



Das Programm ist fertig erstellt.

Notes:


9th example, cylinder

-

Task:


The blank for the program example has the dimensions $\text{Ø}40 \times 50$ mm

- ⇒ Programming in programGUIDE
- ⇒ Chamfering with centering drill 90°
- ⇒ 12 centerings on chamfer

Drawing:

Notes:

Flow diagram:



After creating a new G-code program,

New G code program

Type

Name

Describe a block structure for this G-code program.

Function	Block name
Start commands	START
1st chamfering, cylinder	CHAMFER
Centerings on chamfer	LOOP_CENTERING
End	END



Notes:

The program header in the "START" block is programmed in the first step.

```
G54 G90 G17 G40
T="CENTERDRILL 12"
M6
S5000 F1000 M3
CYCLE800
(2, "TABLE", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 1, 100, 1)
WORKPIECE(, "C", , "CYLINDER", 0, 0, -50, -80, 40)
```

```
START
G54 G90 G17 G40
T="CENTERDRILL 12"
M6
S5000 F1000 M3
CYCLE800(2, "TABLE", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 1, 100, 1)
WORKPIECE(, "C", , "CYLINDER", 0, 0, -50, -80, 40)
```

Travel to initial setting.

PL G17 (XY)
TC TABLE
Retract Z XY
Swivel Yes
Swivel plane New
X0 0.000
Y0 0.000
Z0 0.000
Swivel mode Axis by axis
Sequence of axes X Y Z
X 0.000 °
Y 0.000 °
Z 0.000 °
X1 0.000
Y1 0.000
Z1 0.000
Select Tool

Blank description as cylinder.
Blank Cylindr
∅A 40.000
HA 0.000
HI -50.000 inc

The chamfer is programmed with the "Spigot" cycle.

```
G0 X0 Y0
CYCLE77(100, 0, 1, , 5, 40, 0, 0, 0.5, 0.1, 0.1, 1000, 1000, 0, 5, 6, 5, 5.5, 100, 1, 101)
```

Input Complete
PL G17 (XY) Down-cut
RP 100.000
SC 1.000
F 1000.000

Machining Chamfer
Single position
X0 0.000
Y0 0.000
Z0 0.000
∅ 40.000
FS 5.000
ZFS 5.500 inc

```
CHAMFER
G0 X0 Y0
CYCLE77(100, 0, 1, , 5, 40, 0, 0, 0.5, 0.1, 0.1, 1000, 1000, 0, 5, 6, 5, 5.5, 100, 1, 101)
End of group
```

Notes:


A mark is programmed first in the "LOOP_CENTERING" block.

MARK1 :


In the loop, "CYCLE800" is called with

Swivel plane Additive

The position should switch by 30° after each loop pass.




PL	G17 (XY)
TC	TABLE
Retract	↳, Z XY
Swivel	Yes
Swivel plane	Additive
X0	0.000
Y0	-17.500
Z0	-2.500
Swivel mode	Axis by axis
Sequence of axes:	X Y Z
X	45.000 °
Y	0.000 °
Z	0.000 °
X1	0.000
Y1	0.000
Z1	0.000
Select	+



Geschwenkt wird auf Mitte der Fase um 45°Grad.


The hole centering

```
GO X0 Y0 Z50
CYCLE81(50,0,1,4,,0,10,1,11)
```

PL	G17 (XY)
RP	50.000
SC	1.000
	Single position
Z0	0.000
	Diameter
ø	4.000
DT	0.000 s

and the new call of "CYCLE800" with positioning of the axes follow.



PL	G17 (XY)
TC	TABLE
Retract	↳, Z XY
Swivel	No
Swivel plane	Additive
X0	0.000
Y0	0.000
Z0	0.000
Swivel mode	Axis by axis
Sequence of axes:	X Y Z
X	-45.000 °
Y	0.000 °
Z	0.000 °
X1	0.000
Y1	17.500
Z1	2.500
Select	+




Notes:

The additive offset by 30° and the call how often this rotation within the marks should occur follow.

```
AROT Z30
MARK2 :
REPEAT MARK1 MARK2 P11.
```

```
CYCLE800(2, "TABLE", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, 100, 1)
CYCLE800(2, "0", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, , 1)
M30
```



In the "END" block, "CYCLE800" is programmed again in the initial setting and the "Tool Carrier" is deselected.

```
END
CYCLE800(2, "TABLE", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, 100, 1)
CYCLE800(2, "0", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, , 1)
M30
```

Das Programm ist fertig erstellt.

[10th example, turning on the tool](#)


Task:

The blank for the program example has the dimensions 100x100x20 mm



- ⇒ A groove is to be produced with ball mill diameter 8
- ⇒ The program is to be programmed in G-code
- ⇒ Set the tool in X and Y each by 20°, and retain this position during the subsequent milling
- ⇒ Subsequent initial setting

Notes:

Drawing:




The tool orientation is always perpendicular to the machining plane after swiveling with "CYCLE800".





Notes:

When machining with a ball mill, it is important that the tool is not perpendicular to the machining plane, because the ball mill does not then cut theoretically, because the speed is zero at the contact point.

The measured point for a ball mill, the so-called "TOOL-CENTER-POINT" (TCP), should always be measured at the ball center point.



Once the ball mill has been measured in this way, it can be swiveled arbitrary at the point or "set". In the simulation, only the external diameter of the tool is represented as cutter.




the tool can be set at the "X" and "Y" axes.

Important:
 "CYCLE800" must be called before calling the "Turn-On Tool" cycle.
 The coordinate system is **not swiveled** during "Turn-On Tool".

Es verändert sich nur die Orientierung des Werkzeugs bezogen zur Werkstückoberfläche.


Notes:

After creating a new program,



the blocks are programmed.

Function	Block name
Start commands	START
Turn-on tool	TURN_ON_TOOL
Way commands	WAY
End commands	END





The program header is programmed in the "START" block.

```
N10 G17 G64 G94 G90
N20 T="BALL_END_CYL_D8"
N30 M6
N40 G90 S8000 F1000 M3 M8
N50 CYCLE800(4,"TABLE",200000,57,0,0,0,0,0,0,0,0,0,0,1,,1)
G54
N70 WORKPIECE(,"",,"BOX",112,0,-20,-80,100,100,0,0)
```

The tool is then turned on in the "TURN_ON" block


```
N80 CYCLE800(0,"TABLE",101,57,,,,20,20,,,,-1,100,1)
```



Notes:

and the positions programmed in the "WAY" block.


```
N90 G0 X 20 Y100
N100 G0 Z-2
N110 G1 y80
N120 G1 X90 Y0
N130 G0 z100
```



```
WAY
N90 G0 X 20 Y100
N100 G0 Z-2
N110 G1 y80
N120 G1 X90 Y0
N130 G0 z100
End of group
```


The program end is programmed in the "END" block.

```
N140 CYCLE800(4, "TABLE", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, , 1)
N150 CYCLE800(4, "0", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, , 1)
M30
```



```
END
N140 CYCLE800(4, "TABLE", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, , 1)
N150 CYCLE800(4, "0", 200000, 57, 0, 0, 0, 0, 0, 0, 0, 0, 0, 0, 1, , 1)
M30
```

The program is now fully created.



Notes:

M102: END

Notes: