

## TECHNICAL DATA SHEET

## BRUSH SPARKING

## 01 – ORIGIN

Brush sparking, which is most frequently seen at the leaving (trailing) edge, occurs for several reasons. Here is the list of the most common causes:

**ELECTRICAL**

- In DC machines: incorrect neutral setting (see TDS-06), uneven spacing between the brush arms or a connection defect in the armature winding
- Overloading
- Insulation fault in the windings
- Quality of the power supply...

**MECHANICAL:** shock and vibrations, due to:

- Excessive friction (unsuitable grade, low roughness – see TDS-02, low humidity – see TDS-17, pre-seating not done – see TDS-19...),
- Major out of round or eccentricity of the commutator / slip ring,
- Insufficient spring pressure on the brushes (see TDS-11),
- Incorrect position of brush-holders,
- Excessive clearance between the brush and the brush-holder, linked to incorrect tolerances or an error of brush dimensions – see TDS-04...

## 02 – EFFECTS

Whatever the reason may be, the **sparking is always harmful:**

- For the brush, whose rate of wear increases
- To the commutator (or the rings) which is damaged by burning of the metal.

Their degree of aggressiveness depends upon:

- **Their volume:** which can go from being barely perceptible at the edge, intermittent or continuous, to sustained arcing, static or mobile, with or without the generation of incandescent particles (streamers)
- **Their color:**
  - small **violet** sparks are fairly inoffensive, they only affect the brush
  - **red or orange** sparks, with or without generation of incandescent carbon appearing during overloads; cause a higher rate of brush wear
  - **blue** sparks, brilliant and noisy, with burning, generally indicate a serious commutation fault ; it accelerates the rate of brush wear and damages the commutator
  - **green** sparks which are voluminous, always with burning, indicate a serious fault in machine operation and precedes a flash over. It brings about rapid and profound damage to the commutator and to the brushes.

## 03 – NOTATION





It is often useful to be able to define concisely and precisely the degrees of brush sparking of a machine for a determined operating duty.

MERSEN PROPERTY

Different systems of classification exist. Two of them are used by Mersen teams, they are based on the same schematic representation:

- The **Westinghouse index**, one which is most frequently used, is acceptable in the majority of cases
- The **IEC classification**, based on the International Electrotechnical Commission IEC 60276:2018

Table 1 specifies these definitions with the corresponding schematic representation:

| Representation<br>(axial view – carbon brush<br>on commutator)                      | IEC 60276<br>classification | Westinghouse index | Designation                    |
|-------------------------------------------------------------------------------------|-----------------------------|--------------------|--------------------------------|
|    | 1                           | 1                  | Black                          |
|    | 2                           | 1 ¼                | Intermittent beads             |
|    | 3                           | 1 ½                | A few beads                    |
|    | 4                           | 1 ¾                | Numerous beads                 |
|    | 5                           | 2                  | Intermittent shooting sparks   |
|    | 6                           | 2 ¼                | A few shooting sparks          |
|   | 7                           | 2 ½                | Numerous streamers             |
|  | 8                           | 3                  | Heavy and continuous streamers |

 Bead  
  Shooting Spark  
  Streamer

Table 1 - Classification of sparking in accordance with IEC 60276:2018 and "Westinghouse" classification systems

Usually the admissible limits are:

- **Normal operating conditions:** 1 to 3 within the IEC standard, 1 to 1 ½ within the Westinghouse system
- **Rush operating conditions / Overload:** Up to 4 within the IEC standard, up to 1 ¾ within the Westinghouse system

#### Very important:

Sparking **above degree 5** within the IEC 60276:2018, **2** within the Westinghouse system, is **considered as injurious** for the commutator or slip ring.

We are at your disposal for any technical assistance.

#### List of references:

IEC 60276 - Carbon brushes, brush holders, commutators and slip-rings – Definitions and nomenclature – Edition 2 – May 2018

TDS-02: Condition of the surface of commutators and slip rings - Roughness

TDS-04: Dimensions of carbon brushes and brush-holders

TDS-06: Setting the neutral

TDS-11: Pressure on carbon brushes

TDS-17: Air humidity

TDS-19 : Brush seating

The specifications or data contained in present catalogue are only given for information and do not create any undertakings whatsoever. Any copy, reproduction or translation, either partially or fully, of these information is subject to the Mersen's prior written consent. In addition, due to the continuing improvement of techniques and change of applicable standards, Mersen is entitled to modify at any time the characteristics and specifications of its products as described in present catalogue.

Contact: [info.ptt@mersen.com](mailto:info.ptt@mersen.com)

MERSEN PROPERTY