

SPINDLE DRIVE CONTROLLER

TYPE FR-SX

MAINTENANCE MANUAL

— CONTENTS —

CHAPTER 1 GENERAL

1.1 Purpose of the Service Manual	1
1.2 Safety precautions and servicing personnel	1
1.3 Storing	1

CHAPTER 2 SPECIFICATIONS

2.1 AC spindle motor	2
2.2 AC spindle controller	4
2.3 Controller unit composition	7
2.4 External wiring	9
2.5 Pins arrangement	11

CHAPTER 3 OPERATION AND SETTING UP

3.1 Preparation for operation	14
3.2 Turning on the power	14
3.3 Adjustment	15
3.4 Startup operation	15
3.5 Spindle orientation adjustment procedure	16

CHAPTER 4 PERIODIC MAINTENANCE

4.1 Checking the controller unit	18
4.2 Checking the motor	78

CHAPTER 5 CHECKING THE CARDS

(Lists of LEDs, DIP switches, check pins, variable resistors)

5.1 SX-CPU0, CPU1 cards	20
5.2 SX-CPU2 card	29
5.3 SX-I01 card	39
5.4 SX-PW card	47
5.5 SX-AJ card	50

CHAPTER 6 SPINDLE ORIENT POSITION DETECTOR INSTALLATION PROCEDURE

6.1 Magnetic sensor single-point orientation	
6.1.1 Principle	a
6.1.2 Time chart	53
6.1.3 Direction of installation of magnet and sensor	54
6.1.4 Cautions on installation of magnet	56
6.1.5 Cautions on installation of sensor	56
6.1.6 Overall view of magnetic sensor	58

6.2 Encoder type multi-point orientation

6.2.1 Principle	59
6.2.2 Encoder type multi-point orientation system composition	60
6.2.3 Overall view of encoder	61

CHAPTER 7 TROUBLESHOOTING

7.1 Preliminary checking	62
7.2 1st step troubleshooting	62
7.3 2nd step troubleshooting	64
7.4 Detailed checking for each trouble	66

CHAPTER 8 REPLACEMENT OF PARTS

8.1 Replacement of each card	79
8.2 Thyristor module and transistor module	80
8.3 Speed detector and shaft coupling	81
8.4 Cooling fan	81
8.6 Bearings	82

CHAPTER 9 PARTS LIST

CHAPTER 1 GENERAL

1.1 Purpose of the Service Manual

FR-SX Series is a line of AC spindle motor speed control units (inverter) of regenerative braking type.

This Service Manual mainly describes periodic maintenance and troubleshooting practices that are very important for trouble-free, long use of your FR-SX.

Please read this Service Manual carefully until you make yourself familiar with the servicing practices of the unit.

1.2 Safety precautions and servicing personnel

The following cautions are very important to assure safety in maintenance work.

- The unit should be started, maintained and checked by qualified person. It is very hazardous that a person having no electrical knowledge handles the unit.
- Before the unit under live condition is handled, remove finger ring, wrist watch, tie pin and other metallic objects from the body.
- It should be born in mind that electric shock might result in death.

Care should be taken to the fact that some parts of the unit are at high voltage no matter whether the power source itself is ground or not.

When any testing apparatus is applied to the unit, the testing person should not touch any grounded metallic part. Since test apparatus or equipment is usually not grounded and test apparatus is at high voltage against the ground, care should be taken not to touch a grounded part when the unit are operated at adjustment or remedy.

- Do not wear loose cloths that might be involved in rotating or movable parts when gaining access to rotating or moving parts of unit
- Do not remove or install a card while the unit is fed with power supply or operated. Otherwise the unit may be seriously damaged.
- Do not touch the unit immediately after the power is turned off, but wait for at least one minute (time necessary for complete discharging of capacitors) before starting maintenance.

1.3 Storing

When the unit is not immediately installed and used, store it in a clean, dry place at moderate temperature using care not to allow entering of moisture and dust in the unit

Moisture or dust involved in the unit may cause deterioration of insulation.

When the unit is left out of use for any length of time, keep the unit in the same conditions as it is in operation. It is recommended, depending on the condition in the storing place, to use a space heater.

CHAPTER 2 SPECIFICATIONS

2.1 AC spindle motor

(1) Standard specification (I)

Output capacity	Continuous rating (kW)	3.7	5.5	7.5	11	15	18.5
	30 min. rating (kW)	5.5	7.5	11	15	18.5	22
	50% ED rating (kW)	5.5	7.5	11	15	18.5	22
Speed	Base speed (RPM)	1500			1500		
	Max. speed (RPM)	6000 ^{Note 1}			4500		
Frame No.		A112	B112	8132	C132	A160	
Rated torque (cont.) (kg-m)		2.4	3.57	4.87	7.15	9.74	12.0
GD ² (kg.m ²)		0.07	0.093	0.2	0.25	0.35	0.5
Weight (kg)		65	75	100	115	130	190
Permissible radial load (kg)		150	200	300			
Cooling fan (W)		35					
Vibration		V10					
Noise (dB) (A)		72				77	
Installation		Output shaft: Horizontal or downward					
Overload capacity		120% of 30 min. rating, for one minute					
Ambient temperature (°C)		0 ~ 40					
Insulation class		F					
Paint color		Munsell N5.5					
Accessories		Pulse generator, overheat detector					
Standard applied		JIS-C4004					
Controller model FR-SX-2-		5.5K	7.5K	11K	15K	18.5K	22K
Power source requirement (kVA)		9	12	17	23	29	
Power source voltage and frequency		200/200~230V±10%, 50/60Hz±3%					

Note 1: For speed larger than 4,500 rpm, the output (capacity) is reduced to the value calculated with the following formula:

$$\text{Rated output} \times \frac{4500}{\text{Speed RPM}}$$

Note 2: When power source other than specified above is used, a suitable transformer should be used.

(2) Standard specification (II)

When the Standard Specification (I) is not applicable because speed reduction ratio that meets 1,500 rpm base speed is not available, this Standard Specification (II) may be adapted.

Output capacity	Continuous rating (kW)	3.7	5.5	7.5	11	15	18.5
	30 min. rating (kW)	5.5	7.5	11	15	18.5	22
	50% ED rating (kW)	5.5	7.5	11	15	18.5	22
Speed	Base speed (RPM)	1150					
	Max. speed (RPM)	4600					
Frame No.		B112	B132		CI32	AI60	8160
Rated torque (cont.) (kg-m)		3.13	4.66	6.35	9.32	12.7	15.7
GD ² (kg.m ²)		0.093	03	0.25	0.35	0.5	0.83
Weight (kg)		75	100	115	130	190	245
Permissible radial load (kg)		200	300				
Cooling fan (W)		35					
Vibration		V10					
Noise (dB) (A)		72			77		
Installation		Output shaft: horizontal or downward					
Overload capacity		120% of 30 min. rating, for one minute					
Ambient temperature (°C)		0 ~ 40					
Insulation class		F					
Paint color		Munsell N5.5					
Accessories		Pulse generator, overheat detector					
Controller model FR-SX-2-		5.5K	7.5K	11K	15K	18.5K	22K
Power source requirement (kVA)		9	12	17	23	28	
Power source voltage and frequency		200/200~230V±10%, 50/60Hz±3%					

2.2 AC spindle controller

(1) Specification

Model F R-SX-2-		5.5K	7.5K	11K	15K	18.5K	22K
Output capacity (kW)		5.5	7.5	11	15	18.5	22
50% ED output	Output current (A)	43	55	74	100	125	148
	Power requirement (kVA)	9	12	17	23	28	33
Cont. rating output	Heat value (W)	340	400	490	590	700	810
Weight (kg)		42		55		73	
Main circuit		Transistor sine-wave PWM inverter					
Control circuit		Speed feedback control with pulse generator, digital closed-loop control, optimized F-V pattern control					
Braking method		Power regenerative braking					
Speed control range		35 ~ 6000 RPM					
Speed regulation		Less than 0.2% of maximum speed (with load changing within a range from 10% to 100%)					
Speed command		Digital command, binary 12 bits or BCD 2 digits <small>Note</small> Analog command, +10V Max. (Input impedance: approx. 10 Kohms)					
Acceleration/ deceleration method		Slip control acceleration/deceleration (Time limit accel./decel.: 0.5 ~ 10 sec.)					
Ambient temperature/ humidity		-5 ~ 50°C/Less than 85%					
Environmental condition		To be free from detrimental gas and dust (To conform with JEM1103, Grade "C")					
Vibration		Less than 0.5G					
Standard applied		IEC					
Cooling		Fan					

Now: Incorporated DIP switch is used to select digital speed command between "binary 12 bits" and "BCD 2 digits" and external signal is used to select analog speed command.

(2) Protective functions

Name	Function	Description
OVER HEAT (MOTOR)	Overload/overheat protection	When motor is overloaded, or overheats due to standstill of fan motor, the base and gate are shut off.
EXCESSIVE SPEED ERROR	Prevention of too large speed control error	If commanded speed differs From actually running speed to a degree larger than specified tolerance, the base and gate are shut off.
BREAKER TRIP	Short-circuiting protection Grounding protection	If large current flows in the main circuit, the base and gate are shut off.
PHASE LOSS	Preventing of single-phase operation	If any phase of power source is disconnected at the time the power is turned on, the base and gate are shut off.
EXTERNAL EMERGENCY	Emergency stop with external signal	With emergency stop signal given by external device, motor is stopped and the base is shutoff.
OVER SPEED	Overspeed protection	If motor speed exceeds 115% of the maximum speed, the base and gate are shut off.
IOC TRIP (CONVERTER)	Instantaneous overcurrent protection	If overcurrent flows in the converter, the base and gate are shut off.
OVER HEAT (CONTROLLER)	Main circuit overload protection	If main circuit semiconductor overheats due to overload or standstill of fan, the base and gate are shut off.
UNDER VOLTAGE	Main circuit source voltage drop protection	If the source voltage drops below the specified level, the base and gate are shut off.
OVER VOLTAGE (REGENERATION)	Main circuit over-voltage protection	If regenerative voltage at main circuit capacitor exceeds the specified level, the base and gate are shut off.
IOC TRIP (INVERTER)	Instantaneous overcurrent protection	If overcurrent flows in the invener, the base and gate are shut off.

Note: If any protective means (except for EXTERNAL EMERGENCY) works, the base (inverter) and gate (converter) are shut off and the motor stops after inertia running.


(3) Auxiliary functions

Name of function	Application	Description	Output
LOAD METER SIGNAL	Connected to load meter	An one-way swing DC1mA meter is connected. Full scale corresponds to 150% load (adjustable within a range from 100% to 150%).	
SPEED METER SIGNAL	Connected to speed meter	An one-way swing DC1mA meter is connected. Full scale corresponds to the maximum speed.	
ZERO SPEED SIGNAL	Machine interlock	Signal for contacts that close when motor speed decreases below 50 or 20 ± 10 rpm.	Contacts open emitter
THRESHOLD SPEED SIGNAL	Response to NC	Output transistor turns on with this signal when speed reaches within a range of $\pm 15\%$ of preset speed	Open emitter
LOAD DETECT SIGNAL (CURRENT)	For prevention of plunging of cutter	The output transistor turns on with this signal when chipload exceeds the specified value (110%) near the limit value (120% output).	Open emitter
OVERRIDE	For override in automatic operation	Override setting range: 50 ~ 120% Override can be reset by opening controller terminal DEF.	
SPINDLE ORIENT (Optional function)	Indexing of spindle	Magnetic sensor type single-point indexing and encoder type multi-point indexing are possible. With orientation start signals (ORCM1, ORCM2), start command signal, completion signal and orientation completion signal are output	Contacts Open
TORQUE LIMIT	For gear shifting, etc.	When gearing is shifted, spindle motor is run with a temporarily reduced torque. This function is used when torque is limited.	Open emitter

2.3 Controller unit composition


The AC spindle motor controller consists of the following 7 sections.

- (1) Front panel (name plate)
- (2) SX-C?U (1,2) cards
- (3) SX-I01 card
- (4) SX-PW card
- (5) SX-AJ1 card
- (6) Converter
- (7) Inverter



(7) Inverter


(6) Converter




(5) SX-AJ1



2.4 External wiring

(1) **AC spindle motor controller equipped with magnetic sensor type signal-point orientation function.**




(2) AC spindle motor controller equipped with encoder type multi-point orientation function.





MODEL FR-SX-2-15K AC SPINDLE CONTROLLER

PARTS ARRANGEMENT DIAGRAM



CAUTION IN CASE OF REPAIRS OR OVERHAULING OF THIS UNIT, THE USER SHOULD BE AWARE OF THE FOLLOWING PRECAUTIONS AND TAKE THEM INTO ACCOUNT.


注意 コンデンサ等の修理には専門知識を要するため、取扱を誤って人身に危害、財産の損失・交換を招くことがあります。

人 MITSUBISHI ELECTRIC CORPORATION, JAPAN

80990C558

MODEL FR-SX-2-11K AC SPINDLE CONTROLLER

PARTS ARRANGEMENT DIAGRAM



CAUTION IN CASE OF REPAIRS OR OVERHAULING OF THIS UNIT, THE USER SHOULD BE AWARE OF THE FOLLOWING PRECAUTIONS AND TAKE THEM INTO ACCOUNT.


注意 コンデンサ等の修理には専門知識を要するため、取扱を誤って人身に危害、財産の損失・交換を招くことがあります。

人 MITSUBISHI ELECTRIC CORPORATION, JAPAN

80990C557

MODEL FR-SX-2-22K AC SPINDLE CONTROLLER

PARTS ARRANGEMENT DIAGRAM



TYPE	FR-SX-2-22K
AC INPUT	170 V 160 A
LINE PWR	170 V 160 A
REFERENCE SIGNAL	1-10 VDC
STYLUS	10840443954, 954


CAUTION IN CASE OF MISUSE OR OVERLOADING OF THIS UNIT, THE UNIT MAY BE DAMAGED. PLEASE BE CAREFUL TO AVOID SUCH A SITUATION.

注意 コンデンサの故障に起因する事故のため、修理を行うときは、必ずコンデンサの交換・交換を行う必要があります。

人 MITSUBISHI ELECTRIC CORPORATION, JAPAN
80990C560

MODEL FR-SX-2-18.5K AC SPINDLE CONTROLLER

PARTS ARRANGEMENT DIAGRAM



TYPE	FR-SX-2-18.5K
AC INPUT	170 V 135 A
LINE PWR	170 V 135 A
REFERENCE SIGNAL	1-10 VDC
STYLUS	10840443953, 953

CAUTION IN CASE OF MISUSE OR OVERLOADING OF THIS UNIT, THE UNIT MAY BE DAMAGED. PLEASE BE CAREFUL TO AVOID SUCH A SITUATION.

注意 コンデンサの故障に起因する事故のため、修理を行うときは、必ずコンデンサの交換・交換を行う必要があります。

人 MITSUBISHI ELECTRIC CORPORATION, JAPAN
80990C559

CHAPTER 3 OPERATION AND SETTING UP

3.1 Preparation for operation

When the AC spindle motor controller is fed with the power source for the first time, the following checking should be made.

- (1) Has external wiring been completed in accordance with the wiring diagram?
- (2) Are the motor and controller unit properly grounded?
- (3) Are shielding wire ends properly connected?
 - They should be connected to shielding terminals.
 - They should be connected without looping.
- (4) Are all components not damaged, and securely installed?
- (5) Is any foreign matter such as wire chip involved in the unit?
- (6) Does each card present good appearance?
- (7) Does ROM No. conform with the order sheet?
 - Do DIP switch settings conform with the order sheet?

3.2 Turning on the power

When the checking has been completed, feed the controller unit with the power source as follows:

- (1) Turn on the power.
- (2) Make sure no alarm indication LED (LED12, 13, 14 and 15) on the controller front panel does not light
- (3) Make sure status indication LEDs (LED2 "READY" and LED10 "ZERO SPEED") light.

Now the controller is ready for operation.

Although the power cable can be connected to the controller without noting the phase connection, phase sequence can be checked through LED1 "PHASE SEQUENCE".

LED1 lights when the power cable is connected in correct phase sequence.

3.3 Adjustment

(1) Speed meter calibration VR1 and load-meter calibration VR2

When speed meter is connected to the spindle inverter, turn and set the VR1 so that the speed meter reads the maximum speed with DIP switches SW1~3 set at OFF.

Also adjust the load meter to 120% by setting the VR2.

When the two variable resistors have been set, set SW1~3 to ON and set the RESET switch (ST1) to ON.

Since other variable resistors have been factory-adjusted, do not disturb these settings.

(2) DIP switches and setting pins

Check that DIP switches and setting pins are set properly as specified in the other sheet.

If not, correct setting.

When setting is changed, be sure to operate the RESET switch (ST1) to ON.

When spindle indexing (stop) position must be changed, change the settings of DIP switches and setting pins for individual machine.

For setting procedure, refer to para. 3.5.

3.4 Startup operation (accommodation)


Connect the motor shaft with the machine shaft and start operation to check the controller unit for condition.

Then exert load on the motor and check the following items:

- Unusual sound
- Unusual odor
- Bearing temperature

3.5 Spindle orientation adjustment procedure

(1) Magnetic sensor type spindle orientation



The speed change pattern at spindle orientation (indexing) is as illustrated above.

When the spindle stops running over the previously determined stop position (indexing position)

- Shorten setting of timer (SW2-5, 6, 7).
- Increase positioning loop gain (SW-2, 3, 4).
- Decrease orientation speed.

When shorter orientation time is desired

- Prolong setting of timer (SW2-5, 6, 7).
- Increase positioning loop gain (SW2-2, 3, 4).
- Increase orientation speed.

When hunting occurs at spindle stop


- Decrease positioning loop gain (SW2-2, 3, 4).
- Decrease sensitivity of magnetic sensor (VR4).

Stop position can be adjusted by VR5.

Notes: (1) The data of gearing ratio stored in the ROM should meet the gearing ratio in use.

(2) Adjustment may vary depending on gearing ratio.

(2) Encoder type spindle orientation



The speed change pattern a spindle stop is as illustrated above.

When the spindle stops running over the predetermined stop position (indexing position).....

- Decrease 1st positioning loop gain.
- Decrease orientation speed.
- Decrease 2nd positioning loop gain.

When shorter orientation time is desired.. . .

- Increase 1st positioning loop gain.
- Increase orientation speed.
- Increase 2nd positioning loop gain.

When hunting occurs at spindle stop

- Decrease 2nd positioning loop gain.

Stop position can be adjusted by operating SW8, 9 and 10.

Notes: (1) The data of gearing ratio stored in the ROM should meet the gearing ratio in use.

(2) Adjustment may vary depending on gearing ratio.

In order to assure the full performance and trouble-free, long use of the controller unit, trustworthy maintenance is indispensable. Perform the periodic maintenance as instructed below.

Note: Electric shock might result in death.

Before starting the maintenance, do not fail to make sure all power sources are turned off.

4.1 Checking the controller unit

Item	Frequency	Checkup	Remedy
1. Cooling fan	Monthly	(1) Does the fan rotate smoothly when turned by hand? (2) Does the fan rotate powerfully when the power is given? (3) Does unusual sound occur in bearing?	Replace defective fan.
2 Cleanliness, loose screw	At suitable interval	Periodically clean each part and retighten input/output terminal screws and other screws.	
3. Miniature relay	Every 3 months	(1) Is contact not worn out? (2) Can miniature relay let work contactor in the main circuit?	Replace defective relay.
4. Wiring	At suitable interval	Is any conductor in contact with the casing (this may occur when wire is pinched by hinges)?	

4.2 Checking the motor

Item	Frequency	Checkup	Remedy
1. Noise, vibration	Monthly	<ul style="list-style-type: none"> o Does unusual sound or vibration occur? If u-l sound or vibration occurs, perform the following checking: (1) Check the foundation and installation. (2) Check alignment of shafts. (3) Check if vibration is transmitted from the machine connected with the motor. (4) Check bearings for condition (if noise is caused by bearing). (5) Check if large noise or intense vibration is caused by speed reduction gears or drive belt (6) Check the controller unit for condition. (7) Check the cooling fan for condition. (8) Check belt tension. 	


Item	Frequency	Checkup	Remedy
2. Temperature rise	Monthly	<ul style="list-style-type: none"> ○ Is bearing temperature not too high? (Usual bearing temperature: +10 ~ 40°C) ○ Is motor frame temperature not too high? (1) Check that the cooling fan runs in good condition. (2) Check if cooling air passage (space between the motor frame and the cover) is clogged with foreign matter. (3) Check if load is excessively large. (4) Check the controller unit for condition. 	<p>Clean.</p> <p>Refer to 'Trouble shooting'.</p>
3. Insulation resistance	Every 6 months	<p>0 Is insulation resistance not too small?</p> <p>— To check insulation resistance, disconnect the motor from the controller unit and measure resistance between the entire circuit and the ground using a megger. (The insulation resistance should be larger than 1 Megohms when measured with 500V megger) If the insulation resistance is smaller than 1 Megohms, clean the motor interior and dry. To dry, breakdown the motor and place it in an oven at a temperature not exceeding 90°C.</p>	
4. Cooling fan	Weekly, monthly	<p>0 Does the cooling fan rotate satisfactorily without generating unusual sound and vibration?</p>	

CHAPTER 5 CHECKING THE CARDS


Note: Since all control cards have been factory-adjusted, do not disturb the settings.

5.1 SX-CPU0 and CPU1 cards

SX-CPU0 ... no orientation card
 SX-CPU1 ... Magnetic orientation card



PROGRAM B.O.M.



(1) List of LEDs

LED No.	Name	Application	Description
LED1	PHASE SEQUENCE	Power source phase discrimination	Lights when power source connection is in positive-phase sequence. Does not light when power source connection is in negative-phase sequence. ^{Note}
LED2	READY	Ready for operation	Lights when the controller is ready for operation. Does not light when SET1 – SET2 input of OFF and emergency stop command is given (base and gate shut off).
LED3	CW DRIVE	Motor CW rotation command	Lights when motor CW rotation command is input, or when the spindle is indexed.
LED4	CCW DRIVE	Motor CCW rotation command	Lights when motor CCW rotation command is input
LED5	SPEED DETECTION	Speed detection	Lights when motor speed decreases below the speed preset by DIP.
LED8	CURRENT DETECTION	Current detection	Lights when current larger than 110% of rated current flows in the motor.
LED7	UP TO SPEED	Threshold speed	Lights when motor speed reaches $\pm 15\%$ of commanded speed.
LED8	APPROACH	Access to orientation position	Lights when spindle enters orientation (indexing) area.
LED9	INPOSITION	Inposition	Lights when spindle stops within the range preset by rotary switch.
LED10	Z E R O S P E E D	Zero speed	Lights when spindle speed goes down below the "zero" speed set by DIP switches.
LED11			Not used.

Note: The inverter works satisfactorily no matter whether its phase sequence is positive or negative.

List of DIP switches

Switch No.	Name	Description
SW1-1	NORMAL/TEST	<p>ON "NORMAL" (Usual operation) OFF "TEST" (Test operation)</p> <p>In usual operation, the switch is set as "NORMAL" position. When the circuit is checked or spindle orientation is checked, the switch is set at "TEST" position.</p>
SW1-2	CLOSE/OPEN	<p>ON "CLOSE" OFF "OPEN"</p> <p>Speed control loop OPEN/CLOSE changeover. Speed detector function can be checked by comparing operating conditions when the switch is sat at "CLOSE" and "OPEN".</p>
SW1-3	BINARY/BCD	<p>ON "BINARY" OFF "BCD"</p> <p>Digital speed command mode can be selected by this switch. Speed command is read in binary 12-bit data with the switch sat at ON, and in BCD 2-digit data with the switch set at OFF.</p>
SW1-4	ATTENUATED EXCITATION	<p>ON "ATTENUATED EXCITATION" OFF "NOT ATTENUATED EXCITATION"</p> <p>In usual operation, the switch is set at ON. With the switch set at ON, excitation voltage is decreased for reduction of noise (when slippage decreases).</p>
SW1-5		
SW1-6	METER CALIBRATION	<p>ON "METER CALIBRATION" OFF "USUAL OPERATION"</p> <p>This switch is operated when speed meter or load meter is calibrated. With the switch set at ON, meter full-scale voltage is output permitting calibration of mater.</p>

Switch No.	Name	Description																												
SW1-7	MAX. SPEED SETTING	ON "LOW SPEED" (PIN1 of SX-101 is set at "B") OFF ... "HIGH SPEED" (PIN1 of SX-101 is set at ● "A") When base speed is 1500 rpm, HIGH SPEED=6000 rpm LOW SPEED = 4500 rpm When base speed is 1150 rpm, HIGH SPEED = 4600 rpm LOW SPEED = 3450 rpm																												
SW1-8	ZERO SPEED SETTING	ON Zero speed signal is output when spindle speed goes down below 25 rpm. OFF ... Zero speed signal is output when spindle speed goes down below 50 rpm.																												
SW2-1		Not used																												
SW2-2 ~ SW2-4	MAGNET C SENSOR ORIENT POSITION- ING LOOP GAIN 1	<table><tr><td></td><td>(2)</td><td>(3)</td><td>(4)</td></tr><tr><td>Mode 0</td><td>○</td><td>○</td><td>○</td></tr><tr><td>Mode 1</td><td>○</td><td>○</td><td>×</td></tr><tr><td>Mode 2</td><td>○</td><td>×</td><td>○</td></tr><tr><td>Mode 3</td><td>○</td><td>×</td><td>×</td></tr><tr><td>⋮</td><td></td><td>⋮</td><td></td></tr><tr><td>Mode 7</td><td>×</td><td>×</td><td>×</td></tr></table> <p>○ ON x OFF</p> <p>This switch function is effective only for magnetic sensor type orientation.</p> <p>Positioning loop gain can be set for speed ranging from "orientation speed" to "servo control speed".</p> <p>The standard switch setting is "mode 0" and mode of larger number is selected to shorten orientation time.</p>		(2)	(3)	(4)	Mode 0	○	○	○	Mode 1	○	○	×	Mode 2	○	×	○	Mode 3	○	×	×	⋮		⋮		Mode 7	×	×	×
	(2)	(3)	(4)																											
Mode 0	○	○	○																											
Mode 1	○	○	×																											
Mode 2	○	×	○																											
Mode 3	○	×	×																											
⋮		⋮																												
Mode 7	×	×	×																											
SW2-5 ~ SW2-7	MAGNETIC SENSOR ORIENT SPEED TIMER	<table><tr><td></td><td>(5)</td><td>(6)</td><td>(7)</td></tr><tr><td>180 ms Mode 0</td><td>○</td><td>○</td><td>○</td></tr><tr><td>190 ms Mode 1</td><td>○</td><td>○</td><td>×</td></tr><tr><td>Mode 2</td><td>○</td><td>×</td><td>○</td></tr><tr><td>⋮</td><td></td><td>⋮</td><td></td></tr><tr><td>250 ms Mode 7</td><td>×</td><td>×</td><td>×</td></tr></table> <p>○ ON x OFF</p> <p>10 ms increment</p> <p>This switch function is effective only for magnetic sensor type orientation.</p> <p>Time taken for speed change from "orientation speed" to "servo control speed" is set.</p> <p>If spindle stops running over the predetermined position, mode of larger number is selected.</p>		(5)	(6)	(7)	180 ms Mode 0	○	○	○	190 ms Mode 1	○	○	×	Mode 2	○	×	○	⋮		⋮		250 ms Mode 7	×	×	×				
	(5)	(6)	(7)																											
180 ms Mode 0	○	○	○																											
190 ms Mode 1	○	○	×																											
Mode 2	○	×	○																											
⋮		⋮																												
250 ms Mode 7	×	×	×																											

Switch No.	Name	Description																																																		
SW2-8																																																				
SW3-1 ~ SW3-2	TORQUE LIMIT	<table><tr><th colspan="2">External signal input</th><th colspan="2">1 2</th><th></th></tr><tr><th>TL1</th><th>TL2</th><th></th><th></th><th></th></tr><tr><td>0</td><td>x</td><td>0</td><td>0</td><td>Torque limited to 10%</td></tr><tr><td></td><td></td><td>0</td><td>0</td><td>Torque limited to 15%</td></tr><tr><td></td><td></td><td>x</td><td>0</td><td>Torque limited to 20%</td></tr><tr><td></td><td></td><td>x</td><td>x</td><td>Torque limited to 25%</td></tr><tr><td>x</td><td>0</td><td>0</td><td>0</td><td>Torque limited to 20%</td></tr><tr><td></td><td></td><td>0</td><td>x</td><td>Torque limited to 30%</td></tr><tr><td></td><td></td><td>x</td><td>0</td><td>Toque limited to 40%</td></tr><tr><td></td><td></td><td>x</td><td>x</td><td>Torque limited to 50%</td></tr></table> <p>The switch setting is not changed unless particular torque limit is required.</p>	External signal input		1 2			TL1	TL2				0	x	0	0	Torque limited to 10%			0	0	Torque limited to 15%			x	0	Torque limited to 20%			x	x	Torque limited to 25%	x	0	0	0	Torque limited to 20%			0	x	Torque limited to 30%			x	0	Toque limited to 40%			x	x	Torque limited to 50%
External signal input		1 2																																																		
TL1	TL2																																																			
0	x	0	0	Torque limited to 10%																																																
		0	0	Torque limited to 15%																																																
		x	0	Torque limited to 20%																																																
		x	x	Torque limited to 25%																																																
x	0	0	0	Torque limited to 20%																																																
		0	x	Torque limited to 30%																																																
		x	0	Toque limited to 40%																																																
		x	x	Torque limited to 50%																																																
SW3-3 ~ SW3-5	Acceleration/Deceleration TIME CONSTANT	<p>Speed command time constant for speed ranging from zero speed to maximum speed is set.</p> <p>Standard setting: t .5 s</p> <p>0 ON x OFF</p> <table><tr><th>3</th><th>4</th><th>5</th><th></th></tr><tr><td>0</td><td>0</td><td>0</td><td>0.3 s</td></tr><tr><td>0</td><td>0</td><td>x</td><td>1.5,</td></tr><tr><td>0</td><td>x</td><td>0</td><td>3</td></tr><tr><td>0</td><td>x</td><td>x</td><td>4</td></tr><tr><td>x</td><td>0</td><td>0</td><td>5</td></tr><tr><td>x</td><td>0</td><td>x</td><td>6</td></tr><tr><td>x</td><td>x</td><td>0</td><td>8</td></tr><tr><td>x</td><td>x</td><td>x</td><td>10</td></tr></table>	3	4	5		0	0	0	0.3 s	0	0	x	1.5,	0	x	0	3	0	x	x	4	x	0	0	5	x	0	x	6	x	x	0	8	x	x	x	10														
3	4	5																																																		
0	0	0	0.3 s																																																	
0	0	x	1.5,																																																	
0	x	0	3																																																	
0	x	x	4																																																	
x	0	0	5																																																	
x	0	x	6																																																	
x	x	0	8																																																	
x	x	x	10																																																	
SW3-6 ~ SW3-8	SPEED DETECTION RANGE	<p>Speed detection range can be selected from 8 ranges (2%, 10%, 18%, 26%, 34%, 50% and 58%).</p> <p>When speed enters the speed range set by these switches, the transistor for speed detection turns on.</p>																																																		

Switch No.	Name	Description																																				
SW3-6 ~ sw3-8		<table><tr><td>6</td><td>7</td><td>8</td><td></td></tr><tr><td>○</td><td>○</td><td>○</td><td>2%</td></tr><tr><td>○</td><td>○</td><td>x</td><td>10</td></tr><tr><td>○</td><td>x</td><td>○</td><td>18</td></tr><tr><td>○</td><td>x</td><td>x</td><td>26</td></tr><tr><td>x</td><td>○</td><td>○</td><td>34</td></tr><tr><td>x</td><td>○</td><td>x</td><td>42</td></tr><tr><td>x</td><td>x</td><td>○</td><td>50</td></tr><tr><td>x</td><td>x</td><td>x</td><td>58</td></tr></table>	6	7	8		○	○	○	2%	○	○	x	10	○	x	○	18	○	x	x	26	x	○	○	34	x	○	x	42	x	x	○	50	x	x	x	58
6	7	8																																				
○	○	○	2%																																			
○	○	x	10																																			
○	x	○	18																																			
○	x	x	26																																			
x	○	○	34																																			
x	○	x	42																																			
x	x	○	50																																			
x	x	x	58																																			
SW4-1		Not used																																				
SW4-2 ~ SW4-7	GEAR RATIO SETTING	Spindle orientation speed and servo control speed are set by these switches (gearing ratio is changed for individual application)																																				
SW4-8		Not used.																																				
SW5-1 ~ SW5-2	DIRECTION OF ORIENTATION	<table><tr><td></td><td colspan="2">SW</td><td>0 ON x OFF</td></tr><tr><td></td><td>1</td><td>2</td><td></td></tr><tr><td>PRE</td><td>○</td><td>○</td><td>Orientation in forward direction of motor rotation</td></tr><tr><td>CCW</td><td>○</td><td>x</td><td>Orientation in counter-clockwise direction of motor rotation</td></tr><tr><td>CW</td><td>x</td><td>○</td><td>Orientation in clockwise direction of motor rotation</td></tr><tr><td>c w</td><td>x</td><td>x</td><td>Orientation in clockwise direction of motor rotation</td></tr></table>		SW		0 ON x OFF		1	2		PRE	○	○	Orientation in forward direction of motor rotation	CCW	○	x	Orientation in counter-clockwise direction of motor rotation	CW	x	○	Orientation in clockwise direction of motor rotation	c w	x	x	Orientation in clockwise direction of motor rotation												
	SW		0 ON x OFF																																			
	1	2																																				
PRE	○	○	Orientation in forward direction of motor rotation																																			
CCW	○	x	Orientation in counter-clockwise direction of motor rotation																																			
CW	x	○	Orientation in clockwise direction of motor rotation																																			
c w	x	x	Orientation in clockwise direction of motor rotation																																			

List of rotary switches

Switch No.	Name	Description																																		
SW6	ORIENTATION SPEED SETTING	<table><tr><th>Setting</th><th></th></tr><tr><td>0</td><td>80 rpm</td></tr><tr><td>1</td><td>85</td></tr><tr><td>2</td><td>90</td></tr><tr><td>3</td><td>95</td></tr><tr><td>4</td><td>100</td></tr><tr><td>5</td><td>105</td></tr><tr><td>6</td><td>110</td></tr><tr><td>7</td><td>115</td></tr><tr><td>8</td><td>120</td></tr><tr><td>9</td><td>125</td></tr><tr><td>A</td><td>130</td></tr><tr><td>B</td><td>135</td></tr><tr><td>C</td><td>140</td></tr><tr><td>D</td><td>145</td></tr><tr><td>E</td><td>150</td></tr><tr><td>F</td><td>155</td></tr></table>	Setting		0	80 rpm	1	85	2	90	3	95	4	100	5	105	6	110	7	115	8	120	9	125	A	130	B	135	C	140	D	145	E	150	F	155
		Setting																																		
		0	80 rpm																																	
		1	85																																	
		2	90																																	
		3	95																																	
		4	100																																	
		5	105																																	
		6	110																																	
		7	115																																	
		8	120																																	
		9	125																																	
		A	130																																	
		B	135																																	
		C	140																																	
		D	145																																	
		E	150																																	
F	155																																			
“Orientation speed” for magnetic sensor type orientation is sat by this rotary switch.																																				
The listed speeds are spindle speed RPM and motor speed depends on gearing ratio.																																				
Orientation speed should be decreased when spindle stops running over the predetermined stop position due to large load GD ² .																																				

• List of toggle switches



Switch No.	Name	Description
ST1	RESET	<p>For initializing the inverter.</p> <p>This switch should not be operated while the motor is running.</p> <p>Whenever DIP switch setting is changed, this switch should be operated.</p> <p>DO NOT RESET WHILE THE MOTOR IS RUNNING</p>
ST2	ORIENTATION TEST	<p>The motor runs at “orientation speed” while this switch is held at ON position.</p> <p>When the switch is set to OFF, the motor stops after completion of one cycle of orientation.</p>


List of variable resistors

Since the variable resistors in this card have been properly set by us, do not disturb the settings.

VR No.	Name	Description
VR16	"B" phase zero adjustment	00 not change the setting.
VR13	"A" phase zero adjustment	Do not change the setting.
VR14	"A" phase gain adjustment	CH56, Speed feedback, Sine wave PLG (Pulse generator). Adjusted to $\pm 10V$
VR15	"B" phase gain adjustment	CH55, Speed feedback. Sine wave "LOW SPEED". Adjusted to $\pm 10V$
VR3	Position shift	Fine adjustment of stop position is possible.
VR4	Magnetic sensor	To be a so that magnetic sensor sensitivity indicator LED11 lights.

List of check terminals

Terminal No.	Description
P5A	+5V
DGA	+0V (Digital ground)
CH52	Speed feedback "A" phase, rectangular waveform  For CW rotation
CH51	Speed feedback "B" phase, rectangular waveform  For C.CW rotation
CH57	Linear zone detection signal
CH58	AC converter input
CH60	-15V
CH54	+0V (Analog ground)
CH59	+15V
CH66	Speed feedback "A" phase
CH55	Speed feedback "B" phase
CH56A	Speed feedback "A" phase
CH55A	Speed feedback "B" phase
CH53	+24V





For CW rotation

+10V For low speed rotation
-10V

5.2 SX-CPU2 card

When the controller unit is equipped with 1024Px4/Rev. encoder type multi-point orientation, this card is used.





(1) List LEDs

LED No.	Name	Application	Description
LED 1	PHASE / SEQUENCE	Power source se- quence discrimina- tion	Lights when power source phase se- quence is positive. Does not light when power source phase sequence is negative. (Note 1)
LED2	R E A D Y	Ready for operation	Lights when the controller is ready for operation. Does not light when SET7 – SET2 in- put is OFF and emergency stop com- mand is input (base and gate shut off).
LED3	CW DRIVE	Motor CW rotation command	Lights when motor CW rotation com- mand is input, or when the spindle is indexed.
LED4	CCW DRIVE	Motor CCW rota- tion command	Lights when motor CW rotation com- mand is input.
LED5	SPEED DETECTION	Speed detection	Lights when motor speed decreases below the speed preset by DIP switches.
LED6	CURRENT DETECTION	Current detection	Lights when current larger than 110% of rated current flows in the motor.
LED7	UP TO SPEED	Threshold speed	Lights when motor speed reaches $\pm 15\%$ of commanded speed.
LED8	APPROACH	Access to orienta- tion position	Lights when spindle enters orientation (indexing) area.
LED9	INPOSITION	Inposition	Lights when spindle stops within a angle preset by rotary switch.
LED10	ZERO SPEED	Zero speed	Lights when spindle speed goes down below the "zero" speed set by DIP switches.
LED11			Not used.

Note 1: The inverter work satisfactorily no matter whether phase sequence is positive or negative.

List of DIP switches

Switch No.	Name	Description
SW1-1	NORMAL/TEST	ON "NORMAL" (Usual operation) OFF "TEST" (Test operation) In usual operation, the switch is set at "NORMAL" position. When the circuit is checked or spindle orientation is checked, the switch is set at "TEST" position.
W - 2	CLOSE/OPEN	ON "CLOSE" OFF "OPEN" For switching of speed control loop between "OPEN" and "CLOSE".
SW1-3	BINARY/BCD	ON "BINARY" OFF "BCD" Digital speed command made can be selected by this switch. Speed command is read in binary 12 bit data with the switch set at ON, and in BCD 2-digit data with the switch set at OFF.
SW1-4	ATTENUATED EXCITATION	ON "ATTENUATED EXCITATION" OFF "NOT ATTENUATED EXCITATION" In usual operation, the switch is set at ON. With the switch set at ON, excitation voltage is decreased for reduction of noise level when slippage decreases.
SW1-5		
SW1-6	METER CALIBRATION	ON "METER CALIBRATION" OFF "NORMAL OPERATION" This switch is operated when speed meter or load meter is calibrated.
SW1-7	MAX. SPEED SETTING	ON "LOW SPEED" (PIN1 of SX-101 is set at "B") OFF "HIGH SPEED" (PIN1 of SX-101 is set at "A") When basic speed is 1500 rpm, HIGH SPEED = 6000 rpm LOW SPEED = 4500 rpm When basic speed is 1150 rpm, HIGH SPEED = 4600 rpm LOW SPEED = 3450 rpm

Switch No.	Name	Description																								
SW1-8	ZERO SPEED SETTING	ON Zero speed signal is output when spindle speed goes down below 25 rpm. OFF . . . Zero speed signal is output when spindle speed goes down below 50 rpm.																								
SW2-1		Not used																								
SW2-2 ? 4	ENCODER ORIENT POSITIONING LOOP GAIN 2	<table border="1"><thead><tr><th></th><th>(2)</th><th>(3)</th><th>(4)</th></tr></thead><tbody><tr><td>Mode 0</td><td>○</td><td>○</td><td>○</td></tr><tr><td>Mode 1</td><td>○</td><td>○</td><td>x</td></tr><tr><td>Mode 2</td><td>○</td><td>x</td><td>x</td></tr><tr><td>Mode 3</td><td>○</td><td>x</td><td>x</td></tr><tr><td>Mode 7</td><td>x</td><td>x</td><td>x</td></tr></tbody></table> <p>0 . . . ON x . . . OFF</p> <p>This switch function is effective only for encoder type orientation. Positioning loop gain can be set for speed tanging from "servo control speed" to "creeping speed". The standard witch setting is "mode 0" and mode of larger number is selected to shorten orientation time.</p>		(2)	(3)	(4)	Mode 0	○	○	○	Mode 1	○	○	x	Mode 2	○	x	x	Mode 3	○	x	x	Mode 7	x	x	x
	(2)	(3)	(4)																							
Mode 0	○	○	○																							
Mode 1	○	○	x																							
Mode 2	○	x	x																							
Mode 3	○	x	x																							
Mode 7	x	x	x																							
SW2-5 ? 7	ENCODER ORIENT POSITIONING LOOP GAIN 1	<table border="1"><thead><tr><th></th><th>(5)</th><th>(6)</th><th>(7)</th></tr></thead><tbody><tr><td>Mode 0</td><td>○</td><td>○</td><td>○</td></tr><tr><td>Mode 1</td><td>○</td><td>○</td><td>x</td></tr><tr><td>Mode 2</td><td>○</td><td>x</td><td>○</td></tr><tr><td>Mode 7</td><td>x</td><td>x</td><td>x</td></tr></tbody></table> <p>0 . . . ON x . . . OFF</p> <p>This witch function is effective only for encoder type orientation. Time taken for speed change from "orientation speed" to "servo control speed is set". The standard switch setting is "mode 0" and a mode of larger number is selected to shorten orientation time.</p>		(5)	(6)	(7)	Mode 0	○	○	○	Mode 1	○	○	x	Mode 2	○	x	○	Mode 7	x	x	x				
	(5)	(6)	(7)																							
Mode 0	○	○	○																							
Mode 1	○	○	x																							
Mode 2	○	x	○																							
Mode 7	x	x	x																							
SW2-8	ENCODER OR IENT ENCODER MOUNT DIRECTION	ON CW OFF . . . CCW This switch function is effective only for encoder type orientation. cw rotation is that direction of rotation of the encoder is same as that of motor.																								

Switch No.	Name	Description																																																		
SW3-1 2	TORQUE LIMIT	<table><tr><th colspan="2">External signal input</th><th>1</th><th>2</th><th></th></tr><tr><th>TL1</th><th>TL2</th><th></th><th></th><th></th></tr><tr><td>0</td><td>x</td><td>0</td><td>0</td><td>Torque limited to 10%</td></tr><tr><td></td><td></td><td>0</td><td>x</td><td>Torque limited to 15%</td></tr><tr><td></td><td></td><td>x</td><td>0</td><td>Torque limited to 20%</td></tr><tr><td></td><td></td><td>x</td><td>x</td><td>Torque limited to 25%</td></tr></table> <table><tr><td>x</td><td>0</td><td>0</td><td>0</td><td>Torque limited to 20%</td></tr><tr><td></td><td></td><td>0</td><td>x</td><td>Torque limited to 30%</td></tr><tr><td></td><td></td><td>x</td><td>0</td><td>Torque limited to 40%</td></tr><tr><td></td><td></td><td>x</td><td>x</td><td>Torque limited to 50%</td></tr></table> <p>The switch setting is not changed when particular torque limit is not required.</p>	External signal input		1	2		TL1	TL2				0	x	0	0	Torque limited to 10%			0	x	Torque limited to 15%			x	0	Torque limited to 20%			x	x	Torque limited to 25%	x	0	0	0	Torque limited to 20%			0	x	Torque limited to 30%			x	0	Torque limited to 40%			x	x	Torque limited to 50%
External signal input		1	2																																																	
TL1	TL2																																																			
0	x	0	0	Torque limited to 10%																																																
		0	x	Torque limited to 15%																																																
		x	0	Torque limited to 20%																																																
		x	x	Torque limited to 25%																																																
x	0	0	0	Torque limited to 20%																																																
		0	x	Torque limited to 30%																																																
		x	0	Torque limited to 40%																																																
		x	x	Torque limited to 50%																																																
SW3-3 4 5	Acceleration/Deceleration TIME CONSTANT	<p>Speed command time const for speeds ranging from zero speed to maximum speed is set. Standard setting: 1.5s 0 : ON x : OFF</p> <table><tr><th>3</th><th>4</th><th>5</th><th></th></tr><tr><td>0</td><td>0</td><td>0</td><td>0.3s</td></tr><tr><td>0</td><td>0</td><td>x</td><td>1.5s</td></tr><tr><td>0</td><td>x</td><td>0</td><td>3s</td></tr><tr><td>0</td><td>x</td><td>x</td><td>4s</td></tr><tr><td>x</td><td></td><td>00</td><td>5s</td></tr><tr><td>x</td><td>0</td><td>x</td><td>8s</td></tr><tr><td>x</td><td>x</td><td>0</td><td>9s</td></tr><tr><td>x</td><td>x</td><td>x</td><td>10s</td></tr></table>	3	4	5		0	0	0	0.3s	0	0	x	1.5s	0	x	0	3s	0	x	x	4s	x		00	5s	x	0	x	8s	x	x	0	9s	x	x	x	10s														
3	4	5																																																		
0	0	0	0.3s																																																	
0	0	x	1.5s																																																	
0	x	0	3s																																																	
0	x	x	4s																																																	
x		00	5s																																																	
x	0	x	8s																																																	
x	x	0	9s																																																	
x	x	x	10s																																																	
SW3-6 7 8	SPEED DETECTION RANGE	<p>Speed detection range can be selected from 8 ranges (2%, 10%, 18%, 26%, 34%, 50% and 58%). When speed enters the speed range set by these switches, the transistor for speed detection turns on.</p> <table><tr><th>6</th><th>7</th><th>8</th><th></th></tr><tr><td>0</td><td>0</td><td>0</td><td>2%</td></tr><tr><td>0</td><td>0</td><td>x</td><td>10</td></tr><tr><td>0</td><td>x</td><td>0</td><td>18</td></tr><tr><td>0</td><td>x</td><td>x</td><td>26</td></tr><tr><td>x</td><td></td><td>0</td><td>34</td></tr><tr><td>x</td><td>0</td><td>x</td><td>42</td></tr><tr><td>x</td><td>x</td><td>0</td><td>50</td></tr><tr><td>x</td><td>x</td><td>x</td><td>58</td></tr></table>	6	7	8		0	0	0	2%	0	0	x	10	0	x	0	18	0	x	x	26	x		0	34	x	0	x	42	x	x	0	50	x	x	x	58														
6	7	8																																																		
0	0	0	2%																																																	
0	0	x	10																																																	
0	x	0	18																																																	
0	x	x	26																																																	
x		0	34																																																	
x	0	x	42																																																	
x	x	0	50																																																	
x	x	x	58																																																	

Switch No.:	Name	Description		
SW4-1		Not used.		
SW4-2 3 4 5 6 7	GEAR RATIO SETTING	Spindle orientation speed and servo control speed are set by these switches (gearing ratio is changed from individual application).		
SW4-8				
SW5-1 2	DIRECTION OF ORIENTATION		SW 1 2	0 ... ON X ... OFF
		PRE	0 0	Orientation in forward direction of motor rotation.
		CCW	o x	Orientation in counter-clockwise direction of motor rotation.
		cw	X O	Orientation in clockwise direction of motor rotation.
		cw	xx	Orientation in clockwise direction of motor rotation.



List of rotary switches

Switch NO.	Name	Description		
SW6	ORIENTATION SPEED SETTING	Setting	<p>“Orientation speed” for encoder type orientation is set by this rotary switch. The listed speeds are spindle speed RPM and motor speed depends on gearing ratio. Orientation speed should be decreased when spindle stops running over the predetermined stop position due to large load GD².</p>	
		0		30 rpm
		1		85
		2		90
		3		95
		4		100
		5		105
		6		110
		7		115
		8		120
		9		125
		A		130
		B		135
		C		140
		D		145
		E		150
		F		155
SW7	ENCODER ORIENTA- TION ORIENT INPOSI- TION RANGE	Setting	<p>Range of positioning error in orient completion signal can be set. - One turn of spindle is divided into 4096 points. Error range = $360^{\circ} \times \frac{\text{Setting}}{4096}$ Standard setting: “A”</p>	
		0		0
		1		0.09°
		2		0.18°
		3		0.26°
		4		0.35°
		5		0.44°
		6		0.53°
		7		0.62°
		8		0.70°
		9		0.79°
		A		0.88°
		B		0.97°
		C		1.06°
		D		1.14°
		E		1.23°
		F		1.32°
SW8 SW9 SW10	ORIENT POSITION SHIFT	<p>SW10 0 ~ F x256 SW9 0 ~ F x16 t 2-bit binary SW8 0 ~ F x1</p> <p>Position shift value = $360^{\circ} \times \frac{\text{Setting}}{4096}$</p> <p>Least increment = $360^{\circ} \times \frac{1}{4096}$</p> <p>When the encoder is installed, setting should be made so that spindle stops at the predetermined position.</p>		

Switch No.	Name	Description
		<p>Orientation (indexing position) does not change even when setting is changed when the orientation is not in operation.</p> <p>Position can be shifted in spindle reverse rotating direction with the encoder installed in CW direction, and in spindle forward rotating direction with encoder installed in CCW direction, when rotary switch is turned in direction. _____</p>

List of toggle switches

Switch No.	Name	Description
ST1	RESET	<p>For initializing the invener</p> <p>This switch should not be operated while the motor is running.</p> <p>Whenever DIP switch setting is changed, this should be operated.</p> <p>DO NOT RESET WHILE THE MOTOR IS RUNNING.</p>
ST2	ORIENTATION TEST	<p>The motor runs at "orientation speed" while this switch is held at ON position.</p> <p>When the switch is set to OFF, the motor stops after the completion of one cycle of orientation.</p>



Pin Na.	Name	Description
PIN11	ORIENT POSITION DETECT P L G ON/OFF	<p>"A" side should be set to supply the power source to orient position detect pulse generator from the spindle control unit</p> <p>"B" side should be set to supply the power source to orient position detect pulse generator from the NC.</p>
PIN12	ORIENT POSITION INPUT	<p>For source input</p>  <p>PIN12 ... A PIN13 ... D</p> <p>For sync. input</p>  <p>PIN12 ... B PIN13 ... C</p>


List of variable resistors

Since the variable resistors in this card have been properly set by us, not change the setting.


VR No.	Name	Description
VR11	"6" phase zero adjustment	Do not change the setting.
VR12	"A" phase rem. adjustment	Do not change the setting.
VR13	"A" phase gain adjustment	CH59A, Speed feedback, Sine wave PLG Adjusted to $\pm 10V$
VR14	"B" phase gain	CH60A, Speed feedback, Sine wave PLG "LOW SPEED" to $\pm 10V$
VR15	Not used	
VR16	Not used	


List of check terminals

Terminal No.	Description
P5A	+5V
DGA	+0V (Digital ground)
cii51	Speed feedback "A" phase, rectangular waveform  -For CW rotation
CH52	Speed feedback "B" phase, rectangular waveform  -For CCW rotation
CH53	Orient position feedback mark pulse
CH54	Orient position feedback "A" phase
CH55	Orient position feedback "B" phase
CH56	-15V
CH57	+0V (Analog ground)
CH58	+15V
CH59	Speed feedback "A" phase
CH60	Speed feedback "B" phase
CH59A	Speed feedback "A" phase
CH60A	Speed feedback "B" phase
CH61	+24V



5.3 SX-101 card





List of LEDs

LED No.	Symbol	Description
LED12	AL8	} Alarm display (For details, refer to "List of alarm signals".)
LED13	AL4	
LED14	AK	
LED75	AL1	
LED101 S LED112		Speed command display X1 X2 x 4 ⋮ X2048 } 12 bits

List of setting pins

Pin No.	Symbol	Description
PIN 1	Speed setting	A-TOP (full) speed 6000 rpm (Base speed 1500 rpm) 4600 rpm (Base speed 1150 rpm) B = TOP (full) speed 4500 rpm (Base speed 1500 rpm) 3460 rpm (Base speed 1150 rpm)

Note: Different ROM is used for 1500 rpm and 1150 rpm base speeds.



List of alarm signals

0: LED does not light.
1: LED lights.



Output = H level (Transistor turned off)
Output = L level (Transistor turned on)

Output							
Id.	AL3 (LED 12)	AL4 (LED 13)	AL2 (LED 14)	AL1 (LED 15)	Alarm	Cause	Resetting method
1	0	0	0	1	MOTOR OVERHEAT	Temperature in the motor goes up over the limit ($150 \pm 8^\circ \text{C}$)	After cooling the motor, operate ALARM RESET or RESET button.
20		0	1	0	EXCESS SPEED CON- TROL ERROR	Motor speed largely differs from com- manded speed. Detection speed error ± 5 (3000 rpm)	
3	0	0	1	1	For provision		
4	0	1	0	0	BREAKER TRIP	Unusually high source current flows causing tripping of breaker.	
so		1	1	0	PHASE LOSS	Any phase is discon- nected.	
6	0	1	1	0	EMERGENCY STOP	Emergency stop pushbutton on an external operation panel is depressed to "ON".	Operate the emer- gency stop push- button to set it "OFF". (Peak value = (Rated current) x 400%) (Unit: $60 \pm 5^\circ \text{C}$ Heatsink: $100 \pm 5^\circ \text{C}$)
7	0	1	1	1	OVERSPEED	Motor speed exceeds 115% of rated speed.	
8	1	0	0	0	CONVERTER OVER- CURRENT	Overcurrent flows - in the converter.	
9	1	0	0	1	CONTROLLER OVERHEAT	Temperature of heatsink is too high	
10	1	0	1	0	SOURCE VOL- TAGE DROP	The input source voltage is below 170V for 15 ms or longer.	

Output					Alarm	Cause	Resening method
No.	AL3 (LED 12)	AL4 (LED 13)	AL2 (LED 14)	AL1 (LED 15)			
11	1	0	1	1	OVER-VOLTAGE	DC voltage in the converter is too high.	
12	1	1	0	0	INVERTER OVER-CURRENT	Overcurrent flows in the inverter.	<div>Peak value = (Rated current) x 200%</div> <div>Currently not used</div>
13	1	1	0	1	CPU TROUBLE 1	Trouble occurs with microprocessor.	
14	1	1	1	0	CPU TROUBLE 2	Trouble occurs with microprocessor.	
15	1	1	1	1	CPU TROUBLE 3	Trouble occurs with microprocessor.	

P i n	N o .	Name	Description
PIN2		DIGITAL SPEED COMMAND INPUT MODE SELECTION	<p>For source input</p> <p><u>C, D short-circuited</u> PI N3 opened</p> 
PIN3			<p>For sync input</p> <p><u>A, B short-circuited</u> PIN2 opened</p> 

List of check terminals

Terminal No.	OV	Description
P5A DGA		+5V 0V (Digital ground)
CH3 CH4 CH5 CH6 CH7 CH8 CH9 CH10 CH11 CH12 CH13 CH1	AGA	<p>Analog speed command input TOP (full) speed +10V</p> <p>Overcurrent setting level (Operat. level +10V)</p> <p>Overcurrent setting level (Operat. level +10V)</p> <p>Converter voltage, feedback 5V ... VDC = 200V</p> <p>"U" phase ... Inverter current detection</p> <p>"W" phase ... Inverter current detection</p> <p>Source current detection. 10V ... $\pm AC = (\text{Rated current}) \times \sqrt{2} \times 4$</p> <p>Inverter "U" phase and "W" phase current rectified  $5V \dots I_{UVW} = (\text{Rated current}) \times \sqrt{2}$</p> <p>Reference voltage +1.0V } Adjustable by VR39 Reference voltage -1.0V }</p> <p>Override command +10V ... 120%</p>
CH14	AG8	<p>"W" phase reference sine wave</p>  $6.5V = \text{TOP (full speed)}$ $6.5V = \text{TOP (full speed)}$
CH15	AGB	"V" phase reference sine wave
CH16	AGB	"U" phase reference sine wave
CH17 CH18 CH19		
CH20 CH21 CH22	AGB	<p>"U" phase voltage integrator output</p> <p>"V" phase voltage integrator output</p> <p>"W" phase voltage integrator output</p>
CH23		

Terminal No.	OV	Description
CH24	MAIN CIRCUIT SIDE	Converter voltage on main circuit side.
CH25	MAIN CIRCUIT SIDE	Inverter current "U" phase on main circuit side
CH26	MAIN CIRCUIT SIDE	Inverter current "W" phase on main circuit side
CH27	MAIN CIRCUIT SIDE	Inverter transistor base drive signal "U" phase 0V main circuit transistor "ON"
CH28	MAIN CIRCUIT SIDE	Inverter transistor base drive signal "V" phase 0V main circuit transistor "ON"
CH29	MAIN CIRCUIT SIDE	Inverter transistor base drive signal "W" phase 0V main circuit transistor "ON"
CH30	MAIN CIRCUIT SIDE	Inverter transistor base drive signal "U" phase 0V main circuit transistor "ON"
CH31	MAIN CIRCUIT SIDE	Inverter transistor base drive signal "V" phase 0V main circuit transistor "ON"
CH32	MAIN CIRCUIT SIDE	Inverter transistor base drive signal "W" phase 0V main circuit transistor "ON"
CH33	AGB	Inverter "U" phase voltage feedback
CH34	AGB	Inverter "V" phase voltage feedback
CH35	AGB	Inverter "W" phase voltage feedback
CH36		
CH38	D08A	Inverter "U" phase base amplifier output
CH39	D08B	Inverter "V" phase base amplifier output
CH40	D08C	Inverter "W" phase base amplifier output
CH41	D08D	Inverter "U" phase base amplifier output
CH42	D08D	Inverter "V" phase base amplifier output
CH43	D08D	Inverter "W" phase base amplifier output


Since all variable resistors except for VR1 and VR2 have been set by us, do not change the settings.

No.	Description
VR1	Speed meter calibration
VR2	Load meter calibration
VR11	Reference sine wave "U" phase D/A converter gain adjustment
VR12	Reference sine wave "U" phase zero adjustment
VR13	Reference sine wave "V" phase D/A converter gain adjustment
VR14	Reference sine wave "U" phase gain adjustment CH16
VR15	Reference sine wave "V" phase zero adjustment
VR16	Reference sine wave "W" phase gain adjustment
VR17	Reference sine wave "V" phase gain adjustment CH15
VR18	"U" phase current balance adjustment
VR19	"U" phase current balance adjustment after gain selection (low speed)
VR20	"V" phase current balance adjustment
VR21	"V" phase current balance adjustment after gain selection (low speed)
VR22	"W" phase current balance adjustment
VR23	"W" phase current balance adjustment after gain selection (low speed)
VR24	Reference sine wave "W" phase level adjustment at gain selection
VR25	Reference sine wave "V" phase level adjustment at gain selection
VR26	Reference sine wave "U" phase level adjustment at gain selection
VR27	Inverter "U" phase voltage feedback adjustment CH33
VR28	Inverter "V" phase voltage feedback adjustment CH34
VR29	Inverter "W" phase voltage feedback adjustment CH35
VR31	A/D converter zero adjustment
VR32	Converter voltage feedback gain adjustment CH6
VR33	Current limit level setting CH4
VR34	Overcurrent level setting CH5
VR35	"U" phase current feedback zero adjustment CH 7
VR36	"U" phase current feedback gain adjustment CH?
VR37	"W" phase current feedback zero adjustment CH8
VR38	"W" phase current feedback gain adjustment CH8
VR39	±1.0V Reference source voltage CH12, CH13
VR40	Overspeed level adjustment at "L" speed setting PIN1-B
VR41	Overspeed level adjustment at "H" speed setting PIN1-A

5.4 SX-PW card

This card is the power supply unit that provide FR-SX with all necessary DC sources.

Note: Although there are two types of SX-PW card, which differ from each other in part loading pattern, they are completely compatible.



- Notes:**
1. The card is divided into 7 blocks ranging from block "A" block to block "F" and "0" line of each block is separated and insulated ("0" lines in block an connected).
 2. Blocks "B" ~ "F" are not insulated from the main circuit

Block	Name	Voltage	
Block "A"	P 5 A DGA (0V)	+5V ± 3%	
	AC DOWN	Control source voltage drop detection signal	
	P15A	+15V ± 1.5%	Control power source
	AGA (0V)	ov	
	N15A	-15V ± 1.5%	
P24 D024 (0V)	+24V		
Block "B"	P5B DGB (0V)	+5V ± 3%	Uninsulated part control power source
	P15B	+15V ± 1.5%	
	AGB (0V)		
	N15B	-15V ± 1.5%	
Block "C"	P8A	+8V +15%	"U" phase base power source
	D08A	0V - 5%	
	N8A	-8V +15%	
			- 5%
Block "D"	P8B	+8V +15%	"V" phase base power source
	D080	ov - 5%	
	N8B	-8V +15%	
			- 5%
Block "E"	P8C	+8V +15%	"W" phase base power source
	D08C	0V - 5%	
	N8C	-8V +15%	
			- 5%
Block "F"	P8D	+8V +15%	"U", "V", "W" base power source
	0080	0V - 5%	
	N8D	-8V +15%	
			- 5%

List of LEDs used in SX-PW

LED No.	Description
LED1	+5V (P5A) Lights when voltage is at normal level.
LED2	+15V (P15A) Lights when voltage is at normal level.
LED3	-15V (N15A) Lights when voltage is at normal level.
LED4	+24V (P24A) Lights when voltage is at normal level.


Nom The power source is unusual if the output voltage is not within the range listed in the previous pages even when the LEDs light on


The input power source to this card is specified to AC127 ~ AC35V, 50/60Hz.

5.5 SX-AJ1card

This card is used for auxiliary level settings necessary to adjust the input power source, protection(safety) circuit, current, voltage and feedback

SX-IO1 becomes replaceable by adjusting this card.





Variable resistor No.	Description
VR101	Inverter "U" phase current detect level adjustment
VR102	Inverter "W" phase current detect level adjustment
VR103	Inverter voltage feedback \pm voltage balance adjustment
VR104	Input current feedback level adjustment

CHAPTER 6 SPINDLE ORIENT POSITION DETECTOR INSTALLATION PROCEDURE

6.1 Magnetic sensor single-point orientation (SX-CPU 1 card is used)

6.1.1 Principle

The sensor (detector element) produces two different types of voltage, as shown in Fig. 6.1, depending on its location in reference to the magnet.




Fig. 6.1 Sensor output voltage

MS signal Output voltage is zero when the sensor is located at the center of the magnet, and maximum at both ends of the magnet. The position control is based on the zero voltage position.

LS signal Constant voltage is maintained within the tangs of the magnet. This signal is used to verify that the spindle is positioned within the range of the magnet

6.1.2 Time chart

Fig. 6.2 shows the time chart of each signal.




Fig. 6.2 Time chart

- (1) When ORC1 (orientation command) turns on, the motor speed changes from usual operation speed to the orientation speed.
- (2) When the motor speed reaches the orientation speed, the threshold speed signal (LED7) rises.
- (3) After the occurrence of threshold speed signal and when the sensor LS signal turns to "L" level (when the magnet just passes over the sensor), the "slow down timer" (software) starts counting.
- (4) The timer is set at SW2-5,6,7. When the timer counts up, orient speed control mode changes from the speed control loop to the position control loop (servo, IN).
- (5) Under the position loop control, the spindle stops when the sensor MS signal reaches zero volt.
- (6) When the spindle stops at the predetermined position, the orient completion signal rises and ORA1-ORA2 (orient completion contact signal output) closes in 200 ms after the stopping.


6.1.3 Direction of installation of magnet and sensor

The magnet and sensor must be installed in the specified direction, as shown in Fig. 6.3, 4 and 5.

- (1) The **center** reference hole of magnet and the key groove of sensor should be on the same side.
- (2) The center reference hole should be on the right side when **tool** attached to the spindle **is** on the left side (the reference hole should be opposite to the tool).


Case 1 When the magnet is installed on circumferential surface of rotating disc

The key groove and reference hole should be on counter-load side of the spindle, as shown in Fig. 6.3.



Case 2 When the magnet is installed on the side face of rotating disc

- (1) When the magnet and sensor are installed on the counter-load side of the spindle, the reference hole and key groove should be inward.
- (2) When the magnet and **sensor** are installed on the load side of the spindle, the **reference** hole and key groove should be outward.



6.1.4 Cautions on installation of magnet

The magnet should be installed with the following cautions:

- (1) Do not allow access of any other powerful magnetic object to the magnet.
- (2) Do not give physical shock to the magnet.
- (3) Secure the magnet to the spindle using M4 screws.
- (4) After the magnet has been installed, check and adjust the balance of the spindle.
- (5) Adjust the magnet so that the center reference hole of magnet is aligned with the center of rotating disc (its direction should be as illustrated in Fig. 6.3, 4 and 5).
- (6) Clean the vicinity so that malfunction due to adhesion of iron particles to the magnet does not occur.
- (7) Apply "lock paint" to the damping screws to prevent the screws from becoming loose.
- (8) Since a ground rotating disc may have been magnetized, demagnetize the disc when the magnet is installed on a ground rotating disc.
- (9) The diameter of rotating disc on which the magnet is installed should be within a range from 80 mm to 120 mm. However, disc of large diameter may be used when the spindle rotates at a low speed.

6.1.5 Cautions on installation of sensor

The sensor should be installed with the following cautions:

- (1) Install the sensor so that the key groove of sensor and the magnet reference hole are on the same side.
- (2) Align the center of sensor with the center of magnet (see Fig. 6.3, 4 and 5).
- (3) Adjust the gap between the magnet and the sensor to $1.5 \text{ mm} \pm 0.5 \text{ mm}$ for installation shown in Fig. 6.3, and to $4.5 \text{ mm} \pm 0.5 \text{ mm}$ for installation shown in Fig. 6.4, 5.
*It is recommended for mass production to prepare a gauge for this adjustment.
- (4) Although the connector of the amplifier is oilproof, it should be located away from oil.
- (5) Segregate the cable between the amplifier and the controller unit from the power circuit cables.
- (6) Check the connector wiring, securely set the plugs and tighten lock screws of each connector.





Fig. 6.8 Installation of sensor


6.1 .S Overall view of magnetic sensor

(1) Magnetic sensor

1 Magnet



2 Sensor



3 Amplifier




Fig. 6.9

6.2 Encoder type multi-point orientation

6.2.1 Principle

Fig 6.10 schematically shows the principle of the encoder type multi-point orientation in the form of time chart.




Fig. 6.10 Time chart

- (1) When orientation command, motor speed changes to "orientation speed".
- (2) When motor speed reaches the orientation speed, UP to speed signal (that is detected by comparator) rises. (software)
- (3) When a mark pulse is accepted after the UP to speed signal rises, indexing position data (12-bit binary) is read and at the same time count starts. The motor speed remains at the orientation speed.
- (4) When the spindle reaches ^{setting value of SW2-5.6.7} before the predetermined indexing (orientation) position, the control mode changes from the speed control loop to the position control loop and the motor speed changes from the orientation speed to the speed governed by gain of the positioning control amplifier.
- (5) The spindle enters the positioning control loop linear zone at ^{setting value of SW2-2.3.4} before the predetermined indexing position and the motor is decelerated and then stops at the predetermined indexing position.
- (6) "In-position" signal rises when the spindle reaches the point before the predetermined indexing position by a distance (angle) equal to SW7 setting. In about 200 ms after that, "In-position" signal output contact closes.
- (7) When the orientation command is removed, the motor starts rotating at the commanded (S command) speed.
- (8) Repeating of orientation is possible after one turn of the spindle.
However, the spindle rotates over one turn depending on externally commanded indexing position and settings of SW10, SW9 and SW.

6.22 Encoder type multi-point orientation system composition





Fig. 6.17

Note: If direction of rotation differs between the motor and encoder, due to reduction gear meshing, adjust it by operating DIP switches SW2 - 8 of SX-CPU2.

6.2.3 Overall view of encoder

(1) Dimensions of encoder



CHAPTER 7 TROUBLESHOOTING

7.1 Preliminary checking

If any trouble occurs with the controller unit, it is recommended to perform the following simple checking before starting the troubleshooting.

The preliminary checking is very helpful when you consult with our service agency.

Preliminary checking in case of controller trouble

1. Does any alarm lamp on the controller front panel light? If yes, identify the lamp.
2. Is any fuse blown out?
If yes, identify the phase, fuse of which was blown out (R, S and T phases).
3. Is the same failure or trouble reproducible?
4. Are the ambient temperature and panel inside temperature within the specified range?
5. Did the trouble occur during acceleration, or deceleration or steady-speed operation?
6. Is direction of rotation proper?
7. Did momentary power failure not occur?
8. Does the same failure or trouble occur with specific operation or command?
9. Does the same failure or trouble occur frequently?
10. Did the trouble occur when load is exerted, or when load is removed?
11. Was any part replaced, or any remedy is done by yourself?
12. How many year has been operated the controller?
13. Is the source (line) voltage proper and stable? Does it change depending on time?

7.2 1st step troubleshooting

Perform the following checking at the 1st step of troubleshooting.

- (1) Source voltage $200V \pm 10\%$ 50/60Hz, 210V·220V·230V $\pm 10\%$ 60Hz

In any case, the source voltage should not be below -10% of 200V.

Examples of source voltage drop:

- Voltage drops at a certain time every day.
- Voltage drops at start of a specific machine.

- (2) Are peripheral control functions proper?

Examples of checking:

- Are NC and sequential control circuit in good condition?
- Is any failure or defect found in parts or wiring when checked visually?

- (3) Is the temperature around the controller unit (and in the unit) within 50°C?

- (4) Does the controller unit present good appearance?

Examples of checking:

- Are card components, circuit patterns, etc. in good condition?
- Are all wires securely connected?


Is any part not damaged?

Is there any foreign matter?

(5) Is the DC source output SW-PW at the specified level?

The cause of the trouble may be roughly identified after the above checking.

The most likely troubles with FR-SX can be categorized as follows:



7.3 2nd step troubleshooting

Trouble (I)	Check-up	Remedy
Controller turned on for the first time does not work satisfactorily . . .	Since all units strictly and repeatedly checked before shipping, the most likely cause of the trouble is, (1) The controller was damaged due to large shock or intense strike during transport or installation.	(1) Visually check the appearance of the controller for damage.
	(2) Wrong external wiring, sequential control error, wire/cable disconnection Is grounding wire connected? Note: Difference in phase sequence does not cause any trouble.	(2) Make sure LED1 ~ LED4 (power indication) of SX-PW light Check the external wiring and sequential control.
	(3) Check ROM No. and DIP switch settings against the the order sheet.	(3) Replace ROM or change DIP switch settings if necessary.
	* (4) The motor does not run at the specified speed.	(4) Interchange motor armature connection between any two of three wires (U, V, W).
	(5) The motor can run satisfactorily only when load is not exerted.	(5) Check that the load meets the design value.
	(6) Exact indexing is impossible (stop position is not exact).	(6) Adjust
	(7) Controller alarm LED AL8, AL4, AL2 or All (LED12, LED13, LED14 or LED15) lights.	(7) Refer to para. 7.4.

Trouble (II)	Check-up	Remedy
Controller that had been working in good condition came into standstill ...	(1) Check if fuse is blown out, or main circuit no-fuse breaker is tripped.	(1) Replace blown out fuse. If the new fuse is blown out again, perform the 3rd stop troubleshooting.

Trouble (II)	Check-up	Remedy
	(2) Check the input power source. AC200V \pm 10% 50Hz AC200 ~ 230V \pm 10% 60Hz	(2) Restore the power source if necessary. The power source should be that the power requirement shown to the left can be satisfied at all times.
	(3) Controller alarm LED AL8, AL4, AK or AL1 (LED12, LED13, LED14 or LED15) lights.	Refer to pas 7.4.
	(4) Check the input signals from NC or sequence control. LED? (READY) should light when the system is ready for operation. LED3 (CW) should light for CW rotation start. LED4 (CCW) should light for C.CW rotation start.	14) Enter the correct external signals.
	(5) SW1-2 "OFF" open SW3-3, 4, 5 "OFF" cushion Check if "open" operation is possible by operating RESET button (10S).	(5) Speed feedback encoder is defective if operation is possible (replace the encoder). If operation is impossible, the trouble will be attributable to the main circuit (alarm LED will light).

Trouble (III)	Check-up	Remedy
Controller comes into standstill from time to time . . . Stop position is not exact at all timer Alarm LED lights. Condition is restored by turning on and off the power, or by resetting.	It is very important to be exactly aware of the conditions under which the trouble occurs (load condition, operation mode). The cause (3) is possible. (1) Instantaneous power failure or source voltage drop or "NF TRIP" (when instantaneous power failure occurs during generative braking) "CONVERTER IOC" alarm LED may light.	(1) Check the power source for source voltage regulation. . . . -

Trouble (III)	Check-up	Remedy
	(2) Malfunction due to extremely large noise The controller itself can withstand the line power noise up to 1600V/ins (max. 2000V/lus) in both common mode and normal mode.	(2) Identify noise source and install noise suppressor to the noise source. Check grounding (particularly grounding of detector). Check case grounding.
	(3) Check if load increases momentarily due to vibration, or the like. Check with a particular care if indexing error occurs	(3) Carefully check the mechanism.

7.4 Detailed checking for each trouble

1. If alarm LED lights. . .

The alarm LED of the protection that first gets into function lights.

(1) MOTOR OVER HEAT

AL3 (LED12)	AL4 (LED13)	AL2 (LED14)	AL1 (LED15)
0	0	0	1

Current does not flow into OHS1 and OHS2

Cause	Check-up	Remedy
Over-load	1. Check the motor loading condition. 2 Check start/stop frequency.	1. Lighten the load. 2. Decrease the start/stop frequency.
Fan trouble	Check the fan motor for condition.	Remedy or replace the fan/fan motor.
Motor air intake dogged	Check ventilation (air feed rate).	Clean.
Thermal protector aoubie	Check if resetting is possible after rotating the motor fan for several minutes with the motor stopped	1. Short-circuit between OHS1 and OHS2 and continue the operation. 2 Replace the motor.

(2) EXCESSIVE SPEED ERROR

AL8 (LED12)	AL4 (LED13)	AL2 (LED14)	AL1 (LED15)
0	0	1	1

When speed control error (difference between commanded speed and actual speed) is larger than specified level (500rpm)...

Cause	Check-up	Remedy
Over load	1. Check the motor loading condition.	1. tighten the load.
Speed detection encoder trouble	1. "Open" operation is possible.	1. Replace the encoder.
Card trouble	1. SX-CPU1 or 2 card, SX-IO1 card Double	1. Replace the card CPU 1 or CPU2 first and then IO1.


(3) BREAKER TRIP

AL8 (LED12)	AL4 (LED13)	AL2 (LED14)	AL1 (LED15)
0	1	0	0

LED lights when the main no-fuse breaker trips.

It is possible that IOC (converter, inverter) lights first.

Cause	Check-up	Remedy
Power source voltage drops below 180V.	Check if source voltage goes down the specified level during deceleration (regenerative braking).	Since transient voltage is likely to drop below 180V if source voltage is near 180V during usual operation, boost the source voltage.
IOC trip (Refer to the description about IOC trip)	RefRefer to the description about IOC trip.	a b o u t

Cause	Check-up	Remedy
Converter voltage oscillates during deceleration	Check the maximum speed start/stop waveform when the converter is under full-voltage load condition. 	<ul style="list-style-type: none"> Change acceleration/deceleration constant. Change load GD^2. Replace card SX-101 if necessary.
Phase disconnection	Any phase of input power source is disconnected and PLL is released from locking.	Open and close the no-fuse breaker (power) to check the power.

(4) PHASE LOSS (PHASE DISCONNECTION)

AL3 (LED12)	AL4 (LED13)	AL2 (LED14)	AL1 (LED15)
0	1	0	1

Check to see if the corresponding alarm LEDs light when the power is turned on.

Cause	Check-up	Remedy
Any phase is disconnected	Check voltage at each phase.	Three phases should be connected.
Fuse Ft, 2 or 3 is blown out	Check the cause of blowing out of fuse (short-circuiting, for example).	Replace the blown out fuse.

(5) EXTERNAL EMERGENCY

AL3 (LED12)	AL4 (LED13)	AL2 (LED14)	AL1 (LED15)
0	1	1	0

The corresponding LEDs light when external emergency stop signal is given.

Check the cause of emergency stop and then reset.

(6) OVER SPEED

AL3 (LED12)	AL4 (LED13)	AL2 (LED14)	AL1 (LED15)
0	1	1	1

The LED lights as shown above when the motor speed exceeds 115% of the maximum speed and the over speed detector trips.

Cause	Check-up	Remedy
Improper max. speed setting	Check the settings of SX-IO1 PIN1 and SX-CPU SW1-7.	Correctly set if necessary.
Speed detector trouble	Check the encoder output CPU2 card (CH59 ~ CH57) CH60 ~ CH57 CPU1 card (CH56 ~ CH54) CH57 ~ CH54	Replace the detector. $\frac{512 \times 1500}{60} = 12.8 \text{ KHz}$ at 1600 rpm
Speed control detecting circuit trouble	Defective cards	Replace the card SX-CPU first and then SX-IO1.

(7) IOC TRIP (INVERTER, CONVERTER)

Converter IOC

AL8 (LED12)	AL4 (LED13)	AL2 (LED14)	AL1 (LED15)
1	0	0	0

Inverter IOC



AL8 (LED12)	AL4 (LED13)	AL2 (LED14)	AL1 (LED15)
1	1	0	0

IOC trip occurs on the inverter side as well as the converter side, due to overcurrent.

Check the cause of overcurrent.

It is likely that any ^{main circuit} semiconductor element is damaged if IOC trip occurs again when the RESET button is depressed.

Cause	Check-up	Remedy
Power transistor is damaged.	Remove the connection between the controller and the motor and operate only the controller to see if the alarm LEDs (IOC TRIP) light or not. <ul style="list-style-type: none"> If LEDs light the power transistor is defective. If LEDs does not light, proceed with the next step. 	Replace the power transistor.

Cause	Check-up	Remedy
To large motor load	Check the load to the motor.	tighten the load.
Wrong motor wiring	Check the motor wiring. Check terminal screws for looseness.	Correct motor wiring if necessary Tighten loose screw.
Motor winding layer short-circuiting or grounding	Measure the insulation resistance. If insulation resistance is smaller than 1 Megohms, the motor is defective.	Replace defective motor.
Commutation fails at regenerative braking, due to low source voltage.	The source voltage should be farther than 180V at R, S and T phases.	Boost the power voltage.
Too small power source capacity	Source voltage should be at least 180V at acceleration/deceleration as well as under loaded condition	Increase power source capacity.
Power source voltage waveform trouble	<p>Observe the source voltage waveform during acceleration and deceleration using a synchroscope.</p> <p>1. If voltage discontinues partially ...</p>  <p>2 If voltage is chopped ...</p> 	<p>Improve waveform.</p> <p>1. increase the power source capacity or use a cable of larger size.</p> <p>2. Remedy semiconductor unit that causes deformed waveform.</p>
Source frequency trouble	Source frequency should not change over $\pm 3\%$.	Improve the power source.
Current detector circuit trouble	Inverter CH11 ~ AGA: 10V peak Converter CH9 ~ AGA: 10V peak	Replace card SX-101.

(8) CONTROLLER OVER HEAT

AL8 (LED12)	AL4 (LED13)	AL2 (LED14)	AL1 (LED15)
1	0	0	1

Tine alarm LEDs light as shown above when the controller thermal protection works (cooling fan installed).

Cause	Check-up	Remedy
O v e r l o a d	1. Check motor loading condition. 2 Check start/stop frequency.	1. Lighten the load. 2. Decrease start/stop frequency.
Ambient temperature is too high.	Measure the ambient temperature around the controller.	If the temperature exceeds 50°C, cooling method should be improved.
Thyristor cooling fan trouble	Check the cooling fan operation.	Replace the cooling fan.

(9) UNDER VOLTAGE (VOLTAGE DROP)

AL8 (LED12)	AL4 (LED13)	AL2 (LED14)	AL1 (LED15)
1	0	1	0

The LEDs light as shown above, when the input source voltage goes down below 170V ~ 164V for 15 ms or longer.

Cause	C h e c k - u p	Remedy
When usual operation can resumed after resetting.	The LEDs light when speed is changed or too large load is exerted.	Increase the power source capacity.
When the LEDs light continuously.	When the input power source is normal, the most likely cause is SX-PW card trouble. Signal level across SX-PW terminals ACDOWN and D05A is to be "H" level when the control circuit is normal (+5V).	Replace SX-PW card.

(10) OVER VOLTAGE (CONVERTER)

AL3 (LED12)	AL4 (LED13)	AL2 (LED14)	AL1 (LED15)
1	0	1	1

The LEDs light when the voltage in the incorporated smoothing capacitor exceeds the permissible level.

Cause	Check-up	Remedy
Overload	If the LEDs light during deceleration of motor, check the load.	Lighten the load.
GD ² is too large.	If the LEDs light during deceleration of motor, check the load.	tighten the load. <i>Acc/DEC time constant increase SW3-3.4.5</i>
Converter voltage control is not in good condition.	Check that voltage across P and N terminals of main circuit capacitor is below DC250V under usual operating condition, and if it changes depending on the	If the voltage exceeds 250V, or does not change depending on the speed, the cause of the trouble is defective converter. Replace SX101 card ↓ Replace SX-CPU card
Detector circuit trouble	If the cause of trouble is other than described above, trouble with the detector circuit is possible.	Replace SX-101 card.

(11) CPU trouble


AL3 (LED12)	AL4 (LED13)	AL2 (LED14)	AL1 (LED15)
1	1	0	1
1	1	1	0
1	1	1	1

CPU troubles include arithmetic operation error or logic error.

Reset and try operation again to see the condition. Card or CPU chip must be replaced depending on the trouble.

2. Troubles that do not cause lighting of alarm LED

(1) The motor does not run at all though no alarm LED lights. . .

Cause	Check-up	Remedy
Wrong wiring or wire disconnected.	Check the wiring.	Properly connect wires
Unusual power source Voltage change	Check that the source voltage is at 200V 50Hz/200 ~ 230V 60Hz	Restore the power source.
DC source trouble	Check all output voltages of SX-PW card using a multi-meter.	Replace the card if necessary.
Card trouble	<p>Operate SW1-SW2 to "OFF" (usually "ON") for "open" mode and check that the reference sine wave occurs when commanded speed is increased.</p> <p>SX-101 card CH16-AGB CH15-AGB CH14-AGB</p>  <p>The converter voltage across terminals P and N should be DC50V when the power is turned on.</p>	<p>When the card is in good condition.</p> <p>Replace card SX-101 and then SX-CPU.</p>

(2) The motor can run only at low speed, though no alarm LED lights. . .

Cause	Check-up	Remedy
Wrong motor wiring	Check that motor cable is connected to the output terminals (U, V, W) of controller in correct phase sequence.	Change connection if necessary.
Power source trouble	Check that the power source is in good condition at each phase.	Restore the power source.
Improper speed command (external)	Check that the motor speed follows the external speed command	Improve the external speed command circuit.

Cause	Check-up	Remedy
Speed detector encoder trouble	Set SW1-2 to "OFF" to make sure "open" mode operation is possible.	Replace the encoder if necessary.

- (3) The motor does not run at the commanded speed within a specific speed range. . .

cause	Check-up	Remedy
Improper external speed command	Check that external speed command can linearly vary from 0V to 10V (CH3-AGA).	Remedy or improve the external speed command circuit

- (4) Motor torque is not sufficient.

Perform the checking per steps (5), (6) and (7).

- (5) Times taken for start and stop become longer. . .

Cause	Check-up	Remedy
increase load	Check the load.	Lighten the load.

- (6) Threshold speed signal (UP-TO SPEED) does not output.. .

Cause	Check-up	Remedy
Card SX-101 trouble of output circuit trouble	Check that LED7 of SX-CPU lights when acceleration/deceleration is completed. If it lights, the cause of trouble will be defective output circuit	Replace card SX-101.
Threshold speed detector trouble.	LED7 (UP-TO SPEED) of SX-CPU will not light	Card SX-CPU trouble. Replace the card

- (7) NC feed is ineffective. . .

The most likely cause of this type of trouble is that the threshold speed detection does not function properly. Check the relay sequential operation and also perform checking per step (10).

(8) Speed detection signal does not output ...

Cause	Check-up	Remedy
Card SX-101 trouble	Check that LED5 of SX-CPU1 lights when the motor speed exceeds the preset speed. If it lights, the output circuit is defective.	Replace the card SX-101.
Speed detector circuit trouble	LED5 of SX-CPU2 will not light	Card SX-CPU trouble. Replace the card.

(9) Zero speed detection signal does not output. ..

Cause	Check-up	Remedy
Trouble with relay RA1 of card SX-101	Check that LED 10 of SX-CPU lights at motor speed below 25 rpm or 50 rpm. If signal does not output even though LED 10 lights, the most likely cause of the trouble is defective relay.	Replace relay RA1 or card sx-tot.
Zero speed detector circuit trouble	If LED10 does not light, the cause of the trouble will be defective detector circuit.	Replace card SX-CPU1 or CPU2

(10) Speed range is not selectable.. .

The most likely cause of this type of trouble is that the speed detect function or zero speed function does not work properly.

Perform checking per steps (12) and (13).

(11) Motor speed cannot be accelerated over a certain speed ...


Perform checking per step (7).


(12) Vibration/noises are too large. ..

Cause	Check-up	Remedy
Converter voltage is too high or low.	Voltage across terminals P and N should be DC50V when it is measured with the motor stopped after turning on the power.	Adjust the voltage by turning VR32 of card SX101. If adjustment is impossible, replace card SX-101.
Too large voltage is applied to the motor.	Voltage at CH5A of SX-101 should be $\pm 5.5V$ when the motor runs at the maximum speed.	Adjust the voltage by turning VR24 of card SX-101.

Cause	Check-up	Remedy
Decreased insulation resistance	<p>Disconnect the power cable connection (R, S, T) and measure insulation resistance as follows, using a multimeter (<u>each wire connected to GND terminals should be disconnected</u>).</p> <p>(a) Between entire main circuit and ground ... At least 20 Megohms (Terminals: X₁, X₂, X₃; U, V, W, MS1, MS2)</p> <p>(b) Between control circuit COM and ground. ... At least 20 Megohms (Terminal: OM of terminal block TB1 (Card I01))</p> <p>(c) Between entire control circuit and COM of control circuit ... At least 20 Megohms</p>	if insulation resistance is found decreased, remedy or replace deteriorated part
Motor bearing trouble	Turn the motor by hand to check that the motor can rotate smoothly.	Replace bearings if necessary.
Poor motor installation	Check motor mounting screw for looseness.	Retighten the screws.
Motor shaft runout	Check if any trace of strike is found on the motor shaft	Remedy or replace the motor.
Unbalanced reference sine waves	Check balance of waveform observed at CH16, CH15 and CH14 ~ AGB of card SX-I01.	Adjust balance of current in card SX-I01 or replace the card.

(13) Speed control is usual but orientation (indexing) is out of control ...

Cause	Check-up	Remedy
Spindle does not stop at the predetermined position, though orientation speed can be achieved.	<p>Check the position detecting encoder or magnetic sensor for function.</p> <p>Run the motor under only speed control and check position detecting (feedback) function.</p> <p>SX-CPU2 (in CW rotation)</p> <p>CH55-DGA CH54-DGA CH53-DGA Mark pulse</p> <p>SX-CPU1 (in CW rotation)</p> <p>CH58-AGA (I16-6)</p> <p>CH57-AGA</p> 	<p>Replace encoder or magnetic sensor.</p> <p>Replace card SX-CPU if the card interface is defective.</p> <p>ENCODER ORIENTATION Check the SW2-8 in SX-CPU2 CARD</p>
Stop position differs depending on direction of orientation.	<p>Mark pulse width is improper.</p> <p>Mark pulse width is not equal to 5 pulses (FBx4 times).</p>	<p>Replace detector (encoder or magnetic sensor).</p> <p>Replace with RFH-1024-22-I-68, or equivalent, or replace ROM.</p> <p>NICON</p>
Hunting occurs when spindle stops.	<p>Try to decrease position control loop gain.</p> <p>Decrease the orientation speed.</p>	<p>SX-CPU2 SW2-2 ~ 4 SW2-5 ~ 7 (Position control loop gain) SW6 Orientation speed</p> <p>SX-CPU1 SW5-3 ~ 4 SW6 Orientation speed</p>
Stop position differs depending on gearing ratio.	<p>Check gearing ratio setting.</p> <p>Check setting of DIP switches SW4-2 ~ 7.</p> <p>Check ROM No.</p>	<p>Change gearing ratio setting if necessary. When gearing ratio setting is proper, adjust position control loop gain and/or orientation speed</p>

Faint servo STIFFNESS	<p>o Check that converter voltage is about 30V. when the spindle is indexed.</p> <p>o Check that inverter current of SX-IO1 (CH11 ~ AGA) is A (about V).</p> <p>o Run the motor at low speed to observe the waveform at CH59A and CH60A.</p> <p>CW rotation</p> 	<p>When voltage is improper, replace card SX-IO1.</p> <p>When current is improper, replace card SX-IO1.</p> <p>If the waveforms are not as shown to the right, adjust them by turning V R 13 of card SX-CPU2</p> <p>Adjust by turning VR14.</p>

CHAPTER 8 REPLACEMENT OF PARTS

8.1 Replacement of each card

(1) Card SX-PW

If DC voltage is unusual, replace this card.

To replace this card, card SX-IO1 should be removed.

(2) Card SX-CPU1


Replace this card after checking ROM No. DIP switch settings and set pin settings.

Adjust magnetic sensor sensitivity (VR4) and orientation shift (VR3) again.

(3) Card SX-CPU2

Replace this card after checking ROM No., DIP switch settings and set pin settings.

If indexing (spindle stop) position is problematic, run the motor at low speed and adjust as follows:



CH59A-AGA (CH57) VR13 (SX-CPU2)
CH56A-AGA (CH54) ---- VR14 (SX-CPU1)

CH60A-AGA (CH57) VR14 (SX-CPU2)
CH55A-AGA (CH54) ---- VR17 (SX-CPU1)

If the voltages are not adjusted to $\pm 10V$, turn and set VR13 and 14 to adjust.

(4) Card SX-IO1

Replace this card after checking set in pin settings.

Note that the connectors for connection to the main circuit is on the back of B panel.

Usually no adjustment is required when this card is replace. If large gear sound or speed ripple occurs, however, perform balance adjustment.

CH16-AG8 ("U" phase reference sine wave)

CH15-AG8 ("V" phase reference sine wave)

CH14-AG8 ("W" phase reference sine wave)

(5) Card SX-AJ1

No trouble will occur with the parts of this card, except for blower control relays.
If the card is replaced, all variable resistors must be set again.

8.2 Thyristor module and transistor module

1. Removal of defective module

Disconnect the wires connected to the module, remove the heatsink and then defective module.

Note that plug-in terminal is used for thyristor module gate terminal G, transistor module base terminal B and emitter terminal E.

2. Applying the silicon grease to the module

Evenly apply silicon grease to the reverse surface of the module.

3. Securing the module

Secure each wire with the specified damping torque

Be sure to put a silicon tube to the thyristor module gate terminal, transistor module base terminal and emitter terminal as they were.

Note: SINCE THYRISTOR AND TRANSISTOR ARE OF SPECIAL SPECIFICATION, ORDER THEM TO US FOR REPLACEMENT OR SPARE.

	Model	Screw size	Max. damping torque (kg-cm)	Recommended damping torque (kg-cm)
Thyristor	TM55DZ-H	M6 x 1.0	30	20±2
	TM90DY-H	M6 x 1.0	30	20±2
Transistor	QM100DY-H DM200HA-H DM150DY-H	M5 x 0.8	20	17±2

Table 6.1 Damping torque list

8.3 Speed detector and shaft coupling

Referring to Fig. 8.1 "AC spindle motor construction" and Table 8.2 "Parts list", replace pares of speed detector and/or shaft coupling as follows:

- (1) Remove terminal box cover 5 and disconnect the cables used to connect the motor to the electrical panel.
Three motor main leads (U, V, W), two cooling fan leads (BU, BV), overheat detector leads (OHS1, OHS2) and plugs of speed detector connector 4 .
- (2) Remove the terminal box cover with unused wiring hole and loosen two coupling set screws 23 (distant at about 90° from each to other) that secure the motor shaft to coupling 22 using a hexagon wrench key (M4) passed through the wiring hole,
- (3) Remove four speed detector mounting screws 21 and remove speed detector 24 from coupling 22 .
- (4) Loosen other two coupling set screws 23 and remove coupling 22 from the shaft.
- (5) Replace speed detector 24 and/or coupling 22 .
- (6) Assemble in the reverse steps to the above steps.

Notes: 1. Do not exert force to protection cover 2 in such a manner that the flange of speed detector 24 is mis-aligned with the motor shaft
2. Do not exert force to the bellows of coupling in such a manner that the bellows are bent or expanded.

8.4 Cooling fan

Referring to Fig 8.1 "AC spindle motor construction", Table 8.2 "Parts list" and Fig. 8.2 "Cooling fan leads", replace the cooling fan as follows:

- (1) Remove terminal box cover 5 and cut four cooling fan leads 26 that extend forward from the back of the terminal box from the portion shown in Fig. 7.2.
- (2) Remove four cooling fan mounting screws 25 and gird net and remove cooling fan 1 from protection cover 2 .
- (3) Install a new cooling fan and pass cooling fan leads 26 through the hole at the back of terminal box .
Connect four leads (green, white, black and red) to each corresponding lead using crimp type terminal or by soldering.
- (4) Tighten cooling fan mounting screws 25 and install the gird net.

Note: Connected portion of each cooling fan lead 26 should be insulated by adhesive tape.

8.5 Bearings

Referring to Fig.8.1 "AC spindle motor construction" and Table 8.2 "Parts list", replace bearing as follows:

- (1) Remove speed detector 24 and coupling 22 as described at para. 8.3.
- (2) Remove four protection cover mounting bolts 6 using a hexagon spanner and remove protection cover 2 together with cooling fan 1 from the bracket-9 on the counter-load side.

Note: Carefully draw out motor main leads (U, V, W) and overheat detector leads (OHS1, OHS2) from the lead hole of protection cover 2.

- (3) Remove four bracket mounting bolts 8 that secure bracket 9 on the counter-load side to frame 14 using a spanner.
- (4) Remove four bearing holder plate mounting screws 7 with screwdriver and disconnect bearing holder plate 10 from bracket 9 on the counter-load side.
- (5) Draw out rotor 11 toward the counter-load side and remove stator 12 from the interior.
- (6) Using a press or bearing remover, remove bearing 18 on the load side and bearing on the counter-load side and replace them.

Note: Make sure preload spring is located at bracket 15 on the load side, and bearing holder plate 10 between bearing 20 on the counter-load side and rotor 11.

- (7) To reassemble, fit bracket 9 on the counter-load side to bearing 20 on the counter-load side, tighten four bearing holder plate mounting screws 7 and properly position bracket 9 and bearing holder plate 10.
- (8) Align the motor leads in reference to the lead hole of bracket 9 on the counter-load side and insert rotor 11 attached to bracket 9 into stator 12.

Note: Preload spring 16 should be inserted between bracket 15 on the load side and bearing 18 on the load side.
Care should be taken not to damage the coil when the rotor is inserted into the stator.

- (9) Tighten four bracket mounting bolts 8 on the counter-load and secure bracket 9 to frame 14.
 - (10) Tighten four bearing holder plate mounting screws 7 using a screwdriver and secure bearing holder plate 10 to bracket 9 on the counter-load side.
 - (11) Remove the sealing agent from the surface where bracket 9 and protection cover 2 are in contact with each other and apply a new oil-resistant sealing agent there. While drawing out the leads from the lead hole, securely fit protection cover 2 to bracket 15 by hand.
- Placing cooling fan 1 upward, alternately tighten two (left and right) protection cover mounting bolts 6.
- Tighten one lower protection cover mounting bolt 6 and then upper one.

Note: Since accuracy of installation of protection cover 2 to bracket 9 on the counter-load side is largely influential to adequacy of shaft connection, accurately install protection cover 2 as instructed above.

It is recommended to make sure runout of motor shaft, and the flange of speed detector 24 is within about 0.2 mm (TIR).

- (12) For reassembling of speed detectors 24 and 22, refer to para. 8.3.




Fig. 8.1 AC spindle motor construction

Table 8.2 Parts list

No.	Name	No.	Name
1	Cooling fan	15	Bracket on load side
2	Protection cover	16	Preload spring
3	Speed detector connector mounting plate	17	Shaft
4	Speed detector connector	18	Bearing on load side
5	Terminal box cover	19	Bracket mounting block on load side
6	Protection cover mounting bolt	20	Bearing on counter-load side
7	Bearing holder plate mounting screw	21	Speed detector mounting screw
8	Bracket mounting bolt on counter-load side	22	Coupling
9	Bracket on counter-load side	23	Coupling set screw
10	Bearing holder plate	24	Speed detector (ENCODER)
11	Rotor	25	Cooling fan mounting screw
12	Stator	26	Cooling fan leads
13	Frame cover		
14	Frame		




Fig. 8.2 Cooling fan leads

CHAPTER 9 PARTS LIST

AC SPINDLE CONTROLLER & MOTOR (TYPE FR-SX-2)

NOTE: Option spare parts A Maintenance spare parts for every two years.
Option spare parts B Maintenance spare parts for every five years.
Option spare parts C Maintenance spare parts for machine maker's stock.

EM	DECRPTION	TYPE		MAKER	SYMBOL	QTY	SPARE PARTS				NOTE
							STAND.	OPTION			
		kW						A	B	C	
1	CIRCUIT BREAKER	5.5	NF50CB	MITSUBISHI ELECTRIC	CB1	1	0	0	0	1	
		7.5	BK0-C1572-35-50A								
		11	NF100CB								
		15	BK0-C1572-37-100A								
		18.5	NF225CB								
22	BK0-C1572-39-150A										
2	THYRISTOR	6.6	TM90DZ-H	MITSUBISHI ELECTRIC	SCRR-F SCRS-F SCRT-F	3	0	0	0	3	FOR CONVERTER
		7.6									
		11									
		15									
		16.5									
22											
3	THYRISTOR	5.5	TM55DZ-H	MITSUBISHI ELECTRIC	SCRR-R SCRS-R SCRT-F	3	0	0	0	3	FOR CONVERTER
		7.5									
		11	TM90DZ-H								
		15									
		18.5									
22											
4	TRANSISTOR	5.5	QM100DY-H	MITSUBISHI ELECTRIC	TRU TRV TRW	3	0	0	0	3	FOR INVERTER
		7.5	QM150DY-H			3	0	0	0	3	
		11	DM200HZ-H			6	0	0	0	6	
		15	QM150DY-H			6	0	0	0	6	
		18.5				9	0	0	0	9	
		22				9	0	0	0	9	
5	CAPACITOR	6.6	400UF BK0-C1784-H01	NITSUKO	C1-1 1-2 1-3 1-4 1-5	2	0	0	2	2	
		7.6				2	0	0	2	2	
		11				3	0	0	3	3	
		15				4	0	0	4	4	
		18.5				6	0	0	5	5	
		22	4700UF BK0-C1784-H02	NITICON		6	0	0	5	5	
6	FAN	6S	N3951ML	TOOBISHI	FAN1 2	2	0	2	0	2	
		7S									
		11	HS4556ML								
		16									
		18.5									
22											

ITEM	DESCRIPTION	kW	TYPE	MAKER	SYMBOL	QTY	SPARE PARTS				NOTE
							STAND.	OPTION			
								A	B	C	
7	TRANSISTOR	5.5	3PH BKD-C1840-H01	CHINO	T3	1	0	0	0	1	
		7.5									
		11									
		15									
		18.5									
8	TRANSISTOR	5.5	1PH BKD-C1838-H01	CHINO	R.2	2	0	0	0	2	
		7.5									
		11									
		15									
		18.5									
9	AC REACTOR	5.5	0.2MH50A	CHUO	ACL	1	0	0	0	1	
		7.5	BKD-C1883-H02								
		11	0.17MH75A								
		15	0.1MH100A BKD-C1883-H05								
		18.5	0.065MH150A								
10	DC REACTOR	5.5	1MH45A	CHUO	L	1	0	0	0	1	
		7.5	BKD-C1894-H02								
		11	1MH68A								
		15	1MH90A								
		18.5	1MH130A								
11	CAPACITOR	5.5	MEUZ105K 600A BKD-NA1061-06	NITSUKO	C2	3	0	0	3	3	
		7.5									
		11									
		15									
		18.5									
12	RESISTOR	5.5	3.5MOHM BKD-C1925-H01	MICRON	RU RV RW	3	0	0	0	3	
		7.5									
		11									
		15									
		18.5									
13	CT	5.5	150/0.05A	YOSIKAWA	CT	1	0	0	0	1	
		7.5									
		11									
		15									
		18.5									

ITEM	DESCRIPTION	kW	TYPE	MAKER	SYMBOL	QTY	SPARE PARTS				NOTE								
							STAND.	OPTION											
								A	B	C									
14	SURGE KILLER	-	BK0-C1855-H01	NISIN	SK1-6	6	0	0	0	6									
15	FILTER	-	BK0-C1938-H01	NISIN		1	0	0	0	1									
16	THERMAL DETECTOR	-	0MD-608	TOOKIN	THS1	1	0	0	0	1									
17	THERMAL DETECTOR	-	0MD-1008	TOOKIN	THS2	1	0	0	0	1									
18	FILTER	-	ZM82202-11	TDK	FIL	1	0	0	0	1									
19	FUSE	-	MF60NR-SA-S	TOYO	F1-3	3	3	0	0	3									
20	PRINTED CIRCUIT BOARD	5.5	BK0-C1872-H02	YAMABISHI	SX-PW	1	0	0	0	1									
		11																	
		18.5	BK0-C1872-H01	TAMURA															
		7.5																	
15																			
22																			
21	PRINTED CIRCUIT BOARD	-	SX-AJ1	MITSUBISHI ELECTRIC	-	1	0	0	0	1									
22	PRINTED CIRCUIT BOARD	-	SX-101	MITSUBISHI ELECTRIC	-	1	0	0	1										
23	PULSE SIGNAL GENERATOR			TAMA-GAWA SEIKI	-	1	0	0	1	1									
24	COUPLING	-	MS76Z104-H03	NIHON MINUATURE COUPLING	-	1	0	0	1	1	FOR PULSE SIGNAL GENERATOR								
25	FAN	-	PFA-600	AKAMATSU ELECTRIC	-	1	0	0	1	1	FOR MOTOR								
26	BEARING (LOAD SIDE)	5.5	6307ZZ	NIHON SEIKO OR NTN TOYO BEARING	-	1	0	0	0	1	FOR MOTOR								
		7.5																	
		11	6310ZZ																
		15																	
18.5																			
22																			
27	BEARING (OPPOSITE SIDE)	5.5	6306ZZ	NIHON SEIKO OR NTN TOYO		1	0	0	1	1	FOR MOTOR								
		7.5																	
		11	6308ZZ																
		15																	
18.5																			
22																			

OPTION CARD

ITEM	DESCRIPTION	kW	TYPE	MAKER	SYMBOL	QTY	SPARE PARTS				NOTE
							STAND.	OPTION			
								A	B	C	
41	MAGNE- SENSOR ORIENT P.C.B		SX-CPU1	MITSUBISHI ELECTRIC	-	1	0	0	0	1	
42	ENCODER ORIENT P.C.B		SX-CPU2	MITSUBISHI ELECTRIC	-	1	0	0	0	1	