

MOD

15640

ALESSANDRO

[illegible]

VISTO ACQUISTI



R.E.M. s.r.l.

Via Ferruccia, 16/a – 03010 Patrica (FR)

Tel. 0775 830116 – Fax 0775 839345

Email: rem-motori@messaggipec.it - Email: info@rem-motori.it

Email: amministrazione@rem-motori.it



Dasa-Rägister
EN ISO 9001:2008
IQ-0310-05

Misurazioni Sede

Commessa: 2022-0117

NUM. REM 15640

M.

Bearing:


6218 C3

Bearing position:

RIPARAZIONE SEDE CALOTTA L. VENTOLA (LATO B)

Application:

SIEMENS 1LA8317-2PC80-ZB3



Measuring directions	Shaft Measurement values [mm] at place				Housing Measurement values [mm] at place		
	a	b	(c)	(d)	a	b	(c)
	Distance L				Distance L		
1					160,020		
2							
3							
4							
	Calculated mean: (1+2+3+4)/4				Calculated mean: (1+2+3+4)/4		

SKF



R.E.M. s.r.l.

Via Ferruccia, 16/a – 03010 Patrica (FR)

Tel. 0775 830116 – Fax 0775 839345

Email: rem-motori@messaggipec.it - Email: info@rem-motori.it

Email: amministrazione@rem-motori.it



Dasa-Rägister
EN ISO 9001:2008
IQ-0310-05

Misurazioni Sede

Commessa: 2022-0117

M.

NUM. REM. 15640

Bearing:


6218 C3

Bearing position:

RIPARAZIONE SEDE CALOTTA L. GIUNTO (LATO A)

Application:

SIEMENS 1LA 8317 -2PC 80 -Z B3



Measuring directions	Shaft Measurement values [mm] at place				Housing Measurement values [mm] at place		
	a	b	(c)	(d)	a	b	(c)
	Distance L				Distance L		
	Diameter d				Diameter D		
1					160,010		
2							
3							
4							
	Calculated mean: (1+2+3+4)/4				Calculated mean: (1+2+3+4)/4		

SKF