

MOD

15641

ALESSANDRO

[illegible]

VISTO ACQUISTI



R.E.M. s.r.l.

Via Ferruccia, 16/a – 03010 Patrica (FR)

Tel. 0775 830116 – Fax 0775 839345

Email: rem-motori@messaggipec.it - Email : info@rem-motori.it

Email: amministrazione@rem-motori.it



Dasa-Rägister
EN ISO 9001:2008
IQ-0310-05

Misurazioni Sede

Commessa: 2022-0118
NUM. REM. 000000015641

Measurement report form

Bearing:


6315 C3

Bearing position:

RIPARAZIONE SERIE CALOTTA 2. VENTOLA (LATO B)

Application:

EFD 2DPIC280M/2N



Measuring directions	Shaft Measurement values [mm] at place				Housing Measurement values [mm] at place			
	a	b	(c)	(d)	a	b	(c)	(d)
	Distance L				Distance L			
	Diameter d				Diameter D			
1					<u>160,010</u>			
2								
3								
4								
	Calculated mean: (1+2+3+4)/4				Calculated mean: (1+2+3+4)/4			

Remarks:

Date:

24-02-2022

Checked by:



SKF



R.E.M. s.r.l.

Via Ferruccia, 16/a – 03010 Patrica (FR)

Tel. 0775 830116 – Fax 0775 839345

Email: rem-motori@messaggipec.it - Email : info@rem-motori.it

Email: amministrazione@rem-motori.it



Dasa-Rägister
EN ISO 9001:2008
IQ-0310-05

Misurazioni Sede

Commessa: 2022-0118
NUM. REM...15641.....

Measurement report form

Bearing:


6315 C3

Bearing position:

RIPARAZIONE SEDE CALOTTA L. GIUNTO (LATO A)

Application:

EFD 2D PIC 280M/2N



Measuring directions	Shaft Measurement values [mm] at place				Housing Measurement values [mm] at place			
	a	b	(c)	(d)	a	b	(c)	(d)
	Distance L				Distance L			
	Diameter d				Diameter D			
1					<u>160,020</u>			
2								
3								
4								
	Calculated mean: (1+2+3+4)/4				Calculated mean: (1+2+3+4)/4			

Remarks:

Date:

24-02-2022

Checked by:



SKF