




Data e ora della misurazione02/11/2016 10:40:05 ,20/07/2017 08:50:44 ,21/09/2017 08:37:24 ,21/11/2017 14:20:56

Siniat\Zona 1\Ventilatore Aria Circolazione 2 - 85\Motore\Punto 2 Ass.\103 Mach. spectr. >600



|                       |          |              |                            |
|-----------------------|----------|--------------|----------------------------|
| Cursore<br>Principale | X [Hz]   | = 22,00      | (76,33) BPFO 6316 (SKF)    |
|                       | Y [mm/s] | = 8,90       | (121,54) BPFI 6316 (SKF)   |
|                       | X [Hz]   | = Non Attivo | (102,54) RPF 6316 (SKF)    |
|                       | Y [mm/s] | = Non Attivo | (9,55) FTF 6316 (SKF)      |
|                       |          | = 1484       | (88,67) BPFO 6319 (SKF)    |
|                       |          |              | (133,93) BPFI 6319 (SKF)   |
|                       |          |              | (116,57) RPF 6319 (SKF)    |
|                       |          |              | (9,84) FTF 6319 (SKF)      |
|                       |          |              | (188,34) BPFO 22220E (SKF) |
|                       |          |              | (256,86) BPFI 22220E (SKF) |
|                       |          |              | (154,98) RPF 22220E (SKF)  |

REM SRL  
Via Ferruccia, 16a  
03010 Patrica FR



Date/Time 29/11/2017 09:31:17

Page 2 of 2

(10,46) FTF 22220E (SKF)

| Data       | Ora      | Evento          | Commento         |
|------------|----------|-----------------|------------------|
| 24/11/2017 | 12:15:46 | Misura mancante | Misura mancante. |
| 23/11/2017 | 17:15:38 | Misura mancante | Misura mancante. |
| 22/11/2017 | 17:58:19 | Misura mancante | Misura mancante. |
| 22/06/2017 | 15:16:17 | Misura mancante | Misura mancante. |