

TYPE 14 VARIATOR PARTS LIST			DRAWING N° 100-03.14.000	
Ref.	Drawing N°	Description	Q.ty	
2	100-10.14.021	Cover	1	
20	100-10.14.200	Output shaft	1	
21	100-10.14.210	Bearing spacer	1	
40		Bearing 6007	1	
41		Bearing 6207	1	
44		Clamping ring stop 35 UNI 7435	1	
48		Clamping ring stop 72 UNI 7437	1	
49		O-ring 1,78x628	1	
50		Sealing ring 35x72x10	1	
53		Feather key 8x7x40 UNI 6604	1	
73		Screw M8x20 UNI 5931 A8G	6	