




Data e ora della misurazione22/06/2017 15:07:54 ,20/07/2017 10:25:26 ,21/09/2017 09:55:50 ,22/11/2017 11:15:29

Siniat\In Sito\Aspirazione Filtro Luhr - 30\Motore\Punto 2\103 Mach. spectr. >600



Cursore Principale	X [Hz]	= 49,50	(200,14) BPFO 6212 (SKF)
	Y [mm/s]	= 8,14	(291,36) BPFI 6212 (SKF)
	X [Hz]	= Non Attivo	(255,58) RPF 6212 (SKF)
	Y [mm/s]	= Non Attivo	(20,00) FTF 6212 (SKF)
		= 2949	(150,60) BPFO 6312 (SKF)
			(242,60) BPFI 6312 (SKF)
			(198,62) RPF 6312 (SKF)
			(18,82) FTF 6312 (SKF)
			(232,04) BPFO 2312 (SKF)
			(357,76) BPFI 2312 (SKF)
			(212,33) RPF 2312 (SKF)

REM SRL
Via Ferruccia, 16a
03010 Patrica FR



Date/Time 29/11/2017 12:26:01

Page 2 of 2

(19,32) FTF 2312 (SKF)

Data	Ora	Evento	Commento
24/11/2017	12:15:48	Misura mancante	Misura mancante.
23/11/2017	17:15:39	Misura mancante	Misura mancante.