




Date/Time 29/11/2017 12:40:47

Page 1 of 2

Data e ora della misurazione 18/11/2015 11:07:05 , 11/05/2016 09:18:40 , 03/11/2016 12:29:36 , 22/11/2017 11:45:21

Siniat\Formatura\Molino BMA - x\Motore\Punto 2 Ass.\143 Roll.bear.enve. > 300 kW < 600 rpm



Cursore Principale	X [Hz]	= 4,40	(73,83) BPFO 6309 (SKF)
	Y [m/s ²]	= 2,019	(120,84) BPFI 6309 (SKF)
	X [Hz]	= Non Attivo	(94,92) RPF 6309 (SKF)
	Y [m/s ²]	= Non Attivo	(9,22) FTF 6309 (SKF)
		= 1460	(73,63) BPFO 6311 (SKF)
			(121,03) BPFI 6311 (SKF)
			(94,00) RPF 6311 (SKF)
			(9,20) FTF 6311 (SKF)

Data	Ora	Evento	Commento
24/11/2017	12:15:47	Misura mancante	Misura mancante.

REM SRL
Via Ferruccia, 16a
03010 Patrica FR



Date/Time	29/11/2017 12:40:47	Page 2 of 2
-----------	---------------------	-------------

23/11/2017	17:15:39	Misura mancante	Misura mancante.
21/11/2017	17:38:41	Misura mancante	Misura mancante.