

1

—

2

—

3

—

4

—

5

—

6

—

7

—

8

—

9

—

10

—

11

—

12

—

13

—

14

—

15

—


16

—


17

—

18



-A102



(SALDATO NELL'INTERNO DI SPINA)  
( Im Stecker eingelötet )

Programmiermodul  
Hauptspindel  
AS71/005-000

TDA1.1-050-3-A00-W1

FMA

|  |             |             |                     |  |               |             |            |             |     |
|--|-------------|-------------|---------------------|--|---------------|-------------|------------|-------------|-----|
|  | DIS. N.     | 31239.14818 | MACCHINA/IMPIANTO : |  | FMA 453       | DRDNE       | MANDRINO 2 | FUGLID      | 501 |
|  | CAD         | Autocad 10  | LAVORAZIONE :       |  | ALBERO MOTORE | COMMESSA    | SPINDEL 2  |             |     |
|  | N. FILE     | 24A501      | DENOMINAZIONE :     |  | TRASFERITA    | ESECUTORE : |            | UNITA       | 24A |
|  | POS. ARCH.: |             | DATA : 16.12.92     |  | AGG. :        | HET         |            | ARMADIO 1.2 |     |