

1

—

2

—

3

—

4

—

5

—

6

—

7

—

8

—

9

—

10

—

11

—

12

—

13

—

14

—

15

—



16

—

17

—

18



|     |                     |  |                     |  |               |  |                     |                       |                |
|-----|---------------------|--|---------------------|--|---------------|--|---------------------|-----------------------|----------------|
| FMA | DIS. N. 31239.17811 |  | MACCHINA/IMPIANTO : |  | FMA 453       |  | ORDINE<br>30.007629 | LUBRIF.<br>SCHMIERUNG | FUGLID<br>1041 |
|     | CAD ,Autocad 12     |  | LAVORAZIONE :       |  | ALBERO MOTORE |  |                     |                       |                |
|     | N. FILE : 33B1041   |  | DENOMINAZIONE :     |  | TRASFERITA    |  | ESECUTORE :<br>HET  |                       |                |
|     | POS. ARCH.:         |  | DATA : 18.04.97     |  | AGG. :<br>b   |  |                     | UNITA<br>33B          | BP             |