

1
—
2
—
3
—
4
—
5
—
6
—
7
—
8
—
9
—
10
—
11
—
12
—
13
—
14
—
15
—
16
—
17
—
18

ARMADIO 1.1
S1.1 PR11/SP11

	1	<
IP1040	2	<
IP2060	3	<
IM2	4	<
E15.0	5	<
E15.1	6	<
E15.2	7	<
E15.3	8	<
E15.4	9	<
A4.0	10	<
A4.1	11	<
A4.2	12	<
A4.4	13	<
A4.5	14	<
A4.6	15	<
A5.0	16	<
	17	<
	18	<
	19	<
	20	<
	21	<
	22	<
	23	<
	24	<

VALENITE

	1	<
IP1040	2	<
IP2060	3	<
IM2	4	<
E15.0	5	<
E15.1	6	<
E15.2	7	<
E15.3	8	<
E15.4	9	<
A4.0	10	<
A4.1	11	<
A4.2	12	<
A4.4	13	<
A4.5	14	<
A4.6	15	<
A5.0	16	<
	17	<
	18	<
	19	<
	20	<
	21	<
	22	<
	23	<
	24	<

ARMADIO 1.1
S1.1 PR12/SP12

	1	<
S	2	<
E26.1	3	<
E26.3	4	<
E26.5	5	<
E26.7	6	<
E27.1	7	<
E27.4	8	<
E27.2	9	<
E27.7	10	<
	11	<
	12	<
	13	<
A6.1	14	<
A6.3	15	<
A6.6	16	<
A6.5	17	<
	18	<
	19	<
E26.0	20	<
E26.2	21	<
E26.4	22	<
E26.6	23	<
E27.0	24	<
E27.3	25	<
E27.5	26	<
E27.6	27	<
	28	<
	29	<
	30	<
	31	<
A6.0	32	<
A6.2	33	<
A6.4	34	<
A6.7	35	<
	36	<
	37	<

SUBMIN D

MARPOSS
PR12/SP12

	1	<
>	2	E26.1
>	3	E26.3
>	4	E26.5
>	5	E26.7
>	6	E27.1
>	7	E27.4
>	8	E27.2
>	9	E27.7
>	10	
>	11	
>	12	
>	13	
>	14	A6.1
>	15	A6.3
>	16	A6.6
>	17	A6.5
>	18	
>	19	
>	20	E26.0
>	21	E26.2
>	22	E26.4
>	23	E26.6
>	24	E27.0
>	25	E27.3
>	26	E27.5
>	27	E27.6
>	28	
>	29	
>	30	
>	31	
>	32	A6.0
>	33	A6.2
>	34	A6.4
>	35	A6.7
>	36	
>	37	

FMA

DIS. N.	31239.13869	MACCHINA/IMPIANTO :	FMA 453	ORDINE :	30.007629	SCHEMA DI MORSE CONN.		FOGLIO
CAD	:Autocad 10	LAVORAZIONE :	ALBERO MOTORE	COMMESSA :				14
N. FILE	: 20B14K	DENOMINAZIONE :	TRASFERTA	ESECUTORE :	HET	SCHEMA DI MORSE CONN.	UNITA	SEGUE
POS. ARCH.:		DATA : 30.04.93	AGG. : ^a ^b			ARMADIO 1.1	20B	