



R.E.M. s.r.l.
Via Ferruccia, 16/a – 03010 Patrica (FR)
Tel. 0775 830116 – Fax 0775 839345
Email : info@rem-motori.it


Misurazioni

Sp1	37,9 °C
Sp2	33,4 °C
Sp3	37,2 °C

Parametri

Emissività	0.95
Temp. rifl.	23 °C

17/06/2022 12:13:31




FLIR6061.jpg

FLIR E6

63957585

17/06/2022 12:13:31



FLIR6061.jpg

FLIR E6

63957585

Delta di n.4°C dopo n.1 hr di tensione applicata. Delta corretto entro 13°C.



R.E.M. s.r.l.
Via Ferruccia, 16/a – 03010 Patrica (FR)
Tel. 0775 830116 – Fax 0775 839345
Email : info@rem-motori.it


Misurazioni

Sp1	37,3 °C
Sp2	33,7 °C

Parametri

Emissività	0.95
Temp. rifl.	23 °C

17/06/2022 12:13:50



FLIR6063.jpg

FLIR E6

63957585

17/06/2022 12:13:50



FLIR6063.jpg

FLIR E6

63957585



R.E.M. s.r.l.
Via Ferruccia, 16/a – 03010 Patrica (FR)
Tel. 0775 830116 – Fax 0775 839345
Email : info@rem-motori.it


Misurazioni

Sp1	38,1 °C
Sp2	37,8 °C
Sp3	33,2 °C
Sp4	37,5 °C

Parametri

Emissività	0.95
Temp. rifl.	23 °C

17/06/2022 12:14:03



17/06/2022 12:14:03

