

NUM. COMMESSA	2021-0696	ID MOTORE	8433
---------------	-----------	-----------	------

COMPILATORE	Andrea Lis
-------------	------------

[illegible]

VISTO ACQUISTI	
----------------	--



R.E.M. s.r.l.

Via Ferruccia, 16/a – 03010 Patrica (FR)

Tel. 0775 830116 – Fax 0775 839345

Email: rem-motori@messaggipec.it - Email : info@rem-motori.it

Email: amministrazione@rem-motori.it



Dasa-Rägister
EN ISO 9001:2008
IQ-0310-05

Misurazioni Sede

Commesso: 2021-0696

Measurement report form

NUM. REM. 8933

Bearing: <u>6210</u>
Bearing position: <u>CALOTA LATO OPPOSTO CUNTO</u>
Application: <u>SIEMENS 1PH 7437</u>

Measuring directions	Shaft Measurement values [mm] at place				Housing Measurement values [mm] at place			
	a	b	(c)	(d)	a	b	(c)	(d)
	Distance L				Distance L			
	Diameter d				Diameter D			
1					90,002			
2								
3								
4								
	Calculated mean: (1+2+3+4)/4				Calculated mean: (1+2+3+4)/4			

Remarks:

Date: 16/11/2021

Checked by:

[Signature]



SKF



R.E.M. s.r.l.

Via Ferruccia, 16/a - 03010 Patrica (FR)

Tel. 0775 830116 - Fax 0775 839345

Email: rem-motori@messaggipec.it - Email: info@rem-motori.it

Email: amministrazione@rem-motori.it



Dasa-Rägister
EN ISO 9001:2008
IQ-0310-05

Misurazioni Sede

Commissa: 2021-06%
NUM. REM...8533.....


Measurement report form

Bearing:
Bearing position:
Application: <u>Motor Siemens IPH 7137</u>

RIPARAZIONE SEDE PULVERIA ϕ 42 mm + RIPARAZIONE
SEDE CHAVETTA 80 X 12

Measuring directions	Shaft Measurement values [mm] at place				Housing Measurement values [mm] at place			
	a	b	(c)	(d)	a	b	(c)	(d)
	Distance L				Distance L			
	Diameter d				Diameter D			
1								
2								
3								
4								
	Calculated mean: $(1+2+3+4)/4$				Calculated mean: $(1+2+3+4)/4$			

Remarks:	
Date: <u>15/11/2021</u>	Checked by: <u>Lu Ab</u>



SKF