

NUM. COMMESSA

2022/06.29

ID.MOTORE

15.72.8

COMPILATORE

DAVIDE

[illegible]

VISTO ACQUISTI



Automazione Industriale
Gestione Macchine Elettriche
Vendita Apparecchiature Elettromeccaniche



MODULO LAVORAZIONI MECCANICHE INTERNE

Commessa: 2022/0029

NUM. REM...5728.....

MATERIALI IMPIEGATI: _____

Misurazioni Sede

Measurement report form

Bearing: <u>6309/22</u>	
Bearing position: <u>LATO GIUNTO</u>	
Application: <u>SEIPEE GM 160LA</u>	

Measuring directions	Shaft Measurement values [mm] at place				Housing Measurement values [mm] at place			
	a	b	(c)	(d)	a	b	(c)	(d)
	Distance L				Distance L			
	Diameter d				Diameter D			
1								
2	<u>65,020</u>							
3								
4								
	Calculated mean: (1+2+3+4)/4				Calculated mean: (1+2+3+4)/4			

Remarks:	
Date:	Checked by:



Automazione Industriale
Gestione Macchine Elettriche
Vendita Apparecchiature Elettromeccaniche



MODULO LAVORAZIONI MECCANICHE INTERNE

Commessa: 2022/0629

NUM. REM...5728.....

MATERIALI IMPIEGATI: _____

Misurazioni Sede

Measurement report form

Bearing:	<u>6309/2Z</u>
Bearing position:	<u>LATO GIUNTO</u>
Application:	<u>SEIPEE GM 160LA</u>

Measuring directions	Shaft Measurement values [mm] at place				Housing Measurement values [mm] at place			
	a	b	(c)	(d)	a	b	(c)	(d)
	Distance L				Distance L			
1								
2								
3								
4								
	Calculated mean: (1+2+3+4)/4				Calculated mean: (1+2+3+4)/4			

Remarks:	
Date:	Checked by: