




Date/Time 29/11/2017 14:38:54

Page 1 of 1

Data e ora della misurazione 18/11/2015 11:12:29 , 10/05/2016 12:11:35 , 03/11/2016 11:35:46 , 23/11/2017 10:05:18

Siniat\Boundler\Sega Principale SX - 44\Motore\Punto 2\143 Roll.bear.enve. > 300 kW < 600 rpm



Cursore Principale	X [Hz]	= 200,00	(47,33) elctrical Electrical
	Y [m/s ²]	= 2,337	(23,67) Disallineamento Misalignment
	X [Hz]	= Non Attivo	(85,37) BPFO 6208 (SKF)
	Y [m/s ²]	= Non Attivo	(127,63) BPFI 6208 (SKF)
		= 1420	(114,57) RPF 6208 (SKF) (9,49) FTF 6208 (SKF)

Data	Ora	Evento	Commento
24/11/2017	12:15:47	Misura mancante	Misura mancante.
22/11/2017	17:58:20	Misura mancante	Misura mancante.